

Claim Photo

Our File Number: 277-065390
Adjuster: Michael Cameron
Insured: Carter Express
Date of Loss:
Customer File Number: 250611
Policy Number:




Photo: 1

Date Taken:
12/11/2025

Taken By:
Jeremy Garcia-
Baez

Description:
VIN



Photo: 2

Date Taken:
12/12/2025

Taken By:
Jeremy Garcia-
Baez

Description:
VIN

Claim Photo

Our File Number: 277-065390
Adjuster: Michael Cameron
Insured: Carter Express
Date of Loss:
Customer File Number: 250611
Policy Number:




Photo: 3

Date Taken:
12/11/2025

Taken By:
Jeremy Garcia-
Baez

Description:
Mileage



Photo: 4

Date Taken:
12/11/2025

Taken By:
Jeremy Garcia-
Baez

Description:
Right front

Claim Photo

Our File Number: 277-065390
Adjuster: Michael Cameron
Insured: Carter Express
Date of Loss:
Customer File Number: 250611
Policy Number:



Photo: 5

Date Taken:
12/11/2025

Taken By:
Jeremy Garcia-
Baez

Description:
Left front



Photo: 6

Date Taken:
12/11/2025

Taken By:
Jeremy Garcia-
Baez

Description:
Right rear

Claim Photo

Our File Number: 277-065390
Adjuster: Michael Cameron
Insured: Carter Express
Date of Loss:
Customer File Number: 250611
Policy Number:



Photo: 7

Date Taken:
12/11/2025

Taken By:
Jeremy Garcia-
Baez

Description:
Left rear



Photo: 8

Date Taken:
12/11/2025

Taken By:
Jeremy Garcia-
Baez

Description:
left side of truck
damage

Claim Photo

Our File Number: 277-065390
Adjuster: Michael Cameron
Insured: Carter Express
Date of Loss:
Customer File Number: 250611
Policy Number:



Photo: 9

Date Taken:
12/11/2025

Taken By:
Jeremy Garcia-Baez

Description:
left side of truck
damage



Photo: 10

Date Taken:
12/11/2025

Taken By:
Jeremy Garcia-Baez

Description:
left side of truck
damage

Claim Photo

Our File Number: 277-065390
Adjuster: Michael Cameron
Insured: Carter Express
Date of Loss:
Customer File Number: 250611
Policy Number:



Photo: 11

Date Taken:
12/11/2025

Taken By:
Jeremy Garcia-
Baez

Description:
left side of truck
damage



Photo: 12

Date Taken:
12/11/2025

Taken By:
Jeremy Garcia-
Baez

Description:
Tank damage

Claim Photo

Our File Number: 277-065390
Adjuster: Michael Cameron
Insured: Carter Express
Date of Loss:
Customer File Number: 250611
Policy Number:



Photo: 13

Date Taken:
12/11/2025

Taken By:
Jeremy Garcia-
Baez

Description:
Closer view of
damage on the left
side



Photo: 14

Date Taken:
12/11/2025

Taken By:
Jeremy Garcia-
Baez

Description:
Overall view of left
side damage

Claim Photo

Our File Number: 277-065390
Adjuster: Michael Cameron
Insured: Carter Express
Date of Loss:
Customer File Number: 250611
Policy Number:



Photo: 15

Date Taken:
12/11/2025

Taken By:
Jeremy Garcia-
Baez

Description:
Left side damage



Photo: 16

Date Taken:
12/11/2025

Taken By:
Jeremy Garcia-
Baez

Description:
Left side damage

Claim Photo

Our File Number: 277-065390
Adjuster: Michael Cameron
Insured: Carter Express
Date of Loss:
Customer File Number: 250611
Policy Number:



Photo: 17

Date Taken:
12/11/2025

Taken By:
Jeremy Garcia-
Baez

Description:
Items inside
damaged area




Photo: 18

Date Taken:
12/11/2025

Taken By:
Jeremy Garcia-
Baez

Description:
Wiring damage

Claim Photo

Our File Number: 277-065390
Adjuster: Michael Cameron
Insured: Carter Express
Date of Loss:
Customer File Number: 250611
Policy Number:



Photo: 19

Date Taken:
12/11/2025

Taken By:
Jeremy Garcia-
Baez

Description:
Back side damage



Photo: 20

Date Taken:
12/11/2025

Taken By:
Jeremy Garcia-
Baez

Description:
Overall view of
back damage

Claim Photo

Our File Number: 277-065390
Adjuster: Michael Cameron
Insured: Carter Express
Date of Loss:
Customer File Number: 250611
Policy Number:



Photo: 21

Date Taken:
12/11/2025

Taken By:
Jeremy Garcia-
Baez

Description:
Back damage



Photo: 22

Date Taken:
12/11/2025

Taken By:
Jeremy Garcia-
Baez

Description:
Right front damage

Claim Photo

Our File Number: 277-065390
Adjuster: Michael Cameron
Insured: Carter Express
Date of Loss:
Customer File Number: 250611
Policy Number:



Photo: 23

Date Taken:
12/11/2025

Taken By:
Jeremy Garcia-
Baez

Description:
Front bumper
damage



Photo: 24

Date Taken:
12/11/2025

Taken By:
Jeremy Garcia-
Baez

Description:
Scratches on right
head light and
fender

Claim Photo

Our File Number: 277-065390
Adjuster: Michael Cameron
Insured: Carter Express
Date of Loss:
Customer File Number: 250611
Policy Number:



Photo: 25

Date Taken:
12/11/2025

Taken By:
Jeremy Garcia-
Baez

Description:
Right side step bar
component damage



Photo: 26

Date Taken:
12/11/2025

Taken By:
Jeremy Garcia-
Baez

Description:
Bumper damage

Claim Photo

Our File Number: 277-065390
Adjuster: Michael Cameron
Insured: Carter Express
Date of Loss:
Customer File Number: 250611
Policy Number:



Photo: 27

Date Taken:
12/11/2025

Taken By:
Jeremy Garcia-
Baez

Description:
Hood damage



Photo: 28

Date Taken:
12/11/2025

Taken By:
Jeremy Garcia-
Baez

Description:
Under right front
side

Claim Photo

Our File Number: 277-065390
Adjuster: Michael Cameron
Insured: Carter Express
Date of Loss:
Customer File Number: 250611
Policy Number:



Photo: 29

Date Taken:
12/11/2025

Taken By:
Jeremy Garcia-
Baez

Description:
Overall view of
front damage



Photo: 30

Date Taken:
12/11/2025

Taken By:
Jeremy Garcia-
Baez

Description:
top left of back side

Claim Photo

Our File Number: 277-065390
Adjuster: Michael Cameron
Insured: Carter Express
Date of Loss:
Customer File Number: 250611
Policy Number:



Photo: 31

Date Taken:
12/11/2025

Taken By:
Jeremy Garcia-
Baez

Description:
Wires




Photo: 32

Date Taken:
12/11/2025

Taken By:
Jeremy Garcia-
Baez

Description:
Wires

Claim Photo

Our File Number: 277-065390
Adjuster: Michael Cameron
Insured: Carter Express
Date of Loss:
Customer File Number: 250611
Policy Number:



Photo: 33

Date Taken:
12/11/2025

Taken By:
Jeremy Garcia-
Baez

Description:
Damaged part
inside the truck




Photo: 34

Date Taken:
12/11/2025

Taken By:
Jeremy Garcia-
Baez

Description:
Engine

Claim Photo

Our File Number: 277-065390
Adjuster: Michael Cameron
Insured: Carter Express
Date of Loss:
Customer File Number: 250611
Policy Number:



Photo: 35

Date Taken:
12/11/2025

Taken By:
Jeremy Garcia-
Baez

Description:
Engine



Photo: 36

Date Taken:
12/11/2025

Taken By:
Jeremy Garcia-
Baez

Description:
Drivers Door trim

Claim Photo

Our File Number: 277-065390
Adjuster: Michael Cameron
Insured: Carter Express
Date of Loss:
Customer File Number: 250611
Policy Number:



Photo: 37

Date Taken:
12/11/2025

Taken By:
Jeremy Garcia-
Baez

Description:
walking inside left
front door




Photo: 38

Date Taken:
12/11/2025

Taken By:
Jeremy Garcia-
Baez

Description:
Under carpet

Claim Photo

Our File Number: 277-065390
Adjuster: Michael Cameron
Insured: Carter Express
Date of Loss:
Customer File Number: 250611
Policy Number:



Photo: 39

Date Taken:
12/11/2025

Taken By:
Jeremy Garcia-
Baez

Description:
Dash




Photo: 40

Date Taken:
12/11/2025

Taken By:
Jeremy Garcia-
Baez

Description:
Drivers Seat

Claim Photo

Our File Number: 277-065390
Adjuster: Michael Cameron
Insured: Carter Express
Date of Loss:
Customer File Number: 250611
Policy Number:



Photo: 41

Date Taken:
12/11/2025

Taken By:
Jeremy Garcia-
Baez

Description:
Passenger's seat




Photo: 42

Date Taken:
12/11/2025

Taken By:
Jeremy Garcia-
Baez

Description:
Sleep area

Claim Photo

Our File Number: 277-065390
Adjuster: Michael Cameron
Insured: Carter Express
Date of Loss:
Customer File Number: 250611
Policy Number:



Photo: 43

Date Taken:
12/11/2025

Taken By:
Jeremy Garcia-
Baez

Description:
Overall view of
inside front of truck



Photo: 44

Date Taken:
12/11/2025

Taken By:
Jeremy Garcia-
Baez

Description:
Options

Claim Photo

Our File Number: 277-065390
Adjuster: Michael Cameron
Insured: Carter Express
Date of Loss:
Customer File Number: 250611
Policy Number:



Photo: 45

Date Taken:
12/11/2025

Taken By:
Jeremy Garcia-
Baez

Description:
Unit #



Photo: 46

Date Taken:
12/11/2025

Taken By:
Jeremy Garcia-
Baez

Description:
Truck information

Claim Photo

Our File Number: 277-065390
Adjuster: Michael Cameron
Insured: Carter Express
Date of Loss:
Customer File Number: 250611
Policy Number:



Photo: 47

Date Taken:
12/11/2025

Taken By:
Jeremy Garcia-
Baez

Description:
Carter Express



Photo: 48

Date Taken:
12/11/2025

Taken By:
Jeremy Garcia-
Baez

Description:
Truck information

Claim Photo

Our File Number: 277-065390
Adjuster: Michael Cameron
Insured: Carter Express
Date of Loss:
Customer File Number: 250611
Policy Number:



Photo: 49

Date Taken:
12/11/2025

Taken By:
Jeremy Garcia-
Baez

Description:
Truck information



Photo: 50

Date Taken:
12/11/2025

Taken By:
Jeremy Garcia-
Baez

Description:
Truck information

Claim Photo

Our File Number: 277-065390
Adjuster: Michael Cameron
Insured: Carter Express
Date of Loss:
Customer File Number: 250611
Policy Number:




Photo: 51

Date Taken:
12/12/2025

Taken By:
Jeremy Garcia-Baez

Description:
Truck label




Photo: 52

Date Taken:
12/11/2025

Taken By:
Jeremy Garcia-Baez

Description:
Annual vehicle inspection label

Claim Photo

Our File Number: 277-065390
Adjuster: Michael Cameron
Insured: Carter Express
Date of Loss:
Customer File Number: 250611
Policy Number:



Photo: 53

Date Taken:
12/11/2025

Taken By:
Jeremy Garcia-
Baez

Description:
Extender
instructions




Photo: 54

Date Taken:
12/11/2025

Taken By:
Jeremy Garcia-
Baez

Description:
FMCSA certified



Claim Photo

Our File Number: 277-065390
Adjuster: Michael Cameron
Insured: Carter Express
Date of Loss:
Customer File Number: 250611
Policy Number:



Photo: 55

Date Taken:
12/11/2025

Taken By:
Jeremy Garcia-Baez

Description:
Jones
manufacturing




Photo: 56

Date Taken:
12/11/2025

Taken By:
Jeremy Garcia-Baez

Description:
Engine information

Claim Photo

Our File Number: 277-065390
Adjuster: Michael Cameron
Insured: Carter Express
Date of Loss:
Customer File Number: 250611
Policy Number:



Photo: 57
Date Taken: 12/11/2025
Taken By: Jeremy Garcia-Baez
Description: Serial #



Photo: 58
Date Taken: 12/11/2025
Taken By: Jeremy Garcia-Baez
Description: Truck label

Claim Photo

Our File Number: 277-065390
Adjuster: Michael Cameron
Insured: Carter Express
Date of Loss:
Customer File Number: 250611
Policy Number:



Photo: 59

Date Taken:
12/11/2025

Taken By:
Jeremy Garcia-
Baez

Description:
Blank tank



Photo: 60

Date Taken:
12/11/2025

Taken By:
Jeremy Garcia-
Baez

Description:
Left rear front tire

Claim Photo

Our File Number: 277-065390
Adjuster: Michael Cameron
Insured: Carter Express
Date of Loss:
Customer File Number: 250611
Policy Number:



Photo: 61

Date Taken:
12/11/2025

Taken By:
Jeremy Garcia-
Baez

Description:
Left rear back tire



Photo: 62

Date Taken:
12/11/2025

Taken By:
Jeremy Garcia-
Baez

Description:
Right rear back tire

Claim Photo

Our File Number: 277-065390
Adjuster: Michael Cameron
Insured: Carter Express
Date of Loss:
Customer File Number: 250611
Policy Number:



Photo: 63

Date Taken:
12/11/2025

Taken By:
Jeremy Garcia-
Baez

Description:
Right rear front tire



Photo: 64

Date Taken:
12/11/2025

Taken By:
Jeremy Garcia-
Baez

Description:
Right front tire

Claim Photo

Our File Number: 277-065390
Adjuster: Michael Cameron
Insured: Carter Express
Date of Loss:
Customer File Number: 250611
Policy Number:



Photo: 65

Date Taken:
12/11/2025

Taken By:
Jeremy Garcia-
Baez

Description:
Left front tire



Photo: 66

Date Taken:
12/11/2025

Taken By:
Jeremy Garcia-
Baez

Description:
Tire information

Claim Photo

Our File Number: 277-065390
Adjuster: Michael Cameron
Insured: Carter Express
Date of Loss:
Customer File Number: 250611
Policy Number:



Photo: 67

Date Taken:
12/11/2025

Taken By:
Jeremy Garcia-
Baez

Description:
Tire information



Photo: 68

Date Taken:
12/11/2025

Taken By:
Jeremy Garcia-
Baez

Description:
5th wheel

Claim Photo

Our File Number: 277-065390
Adjuster: Michael Cameron
Insured: Carter Express
Date of Loss:
Customer File Number: 250611
Policy Number:



Photo: 69

Date Taken:
12/11/2025

Taken By:
Jeremy Garcia-
Baez

Description:
axle housing




Photo: 70

Date Taken:
12/11/2025

Taken By:
Jeremy Garcia-
Baez

Description:
Tire Information

Claim Photo

Our File Number: 277-065390
Adjuster: Michael Cameron
Insured: Carter Express
Date of Loss:
Customer File Number: 250611
Policy Number:



Photo: 71

Date Taken:
12/11/2025

Taken By:
Jeremy Garcia-
Baez

Description:
Headliner




Photo: 72

Date Taken:
12/11/2025

Taken By:
Jeremy Garcia-
Baez

Description:

Claim Photo

Our File Number: 277-065390
Adjuster: Michael Cameron
Insured: Carter Express
Date of Loss:
Customer File Number: 250611
Policy Number:




Photo: 73
Date Taken: 12/11/2025
Taken By: Jeremy Garcia-Baez
Description: Secondary filter