

Claim Photo

Our File Number: 285-000665
Adjuster: Kevin Parker
Insured: Silver Water Trucking
Date of Loss: 06/07/2025
Customer File Number: MNC92506366
Policy Number:



Photo: 1

Date Taken:
07/21/2025

Taken By:
Daryl Seth

Description:
Truck number



Photo: 2

Date Taken:
07/21/2025

Taken By:
Daryl Seth

Description:
Insured name and
VIN on door

Claim Photo

Our File Number: 285-000665
Adjuster: Kevin Parker
Insured: Silver Water Trucking
Date of Loss: 06/07/2025
Customer File Number: MNC92506366
Policy Number:



Photo: 3

Date Taken:
07/21/2025

Taken By:
Daryl Seth

Description:
Odometer reading




Photo: 4

Date Taken:
07/21/2025

Taken By:
Daryl Seth

Description:
Manufactured by
and date
manufactured

Claim Photo

Our File Number: 285-000665
Adjuster: Kevin Parker
Insured: Silver Water Trucking
Date of Loss: 06/07/2025
Customer File Number: MNC92506366
Policy Number:



Photo: 5

Date Taken:
07/21/2025

Taken By:
Daryl Seth

Description:
Right front-
overview




Photo: 6

Date Taken:
07/21/2025

Taken By:
Daryl Seth

Description:
Right front-
closeup

Claim Photo

Our File Number: 285-000665
Adjuster: Kevin Parker
Insured: Silver Water Trucking
Date of Loss: 06/07/2025
Customer File Number: MNC92506366
Policy Number:



Photo: 7

Date Taken:
07/21/2025

Taken By:
Daryl Seth

Description:
Right front- hail
dent



Photo: 8

Date Taken:
07/21/2025

Taken By:
Daryl Seth

Description:
Right front- hail
dent

Claim Photo

Our File Number: 285-000665
Adjuster: Kevin Parker
Insured: Silver Water Trucking
Date of Loss: 06/07/2025
Customer File Number: MNC92506366
Policy Number:



Photo: 9

Date Taken:
07/21/2025

Taken By:
Daryl Seth

Description:
Right filter cover-
no hail damage
noted



Photo: 10

Date Taken:
07/21/2025

Taken By:
Daryl Seth

Description:
Right door -
overview

Claim Photo

Our File Number: 285-000665
Adjuster: Kevin Parker
Insured: Silver Water Trucking
Date of Loss: 06/07/2025
Customer File Number: MNC92506366
Policy Number:



Photo: 11

Date Taken:
07/21/2025

Taken By:
Daryl Seth

Description:
Right door - hail
dent



Photo: 12

Date Taken:
07/21/2025

Taken By:
Daryl Seth

Description:
Right door - hail
dent

Claim Photo

Our File Number: 285-000665
Adjuster: Kevin Parker
Insured: Silver Water Trucking
Date of Loss: 06/07/2025
Customer File Number: MNC92506366
Policy Number:



Photo: 13

Date Taken:
07/21/2025

Taken By:
Daryl Seth

Description:
Right exterior side
of sleeper-
overview



Photo: 14

Date Taken:
07/21/2025

Taken By:
Daryl Seth

Description:
Right exterior side
of sleeper-
overview

Claim Photo

Our File Number: 285-000665
Adjuster: Kevin Parker
Insured: Silver Water Trucking
Date of Loss: 06/07/2025
Customer File Number: MNC92506366
Policy Number:




Photo: 15

Date Taken:
07/21/2025

Taken By:
Daryl Seth

Description:
Right exterior side
of sleeper- hail dent



Photo: 16

Date Taken:
07/21/2025

Taken By:
Daryl Seth

Description:
Right exterior side
of sleeper- hail dent

Claim Photo

Our File Number: 285-000665
Adjuster: Kevin Parker
Insured: Silver Water Trucking
Date of Loss: 06/07/2025
Customer File Number: MNC92506366
Policy Number:



Photo: 17

Date Taken:
07/21/2025

Taken By:
Daryl Seth

Description:
Right exterior side
of sleeper- hail dent



Photo: 18

Date Taken:
07/21/2025

Taken By:
Daryl Seth

Description:
Right exterior side
of sleeper- hail dent

Claim Photo

Our File Number: 285-000665
Adjuster: Kevin Parker
Insured: Silver Water Trucking
Date of Loss: 06/07/2025
Customer File Number: MNC92506366
Policy Number:



Photo: 19

Date Taken:
07/21/2025

Taken By:
Daryl Seth

Description:
Right exterior side
of sleeper- hail dent



Photo: 20

Date Taken:
07/21/2025

Taken By:
Daryl Seth

Description:
Right exterior side
of sleeper- hail dent

Claim Photo

Our File Number: 285-000665
Adjuster: Kevin Parker
Insured: Silver Water Trucking
Date of Loss: 06/07/2025
Customer File Number: MNC92506366
Policy Number:



Photo: 21

Date Taken:
07/21/2025

Taken By:
Daryl Seth

Description:
Right exterior side
of sleeper- hail dent



Photo: 22

Date Taken:
07/21/2025

Taken By:
Daryl Seth

Description:
Right side of rear-
overview

Claim Photo

Our File Number: 285-000665
Adjuster: Kevin Parker
Insured: Silver Water Trucking
Date of Loss: 06/07/2025
Customer File Number: MNC92506366
Policy Number:




Photo: 23

Date Taken:
07/21/2025

Taken By:
Daryl Seth

Description:
Right side of rear-
hail dent



Photo: 24

Date Taken:
07/21/2025

Taken By:
Daryl Seth

Description:
Right side of rear-
hail dent

Claim Photo

Our File Number: 285-000665
Adjuster: Kevin Parker
Insured: Silver Water Trucking
Date of Loss: 06/07/2025
Customer File Number: MNC92506366
Policy Number:



Photo: 25

Date Taken:
07/21/2025

Taken By:
Daryl Seth

Description:
Left side of rear-
overview



Photo: 26

Date Taken:
07/21/2025

Taken By:
Daryl Seth

Description:
Left side of rear-
hail dent

Claim Photo

Our File Number: 285-000665
Adjuster: Kevin Parker
Insured: Silver Water Trucking
Date of Loss: 06/07/2025
Customer File Number: MNC92506366
Policy Number:



Photo: 27

Date Taken:
07/21/2025

Taken By:
Daryl Seth

Description:
Left side of rear-
hail dent



Photo: 28

Date Taken:
07/21/2025

Taken By:
Daryl Seth

Description:
Left side of sleeper-
overview

Claim Photo

Our File Number: 285-000665
Adjuster: Kevin Parker
Insured: Silver Water Trucking
Date of Loss: 06/07/2025
Customer File Number: MNC92506366
Policy Number:



Photo: 29

Date Taken:
07/21/2025

Taken By:
Daryl Seth

Description:
Left side of sleeper
- closeup with no
hail damage noted



Photo: 30

Date Taken:
07/21/2025

Taken By:
Daryl Seth

Description:
Left door -
overview

Claim Photo

Our File Number: 285-000665
Adjuster: Kevin Parker
Insured: Silver Water Trucking
Date of Loss: 06/07/2025
Customer File Number: MNC92506366
Policy Number:




Photo: 31

Date Taken:
07/21/2025

Taken By:
Daryl Seth

Description:
Left door -
closeup with no
hail damage noted



Photo: 32

Date Taken:
07/21/2025

Taken By:
Daryl Seth

Description:
Left filter cover-
overview

Claim Photo

Our File Number: 285-000665
Adjuster: Kevin Parker
Insured: Silver Water Trucking
Date of Loss: 06/07/2025
Customer File Number: MNC92506366
Policy Number:



Photo: 33

Date Taken:
07/21/2025

Taken By:
Daryl Seth

Description:
Left filter cover-
hail dent




Photo: 34

Date Taken:
07/21/2025

Taken By:
Daryl Seth

Description:
Left filter cover-
hail dent

Claim Photo

Our File Number: 285-000665
Adjuster: Kevin Parker
Insured: Silver Water Trucking
Date of Loss: 06/07/2025
Customer File Number: MNC92506366
Policy Number:



Photo: 35

Date Taken:
07/21/2025

Taken By:
Daryl Seth

Description:
Left filter coverage
-



Photo: 36

Date Taken:
07/21/2025

Taken By:
Daryl Seth

Description:
Left front -
overview

Claim Photo

Our File Number: 285-000665
Adjuster: Kevin Parker
Insured: Silver Water Trucking
Date of Loss: 06/07/2025
Customer File Number: MNC92506366
Policy Number:



Photo: 37

Date Taken:
07/21/2025

Taken By:
Daryl Seth

Description:
Left front - closeup
with no hail
damage noted



Photo: 38

Date Taken:
07/21/2025

Taken By:
Daryl Seth

Description:
Hood overview
with no hail
damage noted

Claim Photo

Our File Number: 285-000665
Adjuster: Kevin Parker
Insured: Silver Water Trucking
Date of Loss: 06/07/2025
Customer File Number: MNC92506366
Policy Number:



Photo: 39

Date Taken:
07/21/2025

Taken By:
Daryl Seth

Description:
Hood overview
with no hail
damage noted



Photo: 40

Date Taken:
07/21/2025

Taken By:
Daryl Seth

Description:
Right filter top-
overview

Claim Photo

Our File Number: 285-000665
Adjuster: Kevin Parker
Insured: Silver Water Trucking
Date of Loss: 06/07/2025
Customer File Number: MNC92506366
Policy Number:



Photo: 41

Date Taken:
07/21/2025

Taken By:
Daryl Seth

Description:
Right filter top-
closeup with no
hail damage noted



Photo: 42

Date Taken:
07/21/2025

Taken By:
Daryl Seth

Description:
Right filter top-
overview

Claim Photo

Our File Number: 285-000665
Adjuster: Kevin Parker
Insured: Silver Water Trucking
Date of Loss: 06/07/2025
Customer File Number: MNC92506366
Policy Number:



Photo: 43

Date Taken:
07/21/2025

Taken By:
Daryl Seth

Description:
Right filter top-
closeup with no
hail damage noted



Photo: 44

Date Taken:
07/21/2025

Taken By:
Daryl Seth

Description:
Sleeper roof- with
no hail damage
noted

Claim Photo

Our File Number: 285-000665
Adjuster: Kevin Parker
Insured: Silver Water Trucking
Date of Loss: 06/07/2025
Customer File Number: MNC92506366
Policy Number:



Photo: 45

Date Taken:
07/21/2025

Taken By:
Daryl Seth

Description:
Sleeper roof- with
no hail damage
noted



Photo: 46

Date Taken:
07/21/2025

Taken By:
Daryl Seth

Description:
Cab roof- with no
hail damage noted

Claim Photo

Our File Number: 285-000665
Adjuster: Kevin Parker
Insured: Silver Water Trucking
Date of Loss: 06/07/2025
Customer File Number: MNC92506366
Policy Number:



Photo: 47

Date Taken:
07/21/2025

Taken By:
Daryl Seth

Description:
Horn- with no hail
damage noted



Photo: 48

Date Taken:
07/21/2025

Taken By:
Daryl Seth

Description:
Horn- with no hail
damage noted

Claim Photo

Our File Number: 285-000665
Adjuster: Kevin Parker
Insured: Silver Water Trucking
Date of Loss: 06/07/2025
Customer File Number: MNC92506366
Policy Number:



Photo: 49

Date Taken:
07/21/2025

Taken By:
Daryl Seth

Description:
Chrome deflector-
overview



Photo: 50

Date Taken:
07/21/2025

Taken By:
Daryl Seth

Description:
Chrome deflector-
right side

Claim Photo

Our File Number: 285-000665
Adjuster: Kevin Parker
Insured: Silver Water Trucking
Date of Loss: 06/07/2025
Customer File Number: MNC92506366
Policy Number:



Photo: 51

Date Taken:
07/21/2025

Taken By:
Daryl Seth

Description:
Chrome deflector-
right side, hail dent




Photo: 52

Date Taken:
07/21/2025

Taken By:
Daryl Seth

Description:
Chrome deflector-
right side, hail dent

Claim Photo

Our File Number: 285-000665
Adjuster: Kevin Parker
Insured: Silver Water Trucking
Date of Loss: 06/07/2025
Customer File Number: MNC92506366
Policy Number:




Photo: 53

Date Taken:
07/21/2025

Taken By:
Daryl Seth

Description:
Hail scope sheet on insured tractor