

Claim Photo

Our File Number: 277-065586
Adjuster: Jason Baka
Insured: URM STORES
Date of Loss: 12/07/2025
Customer File Number: 001835-012207-AP-01
Policy Number:



Photo: 1

Date Taken:
12/17/2025

Taken By:
Brant Smith

Description:
Front



Photo: 2

Date Taken:
12/17/2025

Taken By:
Brant Smith

Description:
Front passenger
side

Claim Photo

Our File Number: 277-065586
Adjuster: Jason Baka
Insured: URM STORES
Date of Loss: 12/07/2025
Customer File Number: 001835-012207-AP-01
Policy Number:



Photo: 3

Date Taken:
12/17/2025

Taken By:
Brant Smith

Description:
Passenger side



Photo: 4

Date Taken:
12/17/2025

Taken By:
Brant Smith

Description:
Rear passenger side

Claim Photo

Our File Number: 277-065586
Adjuster: Jason Baka
Insured: URM STORES
Date of Loss: 12/07/2025
Customer File Number: 001835-012207-AP-01
Policy Number:



Photo: 5

Date Taken:
12/17/2025

Taken By:
Brant Smith

Description:
Rear



Photo: 6

Date Taken:
12/17/2025

Taken By:
Brant Smith

Description:
Rear driver's side

Claim Photo

Our File Number: 277-065586
Adjuster: Jason Baka
Insured: URM STORES
Date of Loss: 12/07/2025
Customer File Number: 001835-012207-AP-01
Policy Number:



Photo: 7

Date Taken:
12/17/2025

Taken By:
Brant Smith

Description:
Driver's side



Photo: 8

Date Taken:
12/17/2025

Taken By:
Brant Smith

Description:
Front driver's side

Claim Photo

Our File Number: 277-065586
Adjuster: Jason Baka
Insured: URM STORES
Date of Loss: 12/07/2025
Customer File Number: 001835-012207-AP-01
Policy Number:



Photo: 9

Date Taken:
12/17/2025

Taken By:
Brant Smith

Description:
Driver's side ID
number



Photo: 10

Date Taken:
12/17/2025

Taken By:
Brant Smith

Description:
Driver's side label

Claim Photo

Our File Number: 277-065586
Adjuster: Jason Baka
Insured: URM STORES
Date of Loss: 12/07/2025
Customer File Number: 001835-012207-AP-01
Policy Number:




Photo: 11

Date Taken:
12/17/2025

Taken By:
Brant Smith

Description:
Manufacturer label
with VIN




Photo: 12

Date Taken:
12/17/2025

Taken By:
Brant Smith

Description:
Permit with VIN

Claim Photo

Our File Number: 277-065586
Adjuster: Jason Baka
Insured: URM STORES
Date of Loss: 12/07/2025
Customer File Number: 001835-012207-AP-01
Policy Number:



Photo: 13

Date Taken:
12/17/2025

Taken By:
Brant Smith

Description:
Dash



Photo: 14

Date Taken:
12/17/2025

Taken By:
Brant Smith

Description:
Dash - no power

Claim Photo

Our File Number: 277-065586
Adjuster: Jason Baka
Insured: URM STORES
Date of Loss: 12/07/2025
Customer File Number: 001835-012207-AP-01
Policy Number:




Photo: 15

Date Taken:
12/17/2025

Taken By:
Brant Smith

Description:
Cab overview



Photo: 16

Date Taken:
12/17/2025

Taken By:
Brant Smith

Description:
Damage to
passenger side

Claim Photo

Our File Number: 277-065586
Adjuster: Jason Baka
Insured: URM STORES
Date of Loss: 12/07/2025
Customer File Number: 001835-012207-AP-01
Policy Number:



Photo: 17

Date Taken:
12/17/2025

Taken By:
Brant Smith

Description:
Damage to
passenger side



Photo: 18

Date Taken:
12/17/2025

Taken By:
Brant Smith

Description:
Passenger side
hood measurement
at over front axle

Claim Photo

Our File Number: 277-065586
Adjuster: Jason Baka
Insured: URM STORES
Date of Loss: 12/07/2025
Customer File Number: 001835-012207-AP-01
Policy Number:



Photo: 19

Date Taken:
12/17/2025

Taken By:
Brant Smith

Description:
Passenger side
hood out of
alignment with
bottom panel



Photo: 20

Date Taken:
12/17/2025

Taken By:
Brant Smith

Description:
Damage to
passenger side
steps and casing

Claim Photo

Our File Number: 277-065586
Adjuster: Jason Baka
Insured: URM STORES
Date of Loss: 12/07/2025
Customer File Number: 001835-012207-AP-01
Policy Number:




Photo: 21

Date Taken:
12/17/2025

Taken By:
Brant Smith

Description:
Damage to
passenger side fuel
tank, strap, and
casing



Photo: 22

Date Taken:
12/17/2025

Taken By:
Brant Smith

Description:
Damage to
passenger side fuel
tank and casing

Claim Photo

Our File Number: 277-065586
Adjuster: Jason Baka
Insured: URM STORES
Date of Loss: 12/07/2025
Customer File Number: 001835-012207-AP-01
Policy Number:



Photo: 23

Date Taken:
12/17/2025

Taken By:
Brant Smith

Description:
Passenger side cab
out of alignment



Photo: 24

Date Taken:
12/17/2025

Taken By:
Brant Smith

Description:
Cab out of
alignment and
damage to muffler

Claim Photo

Our File Number: 277-065586
Adjuster: Jason Baka
Insured: URM STORES
Date of Loss: 12/07/2025
Customer File Number: 001835-012207-AP-01
Policy Number:



Photo: 25

Date Taken:
12/17/2025

Taken By:
Brant Smith

Description:
Damage to
passenger side rear
window, muffler,
and brackets



Photo: 26

Date Taken:
12/17/2025

Taken By:
Brant Smith

Description:
Damage to rear
passenger side
window, muffler,
and cab

Claim Photo

Our File Number: 277-065586
Adjuster: Jason Baka
Insured: URM STORES
Date of Loss: 12/07/2025
Customer File Number: 001835-012207-AP-01
Policy Number:




Photo: 27

Date Taken:
12/17/2025

Taken By:
Brant Smith

Description:
Chassis overview



Photo: 28

Date Taken:
12/17/2025

Taken By:
Brant Smith

Description:
Rear license plate

Claim Photo

Our File Number: 277-065586
Adjuster: Jason Baka
Insured: URM STORES
Date of Loss: 12/07/2025
Customer File Number: 001835-012207-AP-01
Policy Number:




Photo: 29

Date Taken:
12/17/2025

Taken By:
Brant Smith

Description:
Undercarriage
overview




Photo: 30

Date Taken:
12/17/2025

Taken By:
Brant Smith

Description:
Bottom of cab

Claim Photo

Our File Number: 277-065586
Adjuster: Jason Baka
Insured: URM STORES
Date of Loss: 12/07/2025
Customer File Number: 001835-012207-AP-01
Policy Number:



Photo: 31

Date Taken:
12/17/2025

Taken By:
Brant Smith

Description:
Undercarriage



Photo: 32

Date Taken:
12/17/2025

Taken By:
Brant Smith

Description:
Front passenger
side undercarriage

Claim Photo

Our File Number: 277-065586
Adjuster: Jason Baka
Insured: URM STORES
Date of Loss: 12/07/2025
Customer File Number: 001835-012207-AP-01
Policy Number:



Photo: 33

Date Taken:
12/17/2025

Taken By:
Brant Smith

Description:
Front driver's side
undercarriage




Photo: 34

Date Taken:
12/17/2025

Taken By:
Brant Smith

Description:
Driver's side engine

Claim Photo

Our File Number: 277-065586
Adjuster: Jason Baka
Insured: URM STORES
Date of Loss: 12/07/2025
Customer File Number: 001835-012207-AP-01
Policy Number:




Photo: 35

Date Taken:
12/17/2025

Taken By:
Brant Smith

Description:
Engine overview




Photo: 36

Date Taken:
12/17/2025

Taken By:
Brant Smith

Description:
Passenger side
engine

Claim Photo

Our File Number: 277-065586
Adjuster: Jason Baka
Insured: URM STORES
Date of Loss: 12/07/2025
Customer File Number: 001835-012207-AP-01
Policy Number:




Photo: 37

Date Taken:
12/17/2025

Taken By:
Brant Smith

Description:
Passenger side
frame label



Photo: 38

Date Taken:
12/17/2025

Taken By:
Brant Smith

Description:
Damage to
passenger side
panel

Claim Photo

Our File Number: 277-065586
Adjuster: Jason Baka
Insured: URM STORES
Date of Loss: 12/07/2025
Customer File Number: 001835-012207-AP-01
Policy Number:



Photo: 39

Date Taken:
12/17/2025

Taken By:
Brant Smith

Description:
Truck model



Photo: 40

Date Taken:
12/17/2025

Taken By:
Brant Smith

Description:
Front license plate

Claim Photo

Our File Number: 277-065586
Adjuster: Jason Baka
Insured: URM STORES
Date of Loss: 12/07/2025
Customer File Number: 001835-012207-AP-01
Policy Number:



Photo: 41

Date Taken:
12/17/2025

Taken By:
Brant Smith

Description:
Damage to
passenger side
bumper



Photo: 42

Date Taken:
12/17/2025

Taken By:
Brant Smith

Description:
Driver's side front
wheel

Claim Photo

Our File Number: 277-065586
Adjuster: Jason Baka
Insured: URM STORES
Date of Loss: 12/07/2025
Customer File Number: 001835-012207-AP-01
Policy Number:



Photo: 43

Date Taken:
12/17/2025

Taken By:
Brant Smith

Description:
Driver's side front
steering tire



Photo: 44

Date Taken:
12/17/2025

Taken By:
Brant Smith

Description:
Driver's side front
outside driver

Claim Photo

Our File Number: 277-065586
Adjuster: Jason Baka
Insured: URM STORES
Date of Loss: 12/07/2025
Customer File Number: 001835-012207-AP-01
Policy Number:



Photo: 45

Date Taken:
12/17/2025

Taken By:
Brant Smith

Description:
Front driver's side
wheels



Photo: 46

Date Taken:
12/17/2025

Taken By:
Brant Smith

Description:
Inside driver wheel

Claim Photo

Our File Number: 277-065586
Adjuster: Jason Baka
Insured: URM STORES
Date of Loss: 12/07/2025
Customer File Number: 001835-012207-AP-01
Policy Number:




Photo: 47

Date Taken:
12/17/2025

Taken By:
Brant Smith

Description:
Driver's side rear
wheels



Photo: 48

Date Taken:
12/17/2025

Taken By:
Brant Smith

Description:
Driver's side front
outside driver

Claim Photo

Our File Number: 277-065586
Adjuster: Jason Baka
Insured: URM STORES
Date of Loss: 12/07/2025
Customer File Number: 001835-012207-AP-01
Policy Number:



Photo: 49

Date Taken:
12/17/2025

Taken By:
Brant Smith

Description:
Driver's side front
inside driver




Photo: 50

Date Taken:
12/17/2025

Taken By:
Brant Smith

Description:
Driver's side rear
outside driver

Claim Photo

Our File Number: 277-065586
Adjuster: Jason Baka
Insured: URM STORES
Date of Loss: 12/07/2025
Customer File Number: 001835-012207-AP-01
Policy Number:



Photo: 51

Date Taken:
12/17/2025

Taken By:
Brant Smith

Description:
Driver's side rear
inside driver




Photo: 52

Date Taken:
12/17/2025

Taken By:
Brant Smith

Description:
Front passenger
wheel

Claim Photo

Our File Number: 277-065586
Adjuster: Jason Baka
Insured: URM STORES
Date of Loss: 12/07/2025
Customer File Number: 001835-012207-AP-01
Policy Number:



Photo: 53

Date Taken:
12/17/2025

Taken By:
Brant Smith

Description:
Front passenger
steering tire



Photo: 54

Date Taken:
12/17/2025

Taken By:
Brant Smith

Description:
Front passenger
side front driver

Claim Photo

Our File Number: 277-065586
Adjuster: Jason Baka
Insured: URM STORES
Date of Loss: 12/07/2025
Customer File Number: 001835-012207-AP-01
Policy Number:



Photo: 55

Date Taken:
12/17/2025

Taken By:
Brant Smith

Description:
Front passenger
front outside driver



Photo: 56

Date Taken:
12/17/2025

Taken By:
Brant Smith

Description:
Front passenger
inside driver

Claim Photo

Our File Number: 277-065586
Adjuster: Jason Baka
Insured: URM STORES
Date of Loss: 12/07/2025
Customer File Number: 001835-012207-AP-01
Policy Number:



Photo: 57

Date Taken:
12/17/2025

Taken By:
Brant Smith

Description:
Front passenger
side wheels



Photo: 58

Date Taken:
12/17/2025

Taken By:
Brant Smith

Description:
Rear passenger side
rear outside wheel

Claim Photo

Our File Number: 277-065586
Adjuster: Jason Baka
Insured: URM STORES
Date of Loss: 12/07/2025
Customer File Number: 001835-012207-AP-01
Policy Number:



Photo: 59

Date Taken:
12/17/2025

Taken By:
Brant Smith

Description:
Passenger side rear
outside tire



Photo: 60

Date Taken:
12/17/2025

Taken By:
Brant Smith

Description:
Passenger side rear
inside tire

Claim Photo

Our File Number: 277-065586
Adjuster: Jason Baka
Insured: URM STORES
Date of Loss: 12/07/2025
Customer File Number: 001835-012207-AP-01
Policy Number:



Photo: 61

Date Taken:
12/17/2025

Taken By:
Brant Smith

Description:
Passenger side rear
wheels



Photo: 62

Date Taken:
12/17/2025

Taken By:
Brant Smith

Description:
Damage to
passenger side
muffler

Claim Photo

Our File Number: 277-065586
Adjuster: Jason Baka
Insured: URM STORES
Date of Loss: 12/07/2025
Customer File Number: 001835-012207-AP-01
Policy Number:




Photo: 63

Date Taken:
12/17/2025

Taken By:
Brant Smith

Description:
Damage to
passenger side
wind break




Photo: 64

Date Taken:
12/17/2025

Taken By:
Brant Smith

Description:
Damage to
passenger side cab

Claim Photo

Our File Number: 277-065586
Adjuster: Jason Baka
Insured: URM STORES
Date of Loss: 12/07/2025
Customer File Number: 001835-012207-AP-01
Policy Number:




Photo: 65

Date Taken:
12/17/2025

Taken By:
Brant Smith

Description:
Damage to
passenger side cab




Photo: 66

Date Taken:
12/17/2025

Taken By:
Brant Smith

Description:
Damage to
passenger side cab

Claim Photo

Our File Number: 277-065586
Adjuster: Jason Baka
Insured: URM STORES
Date of Loss: 12/07/2025
Customer File Number: 001835-012207-AP-01
Policy Number:



Photo: 67

Date Taken:
12/17/2025

Taken By:
Brant Smith

Description:
Damage to
passenger side cab



Photo: 68

Date Taken:
12/17/2025

Taken By:
Brant Smith

Description:
Damage to
passenger side cab

Claim Photo

Our File Number: 277-065586
Adjuster: Jason Baka
Insured: URM STORES
Date of Loss: 12/07/2025
Customer File Number: 001835-012207-AP-01
Policy Number:



Photo: 69

Date Taken:
12/17/2025

Taken By:
Brant Smith

Description:
Damage to
passenger side cab



Photo: 70

Date Taken:
12/17/2025

Taken By:
Brant Smith

Description:
Damage to
passenger side
framing

Claim Photo

Our File Number: 277-065586
Adjuster: Jason Baka
Insured: URM STORES
Date of Loss: 12/07/2025
Customer File Number: 001835-012207-AP-01
Policy Number:



Photo: 71

Date Taken:
12/17/2025

Taken By:
Brant Smith

Description:
Driver's side panel
missing




Photo: 72

Date Taken:
12/17/2025

Taken By:
Brant Smith

Description:
Overview of cab
floor

Claim Photo

Our File Number: 277-065586
Adjuster: Jason Baka
Insured: URM STORES
Date of Loss: 12/07/2025
Customer File Number: 001835-012207-AP-01
Policy Number:



Photo: 73

Date Taken:
12/17/2025

Taken By:
Brant Smith

Description:
Overview of cab
floor



Photo: 74

Date Taken:
12/17/2025

Taken By:
Brant Smith

Description:
Overview of cab
floor

Claim Photo

Our File Number: 277-065586
Adjuster: Jason Baka
Insured: URM STORES
Date of Loss: 12/07/2025
Customer File Number: 001835-012207-AP-01
Policy Number:



Photo: 75

Date Taken:
12/17/2025

Taken By:
Brant Smith

Description:
Hood out of
alignment



Photo: 76

Date Taken:
12/17/2025

Taken By:
Brant Smith

Description:
Passenger side
hood measurement

Claim Photo

Our File Number: 277-065586
Adjuster: Jason Baka
Insured: URM STORES
Date of Loss: 12/07/2025
Customer File Number: 001835-012207-AP-01
Policy Number:



Photo: 77

Date Taken:
12/17/2025

Taken By:
Brant Smith

Description:
Passenger side
hood measurement
at rear