

Claim Photo

Our File Number: 277-065485
Adjuster: Mike Hogan
Insured: Martin Transportation Systems Inc
Date of Loss: 09/12/2025
Customer File Number: IWL25031111
Policy Number:




Photo: 1

Date Taken:
12/10/2025

Taken By:
Jeffery Craven

Description:
VIN
3ALXA7CG1JDJN
7479.



Photo: 2

Date Taken:
12/10/2025

Taken By:
Jeffery Craven

Description:
No power to
odometer. Unable
to get mileage.

Claim Photo

Our File Number: 277-065485
Adjuster: Mike Hogan
Insured: Martin Transportation Systems Inc
Date of Loss: 09/12/2025
Customer File Number: IWL25031111
Policy Number:




Photo: 3

Date Taken:
12/10/2025

Taken By:
Jeffery Craven

Description:
Door label.




Photo: 4

Date Taken:
12/10/2025

Taken By:
Jeffery Craven

Description:
Door label.

Claim Photo

Our File Number: 277-065485
Adjuster: Mike Hogan
Insured: Martin Transportation Systems Inc
Date of Loss: 09/12/2025
Customer File Number: IWL25031111
Policy Number:




Photo: 5

Date Taken:
12/10/2025

Taken By:
Jeffery Craven

Description:
Tractor #17030.



Photo: 6

Date Taken:
12/10/2025

Taken By:
Jeffery Craven

Description:
USDOT #215732.

Claim Photo

Our File Number: 277-065485
Adjuster: Mike Hogan
Insured: Martin Transportation Systems Inc
Date of Loss: 09/12/2025
Customer File Number: IWL25031111
Policy Number:



Photo: 7

Date Taken:
12/10/2025

Taken By:
Jeffery Craven

Description:
4-corner view.




Photo: 8

Date Taken:
12/10/2025

Taken By:
Jeffery Craven

Description:
4-corner view.

Claim Photo

Our File Number: 277-065485
Adjuster: Mike Hogan
Insured: Martin Transportation Systems Inc
Date of Loss: 09/12/2025
Customer File Number: IWL25031111
Policy Number:



Photo: 9

Date Taken:
12/10/2025

Taken By:
Jeffery Craven

Description:
4-corner view.



Photo: 10

Date Taken:
12/10/2025

Taken By:
Jeffery Craven

Description:
4-corner view.

Claim Photo

Our File Number: 277-065485
Adjuster: Mike Hogan
Insured: Martin Transportation Systems Inc
Date of Loss: 09/12/2025
Customer File Number: IWL25031111
Policy Number:



Photo: 11

Date Taken:
12/10/2025

Taken By:
Jeffery Craven

Description:
Front end damage.
Overview.



Photo: 12

Date Taken:
12/10/2025

Taken By:
Jeffery Craven

Description:
Front end damage.

Claim Photo

Our File Number: 277-065485
Adjuster: Mike Hogan
Insured: Martin Transportation Systems Inc
Date of Loss: 09/12/2025
Customer File Number: IWL25031111
Policy Number:



Photo: 13

Date Taken:
12/10/2025

Taken By:
Jeffery Craven

Description:
Front end damage.



Photo: 14

Date Taken:
12/10/2025

Taken By:
Jeffery Craven

Description:
Front end damage.

Claim Photo

Our File Number: 277-065485
Adjuster: Mike Hogan
Insured: Martin Transportation Systems Inc
Date of Loss: 09/12/2025
Customer File Number: IWL25031111
Policy Number:



Photo: 15

Date Taken:
12/10/2025

Taken By:
Jeffery Craven

Description:
Front end damage.




Photo: 16

Date Taken:
12/10/2025

Taken By:
Jeffery Craven

Description:
Front end damage.

Claim Photo

Our File Number: 277-065485
Adjuster: Mike Hogan
Insured: Martin Transportation Systems Inc
Date of Loss: 09/12/2025
Customer File Number: IWL25031111
Policy Number:



Photo: 17

Date Taken:
12/10/2025

Taken By:
Jeffery Craven

Description:
Front end damage.



Photo: 18

Date Taken:
12/10/2025

Taken By:
Jeffery Craven

Description:
Front end damage.

Claim Photo

Our File Number: 277-065485
Adjuster: Mike Hogan
Insured: Martin Transportation Systems Inc
Date of Loss: 09/12/2025
Customer File Number: IWL25031111
Policy Number:



Photo: 19

Date Taken:
12/10/2025

Taken By:
Jeffery Craven

Description:
Front end damage.



Photo: 20

Date Taken:
12/10/2025

Taken By:
Jeffery Craven

Description:
Front end damage.

Claim Photo

Our File Number: 277-065485
Adjuster: Mike Hogan
Insured: Martin Transportation Systems Inc
Date of Loss: 09/12/2025
Customer File Number: IWL25031111
Policy Number:



Photo: 21

Date Taken:
12/10/2025

Taken By:
Jeffery Craven

Description:
Front end damage.



Photo: 22

Date Taken:
12/10/2025

Taken By:
Jeffery Craven

Description:
Front end damage.

Claim Photo

Our File Number: 277-065485
Adjuster: Mike Hogan
Insured: Martin Transportation Systems Inc
Date of Loss: 09/12/2025
Customer File Number: IWL25031111
Policy Number:



Photo: 23

Date Taken:
12/10/2025

Taken By:
Jeffery Craven

Description:
Front end damage.



Photo: 24

Date Taken:
12/10/2025

Taken By:
Jeffery Craven

Description:
Front end damage.

Claim Photo

Our File Number: 277-065485
Adjuster: Mike Hogan
Insured: Martin Transportation Systems Inc
Date of Loss: 09/12/2025
Customer File Number: IWL25031111
Policy Number:



Photo: 25

Date Taken:
12/10/2025

Taken By:
Jeffery Craven

Description:
Front end damage.



Photo: 26

Date Taken:
12/10/2025

Taken By:
Jeffery Craven

Description:
Left side front end.

Claim Photo

Our File Number: 277-065485
Adjuster: Mike Hogan
Insured: Martin Transportation Systems Inc
Date of Loss: 09/12/2025
Customer File Number: IWL25031111
Policy Number:




Photo: 27

Date Taken:
12/10/2025

Taken By:
Jeffery Craven

Description:
Left side front end.



Photo: 28

Date Taken:
12/10/2025

Taken By:
Jeffery Craven

Description:
Left side front end.

Claim Photo

Our File Number: 277-065485
Adjuster: Mike Hogan
Insured: Martin Transportation Systems Inc
Date of Loss: 09/12/2025
Customer File Number: IWL25031111
Policy Number:



Photo: 29

Date Taken:
12/10/2025

Taken By:
Jeffery Craven

Description:
Left side front end.



Photo: 30

Date Taken:
12/10/2025

Taken By:
Jeffery Craven

Description:
Left side front end.

Claim Photo

Our File Number: 277-065485
Adjuster: Mike Hogan
Insured: Martin Transportation Systems Inc
Date of Loss: 09/12/2025
Customer File Number: IWL25031111
Policy Number:



Photo: 31

Date Taken:
12/10/2025

Taken By:
Jeffery Craven

Description:
Left side.



Photo: 32

Date Taken:
12/10/2025

Taken By:
Jeffery Craven

Description:
Left side.

Claim Photo

Our File Number: 277-065485
Adjuster: Mike Hogan
Insured: Martin Transportation Systems Inc
Date of Loss: 09/12/2025
Customer File Number: IWL25031111
Policy Number:



Photo: 33

Date Taken:
12/10/2025

Taken By:
Jeffery Craven

Description:
Left side.



Photo: 34

Date Taken:
12/10/2025

Taken By:
Jeffery Craven

Description:
Left side.

Claim Photo

Our File Number: 277-065485
Adjuster: Mike Hogan
Insured: Martin Transportation Systems Inc
Date of Loss: 09/12/2025
Customer File Number: IWL25031111
Policy Number:



Photo: 35

Date Taken:
12/10/2025

Taken By:
Jeffery Craven

Description:
Left side.



Photo: 36

Date Taken:
12/10/2025

Taken By:
Jeffery Craven

Description:
Left side.

Claim Photo

Our File Number: 277-065485
Adjuster: Mike Hogan
Insured: Martin Transportation Systems Inc
Date of Loss: 09/12/2025
Customer File Number: IWL25031111
Policy Number:



Photo: 37

Date Taken:
12/10/2025

Taken By:
Jeffery Craven

Description:
Left side.



Photo: 38

Date Taken:
12/10/2025

Taken By:
Jeffery Craven

Description:
Left side.

Claim Photo

Our File Number: 277-065485
Adjuster: Mike Hogan
Insured: Martin Transportation Systems Inc
Date of Loss: 09/12/2025
Customer File Number: IWL25031111
Policy Number:



Photo: 39

Date Taken:
12/10/2025

Taken By:
Jeffery Craven

Description:
Rear.



Photo: 40

Date Taken:
12/10/2025

Taken By:
Jeffery Craven

Description:
Rear.

Claim Photo

Our File Number: 277-065485
Adjuster: Mike Hogan
Insured: Martin Transportation Systems Inc
Date of Loss: 09/12/2025
Customer File Number: IWL25031111
Policy Number:



Photo: 41

Date Taken:
12/10/2025

Taken By:
Jeffery Craven

Description:
Rear.



Photo: 42

Date Taken:
12/10/2025

Taken By:
Jeffery Craven

Description:
Right side.

Claim Photo

Our File Number: 277-065485
Adjuster: Mike Hogan
Insured: Martin Transportation Systems Inc
Date of Loss: 09/12/2025
Customer File Number: IWL25031111
Policy Number:



Photo: 43

Date Taken:
12/10/2025

Taken By:
Jeffery Craven

Description:
Right side.



Photo: 44

Date Taken:
12/10/2025

Taken By:
Jeffery Craven

Description:
Right side.

Claim Photo

Our File Number: 277-065485
Adjuster: Mike Hogan
Insured: Martin Transportation Systems Inc
Date of Loss: 09/12/2025
Customer File Number: IWL25031111
Policy Number:



Photo: 45

Date Taken:
12/10/2025

Taken By:
Jeffery Craven

Description:
Right side. Appears
to be prior damage
to mirror.



Photo: 46

Date Taken:
12/10/2025

Taken By:
Jeffery Craven

Description:
Right side.

Claim Photo

Our File Number: 277-065485
Adjuster: Mike Hogan
Insured: Martin Transportation Systems Inc
Date of Loss: 09/12/2025
Customer File Number: IWL25031111
Policy Number:



Photo: 47

Date Taken:
12/10/2025

Taken By:
Jeffery Craven

Description:
Right side.



Photo: 48

Date Taken:
12/10/2025

Taken By:
Jeffery Craven

Description:
Right side.

Claim Photo

Our File Number: 277-065485
Adjuster: Mike Hogan
Insured: Martin Transportation Systems Inc
Date of Loss: 09/12/2025
Customer File Number: IWL25031111
Policy Number:



Photo: 49

Date Taken:
12/10/2025

Taken By:
Jeffery Craven

Description:
Right side.



Photo: 50

Date Taken:
12/10/2025

Taken By:
Jeffery Craven

Description:
Right side.

Claim Photo

Our File Number: 277-065485
Adjuster: Mike Hogan
Insured: Martin Transportation Systems Inc
Date of Loss: 09/12/2025
Customer File Number: IWL25031111
Policy Number:



Photo: 51

Date Taken:
12/10/2025

Taken By:
Jeffery Craven

Description:
Right side.



Photo: 52

Date Taken:
12/10/2025

Taken By:
Jeffery Craven

Description:
Right side.

Claim Photo

Our File Number: 277-065485
Adjuster: Mike Hogan
Insured: Martin Transportation Systems Inc
Date of Loss: 09/12/2025
Customer File Number: IWL25031111
Policy Number:



Photo: 53

Date Taken:
12/10/2025

Taken By:
Jeffery Craven

Description:
Right side.



Photo: 54

Date Taken:
12/10/2025

Taken By:
Jeffery Craven

Description:
Right side.

Claim Photo

Our File Number: 277-065485
Adjuster: Mike Hogan
Insured: Martin Transportation Systems Inc
Date of Loss: 09/12/2025
Customer File Number: IWL25031111
Policy Number:



Photo: 55

Date Taken:
12/10/2025

Taken By:
Jeffery Craven

Description:
Under hood, left
side.




Photo: 56

Date Taken:
12/10/2025

Taken By:
Jeffery Craven

Description:
Under hood, left
side.

Claim Photo

Our File Number: 277-065485
Adjuster: Mike Hogan
Insured: Martin Transportation Systems Inc
Date of Loss: 09/12/2025
Customer File Number: IWL25031111
Policy Number:




Photo: 57

Date Taken:
12/10/2025

Taken By:
Jeffery Craven

Description:
Under hood, left side.



Photo: 58

Date Taken:
12/10/2025

Taken By:
Jeffery Craven

Description:
Under hood, left side.

Claim Photo

Our File Number: 277-065485
Adjuster: Mike Hogan
Insured: Martin Transportation Systems Inc
Date of Loss: 09/12/2025
Customer File Number: IWL25031111
Policy Number:



Photo: 59

Date Taken:
12/10/2025

Taken By:
Jeffery Craven

Description:
Under hood, left
side.



Photo: 60

Date Taken:
12/10/2025

Taken By:
Jeffery Craven

Description:
Under hood, left
side.

Claim Photo

Our File Number: 277-065485
Adjuster: Mike Hogan
Insured: Martin Transportation Systems Inc
Date of Loss: 09/12/2025
Customer File Number: IWL25031111
Policy Number:



Photo: 61

Date Taken:
12/10/2025

Taken By:
Jeffery Craven

Description:
Under hood, left side.



Photo: 62

Date Taken:
12/10/2025

Taken By:
Jeffery Craven

Description:
Under hood, left side.

Claim Photo

Our File Number: 277-065485
Adjuster: Mike Hogan
Insured: Martin Transportation Systems Inc
Date of Loss: 09/12/2025
Customer File Number: IWL25031111
Policy Number:



Photo: 63

Date Taken:
12/10/2025

Taken By:
Jeffery Craven

Description:
Under hood, left
side.



Photo: 64

Date Taken:
12/10/2025

Taken By:
Jeffery Craven

Description:
Under hood, right
side.

Claim Photo

Our File Number: 277-065485
Adjuster: Mike Hogan
Insured: Martin Transportation Systems Inc
Date of Loss: 09/12/2025
Customer File Number: IWL25031111
Policy Number:



Photo: 65

Date Taken:
12/10/2025

Taken By:
Jeffery Craven

Description:
Under hood, right side.



Photo: 66

Date Taken:
12/10/2025

Taken By:
Jeffery Craven

Description:
Under hood, right side.

Claim Photo

Our File Number: 277-065485
Adjuster: Mike Hogan
Insured: Martin Transportation Systems Inc
Date of Loss: 09/12/2025
Customer File Number: IWL25031111
Policy Number:



Photo: 67

Date Taken:
12/10/2025

Taken By:
Jeffery Craven

Description:
Under hood, right
side.



Photo: 68

Date Taken:
12/10/2025

Taken By:
Jeffery Craven

Description:
Under hood, right
side.

Claim Photo

Our File Number: 277-065485
Adjuster: Mike Hogan
Insured: Martin Transportation Systems Inc
Date of Loss: 09/12/2025
Customer File Number: IWL25031111
Policy Number:



Photo: 69

Date Taken:
12/10/2025

Taken By:
Jeffery Craven

Description:
Under hood, right side.



Photo: 70

Date Taken:
12/10/2025

Taken By:
Jeffery Craven

Description:
Under hood, right side.

Claim Photo

Our File Number: 277-065485
Adjuster: Mike Hogan
Insured: Martin Transportation Systems Inc
Date of Loss: 09/12/2025
Customer File Number: IWL25031111
Policy Number:



Photo: 71

Date Taken:
12/10/2025

Taken By:
Jeffery Craven

Description:
Under front of
tractor.



Photo: 72

Date Taken:
12/10/2025

Taken By:
Jeffery Craven

Description:
Under front of
tractor.

Claim Photo

Our File Number: 277-065485
Adjuster: Mike Hogan
Insured: Martin Transportation Systems Inc
Date of Loss: 09/12/2025
Customer File Number: IWL25031111
Policy Number:



Photo: 73

Date Taken:
12/10/2025

Taken By:
Jeffery Craven

Description:
Under front of
tractor.




Photo: 74

Date Taken:
12/10/2025

Taken By:
Jeffery Craven

Description:
Under tractor from
behind front tires.

Claim Photo

Our File Number: 277-065485
Adjuster: Mike Hogan
Insured: Martin Transportation Systems Inc
Date of Loss: 09/12/2025
Customer File Number: IWL25031111
Policy Number:



Photo: 75

Date Taken:
12/10/2025

Taken By:
Jeffery Craven

Description:
Under tractor from
behind front tires.



Photo: 76

Date Taken:
12/10/2025

Taken By:
Jeffery Craven

Description:
Under tractor from
behind front tires.

Claim Photo

Our File Number: 277-065485
Adjuster: Mike Hogan
Insured: Martin Transportation Systems Inc
Date of Loss: 09/12/2025
Customer File Number: IWL25031111
Policy Number:



Photo: 77

Date Taken:
12/10/2025

Taken By:
Jeffery Craven

Description:
Under tractor from
behind front tires.




Photo: 78

Date Taken:
12/10/2025

Taken By:
Jeffery Craven

Description:
Under rear of
tractor.

Claim Photo

Our File Number: 277-065485
Adjuster: Mike Hogan
Insured: Martin Transportation Systems Inc
Date of Loss: 09/12/2025
Customer File Number: IWL25031111
Policy Number:



Photo: 79

Date Taken:
12/10/2025

Taken By:
Jeffery Craven

Description:
Under rear of
tractor.



Photo: 80

Date Taken:
12/10/2025

Taken By:
Jeffery Craven

Description:
Under rear of
tractor.

Claim Photo

Our File Number: 277-065485
Adjuster: Mike Hogan
Insured: Martin Transportation Systems Inc
Date of Loss: 09/12/2025
Customer File Number: IWL25031111
Policy Number:



Photo: 81

Date Taken:
12/10/2025

Taken By:
Jeffery Craven

Description:
Rear of tractor.



Photo: 82

Date Taken:
12/10/2025

Taken By:
Jeffery Craven

Description:
Rear of tractor.

Claim Photo

Our File Number: 277-065485
Adjuster: Mike Hogan
Insured: Martin Transportation Systems Inc
Date of Loss: 09/12/2025
Customer File Number: IWL25031111
Policy Number:



Photo: 83

Date Taken:
12/10/2025

Taken By:
Jeffery Craven

Description:
Rear of tractor.



Photo: 84

Date Taken:
12/10/2025

Taken By:
Jeffery Craven

Description:
Rear of tractor.

Claim Photo

Our File Number: 277-065485
Adjuster: Mike Hogan
Insured: Martin Transportation Systems Inc
Date of Loss: 09/12/2025
Customer File Number: IWL25031111
Policy Number:



Photo: 85

Date Taken:
12/10/2025

Taken By:
Jeffery Craven

Description:
Inside tractor.



Photo: 86

Date Taken:
12/10/2025

Taken By:
Jeffery Craven

Description:
Inside tractor.

Claim Photo

Our File Number: 277-065485
Adjuster: Mike Hogan
Insured: Martin Transportation Systems Inc
Date of Loss: 09/12/2025
Customer File Number: IWL25031111
Policy Number:




Photo: 87

Date Taken:
12/10/2025

Taken By:
Jeffery Craven

Description:
Inside tractor.



Photo: 88

Date Taken:
12/10/2025

Taken By:
Jeffery Craven

Description:
Inside tractor.

Claim Photo

Our File Number: 277-065485
Adjuster: Mike Hogan
Insured: Martin Transportation Systems Inc
Date of Loss: 09/12/2025
Customer File Number: IWL25031111
Policy Number:



Photo: 89

Date Taken:
12/10/2025

Taken By:
Jeffery Craven

Description:
Inside tractor.



Photo: 90

Date Taken:
12/10/2025

Taken By:
Jeffery Craven

Description:
Inside tractor.

Claim Photo

Our File Number: 277-065485
Adjuster: Mike Hogan
Insured: Martin Transportation Systems Inc
Date of Loss: 09/12/2025
Customer File Number: IWL25031111
Policy Number:



Photo: 91

Date Taken:
12/10/2025

Taken By:
Jeffery Craven

Description:
Inside tractor.




Photo: 92

Date Taken:
12/10/2025

Taken By:
Jeffery Craven

Description:
Tire tread depths.
Front left tire,
14/32nds.

Claim Photo

Our File Number: 277-065485
Adjuster: Mike Hogan
Insured: Martin Transportation Systems Inc
Date of Loss: 09/12/2025
Customer File Number: IWL25031111
Policy Number:



Photo: 93

Date Taken:
12/10/2025

Taken By:
Jeffery Craven

Description:
Tire tread depth.
Left side. Front
outer tire of rear
tires. 21/32nds.



Photo: 94

Date Taken:
12/10/2025

Taken By:
Jeffery Craven

Description:
Tire tread depth.
Left side. Front
inner tire of rear
tires. 7/32nds.

Claim Photo

Our File Number: 277-065485
Adjuster: Mike Hogan
Insured: Martin Transportation Systems Inc
Date of Loss: 09/12/2025
Customer File Number: IWL25031111
Policy Number:



Photo: 95

Date Taken:
12/10/2025

Taken By:
Jeffery Craven

Description:
Tire tread depth.
Left side. Rear
outer tire of rear
tires. 12/32nds.



Photo: 96

Date Taken:
12/10/2025

Taken By:
Jeffery Craven

Description:
Tire tread depth.
Left side. Rear
inner tire of rear
tires. 21/32nds.

Claim Photo

Our File Number: 277-065485
Adjuster: Mike Hogan
Insured: Martin Transportation Systems Inc
Date of Loss: 09/12/2025
Customer File Number: IWL25031111
Policy Number:



Photo: 97

Date Taken:
12/10/2025

Taken By:
Jeffery Craven

Description:
Tire tread depth.
Front right tire.
13/32nds.



Photo: 98

Date Taken:
12/10/2025

Taken By:
Jeffery Craven

Description:
Tire tread depth.
Right side. Front
outer tire of rear
tires. 8/32nds.

Claim Photo

Our File Number: 277-065485
Adjuster: Mike Hogan
Insured: Martin Transportation Systems Inc
Date of Loss: 09/12/2025
Customer File Number: IWL25031111
Policy Number:



Photo: 99

Date Taken:
12/10/2025

Taken By:
Jeffery Craven

Description:
Tire tread depth.
Right side. Front
inner tire of rear
tires. 5/32nds.



Photo: 100

Date Taken:
12/10/2025

Taken By:
Jeffery Craven

Description:
Tire tread depth.
Right side. Rear
outer tire of rear
tires. 12/32nds.

Claim Photo

Our File Number: 277-065485
Adjuster: Mike Hogan
Insured: Martin Transportation Systems Inc
Date of Loss: 09/12/2025
Customer File Number: IWL25031111
Policy Number:



Photo: 101

Date Taken:
12/10/2025

Taken By:
Jeffery Craven

Description:
Tire tread depth.
Right side. Rear
inner tire of rear
tires. 15/32nds.