

Claim Photo

Our File Number: 088-005720
Adjuster: Douglas Beck
Insured: Alouidor Transportation LLC / Jackson Alouidor
Date of Loss: 12/25/2025
Customer File Number: 235503315
Policy Number:




Photo: 1

Date Taken:
01/21/2026

Taken By:
Douglas Beck

Description:
VIN
1XPBD49X9ND767977




Photo: 2

Date Taken:
01/21/2026

Taken By:
Douglas Beck

Description:
VIN
1XPBD49X9ND767977

Claim Photo

Our File Number: 088-005720
Adjuster: Douglas Beck
Insured: Alouidor Transportation LLC / Jackson Alouidor
Date of Loss: 12/25/2025
Customer File Number: 235503315
Policy Number:



Photo: 3

Date Taken:
01/21/2026

Taken By:
Douglas Beck

Description:
VIN
1XPBD49X9ND76
7977



Photo: 4

Date Taken:
01/21/2026

Taken By:
Douglas Beck

Description:
Hand stalk control

Claim Photo

Our File Number: 088-005720
Adjuster: Douglas Beck
Insured: Alouidor Transportation LLC / Jackson Alouidor
Date of Loss: 12/25/2025
Customer File Number: 235503315
Policy Number:




Photo: 5

Date Taken:
01/21/2026

Taken By:
Douglas Beck

Description:
Odometer, no
power



Photo: 6

Date Taken:
01/21/2026

Taken By:
Douglas Beck

Description:
Left front

Claim Photo

Our File Number: 088-005720
Adjuster: Douglas Beck
Insured: Alouidor Transportation LLC / Jackson Alouidor
Date of Loss: 12/25/2025
Customer File Number: 235503315
Policy Number:



Photo: 7

Date Taken:
01/21/2026

Taken By:
Douglas Beck

Description:
Left rear




Photo: 8

Date Taken:
01/21/2026

Taken By:
Douglas Beck

Description:
Rear

Claim Photo

Our File Number: 088-005720
Adjuster: Douglas Beck
Insured: Alouidor Transportation LLC / Jackson Alouidor
Date of Loss: 12/25/2025
Customer File Number: 235503315
Policy Number:



Photo: 9

Date Taken:
01/21/2026

Taken By:
Douglas Beck

Description:
Right rear



Photo: 10

Date Taken:
01/21/2026

Taken By:
Douglas Beck

Description:
Right front

Claim Photo

Our File Number: 088-005720
Adjuster: Douglas Beck
Insured: Alouidor Transportation LLC / Jackson Alouidor
Date of Loss: 12/25/2025
Customer File Number: 235503315
Policy Number:



Photo: 11

Date Taken:
01/21/2026

Taken By:
Douglas Beck

Description:
Front



Photo: 12

Date Taken:
01/21/2026

Taken By:
Douglas Beck

Description:
Left front wheel

Claim Photo

Our File Number: 088-005720
Adjuster: Douglas Beck
Insured: Alouidor Transportation LLC / Jackson Alouidor
Date of Loss: 12/25/2025
Customer File Number: 235503315
Policy Number:




Photo: 13

Date Taken:
01/21/2026

Taken By:
Douglas Beck

Description:
Left front wheel



Photo: 14

Date Taken:
01/21/2026

Taken By:
Douglas Beck

Description:
Rear dual tire
overview

Claim Photo

Our File Number: 088-005720
Adjuster: Douglas Beck
Insured: Alouidor Transportation LLC / Jackson Alouidor
Date of Loss: 12/25/2025
Customer File Number: 235503315
Policy Number:



Photo: 15

Date Taken:
01/21/2026

Taken By:
Douglas Beck

Description:
Rear dual tire
inside view



Photo: 16

Date Taken:
01/21/2026

Taken By:
Douglas Beck

Description:
Rear overview

Claim Photo

Our File Number: 088-005720
Adjuster: Douglas Beck
Insured: Alouidor Transportation LLC / Jackson Alouidor
Date of Loss: 12/25/2025
Customer File Number: 235503315
Policy Number:



Photo: 17

Date Taken:
01/21/2026

Taken By:
Douglas Beck

Description:
Right side damage



Photo: 18

Date Taken:
01/21/2026

Taken By:
Douglas Beck

Description:
Right side damage

Claim Photo

Our File Number: 088-005720
Adjuster: Douglas Beck
Insured: Aloudior Transportation LLC / Jackson Aloudior
Date of Loss: 12/25/2025
Customer File Number: 235503315
Policy Number:



Photo: 19

Date Taken:
01/21/2026

Taken By:
Douglas Beck

Description:
Right front wheel
damage




Photo: 20

Date Taken:
01/21/2026

Taken By:
Douglas Beck

Description:
Right front end
damage

Claim Photo

Our File Number: 088-005720
Adjuster: Douglas Beck
Insured: Alouidor Transportation LLC / Jackson Alouidor
Date of Loss: 12/25/2025
Customer File Number: 235503315
Policy Number:




Photo: 21

Date Taken:
01/21/2026

Taken By:
Douglas Beck

Description:
Right front wheel



Photo: 22

Date Taken:
01/21/2026

Taken By:
Douglas Beck

Description:
Right front

Claim Photo

Our File Number: 088-005720
Adjuster: Douglas Beck
Insured: Alouidor Transportation LLC / Jackson Alouidor
Date of Loss: 12/25/2025
Customer File Number: 235503315
Policy Number:



Photo: 23

Date Taken:
01/21/2026

Taken By:
Douglas Beck

Description:
Right front damage




Photo: 24

Date Taken:
01/21/2026

Taken By:
Douglas Beck

Description:
Left side engine
overview

Claim Photo

Our File Number: 088-005720
Adjuster: Douglas Beck
Insured: Aloudior Transportation LLC / Jackson Aloudior
Date of Loss: 12/25/2025
Customer File Number: 235503315
Policy Number:




Photo: 25

Date Taken:
01/21/2026

Taken By:
Douglas Beck

Description:
Left side top view
of engine




Photo: 26

Date Taken:
01/21/2026

Taken By:
Douglas Beck

Description:
Left front wheel
damage

Claim Photo

Our File Number: 088-005720
Adjuster: Douglas Beck
Insured: Alouidor Transportation LLC / Jackson Alouidor
Date of Loss: 12/25/2025
Customer File Number: 235503315
Policy Number:



Photo: 27

Date Taken:
01/21/2026

Taken By:
Douglas Beck

Description:
Right side engine
overview




Photo: 28

Date Taken:
01/21/2026

Taken By:
Douglas Beck

Description:
Right side engine

Claim Photo

Our File Number: 088-005720
Adjuster: Douglas Beck
Insured: Alouidor Transportation LLC / Jackson Alouidor
Date of Loss: 12/25/2025
Customer File Number: 235503315
Policy Number:




Photo: 29

Date Taken:
01/21/2026

Taken By:
Douglas Beck

Description:
Right side top view
of engine




Photo: 30

Date Taken:
01/21/2026

Taken By:
Douglas Beck

Description:
Right front tire
295/15R22.5

Claim Photo

Our File Number: 088-005720
Adjuster: Douglas Beck
Insured: Alouidor Transportation LLC / Jackson Alouidor
Date of Loss: 12/25/2025
Customer File Number: 235503315
Policy Number:



Photo: 31

Date Taken:
01/21/2026

Taken By:
Douglas Beck

Description:
Right side damage




Photo: 32

Date Taken:
01/21/2026

Taken By:
Douglas Beck

Description:
Interior overview

Claim Photo

Our File Number: 088-005720
Adjuster: Douglas Beck
Insured: Alouidor Transportation LLC / Jackson Alouidor
Date of Loss: 12/25/2025
Customer File Number: 235503315
Policy Number:



Photo: 33

Date Taken:
01/21/2026

Taken By:
Douglas Beck

Description:
Interior overview



Photo: 34

Date Taken:
01/21/2026

Taken By:
Douglas Beck

Description:
Interior dashboard
overview

Claim Photo

Our File Number: 088-005720
Adjuster: Douglas Beck
Insured: Alouidor Transportation LLC / Jackson Alouidor
Date of Loss: 12/25/2025
Customer File Number: 235503315
Policy Number:



Photo: 35

Date Taken:
01/21/2026

Taken By:
Douglas Beck

Description:
Interior sleeper
overview




Photo: 36

Date Taken:
01/21/2026

Taken By:
Douglas Beck

Description:
Interior sleeper
overview

Claim Photo

Our File Number: 088-005720
Adjuster: Douglas Beck
Insured: Alouidor Transportation LLC / Jackson Alouidor
Date of Loss: 12/25/2025
Customer File Number: 235503315
Policy Number:



Photo: 37

Date Taken:
01/21/2026

Taken By:
Douglas Beck

Description:
Interior sleeper
overview




Photo: 38

Date Taken:
01/21/2026

Taken By:
Douglas Beck

Description:
Left front wheel

Claim Photo

Our File Number: 088-005720
Adjuster: Douglas Beck
Insured: Alouidor Transportation LLC / Jackson Alouidor
Date of Loss: 12/25/2025
Customer File Number: 235503315
Policy Number:



Photo: 39

Date Taken:
01/21/2026

Taken By:
Douglas Beck

Description:
Left front wheel
inside view



Photo: 40

Date Taken:
01/21/2026

Taken By:
Douglas Beck

Description:
Left rear dual tire

Claim Photo

Our File Number: 088-005720
Adjuster: Douglas Beck
Insured: Aloudior Transportation LLC / Jackson Aloudior
Date of Loss: 12/25/2025
Customer File Number: 235503315
Policy Number:



Photo: 41

Date Taken:
01/21/2026

Taken By:
Douglas Beck

Description:
Tire tread depth
LRFI 15/32



Photo: 42

Date Taken:
01/21/2026

Taken By:
Douglas Beck

Description:
Tire tread depth
LRRO 16/32

Claim Photo

Our File Number: 088-005720
Adjuster: Douglas Beck
Insured: Aloudior Transportation LLC / Jackson Aloudior
Date of Loss: 12/25/2025
Customer File Number: 235503315
Policy Number:



Photo: 43

Date Taken:
01/21/2026

Taken By:
Douglas Beck

Description:
Tire tread depth
LRRI 16/32



Photo: 44

Date Taken:
01/21/2026

Taken By:
Douglas Beck

Description:
Tire tread depth
RRFO 16/32

Claim Photo

Our File Number: 088-005720
Adjuster: Douglas Beck
Insured: Alouidor Transportation LLC / Jackson Alouidor
Date of Loss: 12/25/2025
Customer File Number: 235503315
Policy Number:



Photo: 45

Date Taken:
01/21/2026

Taken By:
Douglas Beck

Description:
Tire tread depth
RRFI 11/32



Photo: 46

Date Taken:
01/21/2026

Taken By:
Douglas Beck

Description:
Tire tread depth
RRRO 14/32

Claim Photo

Our File Number: 088-005720
Adjuster: Douglas Beck
Insured: Alouidor Transportation LLC / Jackson Alouidor
Date of Loss: 12/25/2025
Customer File Number: 235503315
Policy Number:



Photo: 47

Date Taken:
01/21/2026

Taken By:
Douglas Beck

Description:
Tire tread depth
RRRO 14/32



Photo: 48

Date Taken:
01/21/2026

Taken By:
Douglas Beck

Description:
Tire tread depth
RRRI 14/32

Claim Photo

Our File Number: 088-005720
Adjuster: Douglas Beck
Insured: Alouidor Transportation LLC / Jackson Alouidor
Date of Loss: 12/25/2025
Customer File Number: 235503315
Policy Number:



Photo: 49

Date Taken:
01/21/2026

Taken By:
Douglas Beck

Description:
Tire tread depth RF
8/32