

Claim Photo

Our File Number: 277-065451
Adjuster: Jeff Meurer
Insured: LG LOGISTICS INC
Date of Loss: 10/07/2025
Customer File Number: 041048-000129-AP-01
Policy Number:



Photo: 1
Date Taken: 12/10/2025
Taken By: James Miller
Description: VIN sticker on driver side door



Photo: 2
Date Taken: 12/10/2025
Taken By: James Miller
Description: VIN sticker on cab portion inside driver side door

Claim Photo

Our File Number: 277-065451
Adjuster: Jeff Meurer
Insured: LG LOGISTICS INC
Date of Loss: 10/07/2025
Customer File Number: 041048-000129-AP-01
Policy Number:



Photo: 3

Date Taken:
12/10/2025

Taken By:
James Miller

Description:
Maintenance
sticker on inside of
driver side
windshield



Photo: 4

Date Taken:
12/10/2025

Taken By:
James Miller

Description:
Driver side
dashboard

Claim Photo

Our File Number: 277-065451
Adjuster: Jeff Meurer
Insured: LG LOGISTICS INC
Date of Loss: 10/07/2025
Customer File Number: 041048-000129-AP-01
Policy Number:



Photo: 5

Date Taken:
12/10/2025

Taken By:
James Miller

Description:
Inside of cab from
driver side view




Photo: 6

Date Taken:
12/10/2025

Taken By:
James Miller

Description:
Sleeper area

Claim Photo

Our File Number: 277-065451
Adjuster: Jeff Meurer
Insured: LG LOGISTICS INC
Date of Loss: 10/07/2025
Customer File Number: 041048-000129-AP-01
Policy Number:



Photo: 7

Date Taken:
12/10/2025

Taken By:
James Miller

Description:
Sleeper area



Photo: 8

Date Taken:
12/10/2025

Taken By:
James Miller

Description:
View of sleeper
area and top of cab
interior from driver
side

Claim Photo

Our File Number: 277-065451
Adjuster: Jeff Meurer
Insured: LG LOGISTICS INC
Date of Loss: 10/07/2025
Customer File Number: 041048-000129-AP-01
Policy Number:



Photo: 9

Date Taken:
12/10/2025

Taken By:
James Miller

Description:
Cabin interior from
passenger side view




Photo: 10

Date Taken:
12/10/2025

Taken By:
James Miller

Description:
Interior of cab from
passenger side view

Claim Photo

Our File Number: 277-065451
Adjuster: Jeff Meurer
Insured: LG LOGISTICS INC
Date of Loss: 10/07/2025
Customer File Number: 041048-000129-AP-01
Policy Number:



Photo: 11

Date Taken:
12/10/2025

Taken By:
James Miller

Description:
Interior cab area
from passenger side
view



Photo: 12

Date Taken:
12/10/2025

Taken By:
James Miller

Description:
Front of truck
tractor

Claim Photo

Our File Number: 277-065451
Adjuster: Jeff Meurer
Insured: LG LOGISTICS INC
Date of Loss: 10/07/2025
Customer File Number: 041048-000129-AP-01
Policy Number:



Photo: 13

Date Taken:
12/10/2025

Taken By:
James Miller

Description:
Driver side of truck
tractor



Photo: 14

Date Taken:
12/10/2025

Taken By:
James Miller

Description:
Rear of truck
tractor

Claim Photo

Our File Number: 277-065451
Adjuster: Jeff Meurer
Insured: LG LOGISTICS INC
Date of Loss: 10/07/2025
Customer File Number: 041048-000129-AP-01
Policy Number:



Photo: 15

Date Taken:
12/10/2025

Taken By:
James Miller

Description:
Passenger side of
truck tractor



Photo: 16

Date Taken:
12/10/2025

Taken By:
James Miller

Description:
Passenger side of
truck tractor

Claim Photo

Our File Number: 277-065451
Adjuster: Jeff Meurer
Insured: LG LOGISTICS INC
Date of Loss: 10/07/2025
Customer File Number: 041048-000129-AP-01
Policy Number:



Photo: 17

Date Taken:
12/10/2025

Taken By:
James Miller

Description:
Front passenger
corner of truck
tractor



Photo: 18

Date Taken:
12/10/2025

Taken By:
James Miller

Description:
Front driver side
corner of truck
tractor

Claim Photo

Our File Number: 277-065451
Adjuster: Jeff Meurer
Insured: LG LOGISTICS INC
Date of Loss: 10/07/2025
Customer File Number: 041048-000129-AP-01
Policy Number:



Photo: 19

Date Taken:
12/10/2025

Taken By:
James Miller

Description:
Rear driver side
corner of truck
tractor



Photo: 20

Date Taken:
12/10/2025

Taken By:
James Miller

Description:
Rear passenger side
corner of truck
tractor

Claim Photo

Our File Number: 277-065451
Adjuster: Jeff Meurer
Insured: LG LOGISTICS INC
Date of Loss: 10/07/2025
Customer File Number: 041048-000129-AP-01
Policy Number:



Photo: 21

Date Taken:
12/10/2025

Taken By:
James Miller

Description:
Passenger side of
truck tractor
damaged area



Photo: 22

Date Taken:
12/10/2025

Taken By:
James Miller

Description:
Damaged passenger
side door

Claim Photo

Our File Number: 277-065451
Adjuster: Jeff Meurer
Insured: LG LOGISTICS INC
Date of Loss: 10/07/2025
Customer File Number: 041048-000129-AP-01
Policy Number:



Photo: 23

Date Taken:
12/10/2025

Taken By:
James Miller

Description:
Damaged passenger
side door and roof



Photo: 24

Date Taken:
12/10/2025

Taken By:
James Miller

Description:
Damaged passenger
side door

Claim Photo

Our File Number: 277-065451
Adjuster: Jeff Meurer
Insured: LG LOGISTICS INC
Date of Loss: 10/07/2025
Customer File Number: 041048-000129-AP-01
Policy Number:



Photo: 25

Date Taken:
12/10/2025

Taken By:
James Miller

Description:
Front driver side
tire and wheel




Photo: 26

Date Taken:
12/10/2025

Taken By:
James Miller

Description:
Axle 1 driver side
tread depth

Claim Photo

Our File Number: 277-065451
Adjuster: Jeff Meurer
Insured: LG LOGISTICS INC
Date of Loss: 10/07/2025
Customer File Number: 041048-000129-AP-01
Policy Number:



Photo: 27

Date Taken:
12/10/2025

Taken By:
James Miller

Description:
Axle 2 driver side
inside tire tread
depth



Photo: 28

Date Taken:
12/10/2025

Taken By:
James Miller

Description:
Axle 2 driver side
outside tire tread
depth

Claim Photo

Our File Number: 277-065451
Adjuster: Jeff Meurer
Insured: LG LOGISTICS INC
Date of Loss: 10/07/2025
Customer File Number: 041048-000129-AP-01
Policy Number:



Photo: 29

Date Taken:
12/10/2025

Taken By:
James Miller

Description:
Axle 3 driver side
inside tire tread
depth



Photo: 30

Date Taken:
12/10/2025

Taken By:
James Miller

Description:
Axle 3 driver side
outside tire tread
depth

Claim Photo

Our File Number: 277-065451
Adjuster: Jeff Meurer
Insured: LG LOGISTICS INC
Date of Loss: 10/07/2025
Customer File Number: 041048-000129-AP-01
Policy Number:



Photo: 31

Date Taken:
12/10/2025

Taken By:
James Miller

Description:
Axle 2 wheel and
hub driver side



Photo: 32

Date Taken:
12/10/2025

Taken By:
James Miller

Description:
Axle 3 driver side
wheel and hub

Claim Photo

Our File Number: 277-065451
Adjuster: Jeff Meurer
Insured: LG LOGISTICS INC
Date of Loss: 10/07/2025
Customer File Number: 041048-000129-AP-01
Policy Number:



Photo: 33

Date Taken:
12/10/2025

Taken By:
James Miller

Description:
Axle 2 driver side
between wheels



Photo: 34

Date Taken:
12/10/2025

Taken By:
James Miller

Description:
Axle 2 driver side
brake

Claim Photo

Our File Number: 277-065451
Adjuster: Jeff Meurer
Insured: LG LOGISTICS INC
Date of Loss: 10/07/2025
Customer File Number: 041048-000129-AP-01
Policy Number:



Photo: 35

Date Taken:
12/10/2025

Taken By:
James Miller

Description:
Axle 3 driver side
between wheels



Photo: 36

Date Taken:
12/10/2025

Taken By:
James Miller

Description:
Axle 3 driver side
brake

Claim Photo

Our File Number: 277-065451
Adjuster: Jeff Meurer
Insured: LG LOGISTICS INC
Date of Loss: 10/07/2025
Customer File Number: 041048-000129-AP-01
Policy Number:



Photo: 37

Date Taken:
12/10/2025

Taken By:
James Miller

Description:
Axle 1 driver side
brake



Photo: 38

Date Taken:
12/10/2025

Taken By:
James Miller

Description:
Axle 1 passenger
side wheel and hub

Claim Photo

Our File Number: 277-065451
Adjuster: Jeff Meurer
Insured: LG LOGISTICS INC
Date of Loss: 10/07/2025
Customer File Number: 041048-000129-AP-01
Policy Number:




Photo: 39

Date Taken:
12/10/2025

Taken By:
James Miller

Description:
Axle 1 passenger
side tread depth



Photo: 40

Date Taken:
12/10/2025

Taken By:
James Miller

Description:
Axle 1 passenger
side brake

Claim Photo

Our File Number: 277-065451
Adjuster: Jeff Meurer
Insured: LG LOGISTICS INC
Date of Loss: 10/07/2025
Customer File Number: 041048-000129-AP-01
Policy Number:



Photo: 41

Date Taken:
12/10/2025

Taken By:
James Miller

Description:
Axle 2 passenger
side inside tire
tread depth



Photo: 42

Date Taken:
12/10/2025

Taken By:
James Miller

Description:
Axle 2 passenger
side outside tire
tread depth

Claim Photo

Our File Number: 277-065451
Adjuster: Jeff Meurer
Insured: LG LOGISTICS INC
Date of Loss: 10/07/2025
Customer File Number: 041048-000129-AP-01
Policy Number:



Photo: 43

Date Taken:
12/10/2025

Taken By:
James Miller

Description:
Axle 2 passenger
side between
wheels



Photo: 44

Date Taken:
12/10/2025

Taken By:
James Miller

Description:
Axle 2 passenger
side wheel and hub

Claim Photo

Our File Number: 277-065451
Adjuster: Jeff Meurer
Insured: LG LOGISTICS INC
Date of Loss: 10/07/2025
Customer File Number: 041048-000129-AP-01
Policy Number:



Photo: 45

Date Taken:
12/10/2025

Taken By:
James Miller

Description:
Axle 2 passenger
side brake



Photo: 46

Date Taken:
12/10/2025

Taken By:
James Miller

Description:
Axle 3 passenger
side inside tire
tread depth

Claim Photo

Our File Number: 277-065451
Adjuster: Jeff Meurer
Insured: LG LOGISTICS INC
Date of Loss: 10/07/2025
Customer File Number: 041048-000129-AP-01
Policy Number:



Photo: 47

Date Taken:
12/10/2025

Taken By:
James Miller

Description:
Axle 3 passenger
side outside tire
tread depth



Photo: 48

Date Taken:
12/10/2025

Taken By:
James Miller

Description:
Axle 3 passenger
side wheel and hub

Claim Photo

Our File Number: 277-065451
Adjuster: Jeff Meurer
Insured: LG LOGISTICS INC
Date of Loss: 10/07/2025
Customer File Number: 041048-000129-AP-01
Policy Number:



Photo: 49

Date Taken:
12/10/2025

Taken By:
James Miller

Description:
Axle 3 passenger
side brake