

Claim Photo

Our File Number: 277-065443
Adjuster: Devon Karnitz
Insured: Hywind Transport LLC
Date of Loss: 12/03/2025
Customer File Number: 000786-091555-AP-01
Policy Number:




Photo: 1

Date Taken:
12/19/2025

Taken By:
Raymond Selke

Description:
VIN#
3HSDZAPR8JN75
5124



Photo: 2

Date Taken:
12/19/2025

Taken By:
Raymond Selke

Description:
NO POWER TO
ODOMETER

Claim Photo

Our File Number: 277-065443
Adjuster: Devon Karnitz
Insured: Hywind Transport LLC
Date of Loss: 12/03/2025
Customer File Number: 000786-091555-AP-01
Policy Number:



Photo: 3

Date Taken:
12/19/2025

Taken By:
Raymond Selke

Description:
INTERIOR



Photo: 4

Date Taken:
12/19/2025

Taken By:
Raymond Selke

Description:
IN 3882221

Claim Photo

Our File Number: 277-065443
Adjuster: Devon Karnitz
Insured: Hywind Transport LLC
Date of Loss: 12/03/2025
Customer File Number: 000786-091555-AP-01
Policy Number:



Photo: 5

Date Taken:
12/19/2025

Taken By:
Raymond Selke

Description:
FRONT LEFT



Photo: 6

Date Taken:
12/19/2025

Taken By:
Raymond Selke

Description:
FRONT RIGHT

Claim Photo

Our File Number: 277-065443
Adjuster: Devon Karnitz
Insured: Hywind Transport LLC
Date of Loss: 12/03/2025
Customer File Number: 000786-091555-AP-01
Policy Number:



Photo: 7

Date Taken:
12/19/2025

Taken By:
Raymond Selke

Description:
REAR RIGHT



Photo: 8

Date Taken:
12/19/2025

Taken By:
Raymond Selke

Description:
REAR LEFT

Claim Photo

Our File Number: 277-065443
Adjuster: Devon Karnitz
Insured: Hywind Transport LLC
Date of Loss: 12/03/2025
Customer File Number: 000786-091555-AP-01
Policy Number:



Photo: 9

Date Taken:
12/19/2025

Taken By:
Raymond Selke

Description:
**FRAME
DAMAGE**



Photo: 10

Date Taken:
12/19/2025

Taken By:
Raymond Selke

Description:
WHEEL AND
TIRE,
SUSPENSION

Claim Photo

Our File Number: 277-065443
Adjuster: Devon Karnitz
Insured: Hywind Transport LLC
Date of Loss: 12/03/2025
Customer File Number: 000786-091555-AP-01
Policy Number:




Photo: 11

Date Taken:
12/19/2025

Taken By:
Raymond Selke

Description:
STATIONARY
GLASS, HOOD
AND BUMPER



Photo: 12

Date Taken:
12/19/2025

Taken By:
Raymond Selke

Description:
MIRRORS

Claim Photo

Our File Number: 277-065443
Adjuster: Devon Karnitz
Insured: Hywind Transport LLC
Date of Loss: 12/03/2025
Customer File Number: 000786-091555-AP-01
Policy Number:



Photo: 13

Date Taken:
12/19/2025

Taken By:
Raymond Selke

Description:
CAB DAMAGE



Photo: 14

Date Taken:
12/19/2025

Taken By:
Raymond Selke

Description:
CAB DAMAGE

Claim Photo

Our File Number: 277-065443
Adjuster: Devon Karnitz
Insured: Hywind Transport LLC
Date of Loss: 12/03/2025
Customer File Number: 000786-091555-AP-01
Policy Number:



Photo: 15

Date Taken:
12/19/2025

Taken By:
Raymond Selke

Description:
BATTERY BOX



Photo: 16

Date Taken:
12/19/2025

Taken By:
Raymond Selke

Description:
CAB DAMAGE

Claim Photo

Our File Number: 277-065443
Adjuster: Devon Karnitz
Insured: Hywind Transport LLC
Date of Loss: 12/03/2025
Customer File Number: 000786-091555-AP-01
Policy Number:



Photo: 17

Date Taken:
12/19/2025

Taken By:
Raymond Selke

Description:
CAB DAMAGE
AND DOT
MARKING



Photo: 18

Date Taken:
12/19/2025

Taken By:
Raymond Selke

Description:
CAB DAMAGE

Claim Photo

Our File Number: 277-065443
Adjuster: Devon Karnitz
Insured: Hywind Transport LLC
Date of Loss: 12/03/2025
Customer File Number: 000786-091555-AP-01
Policy Number:



Photo: 19

Date Taken:
12/19/2025

Taken By:
Raymond Selke

Description:
BUMPER HOOD
MIRRORS



Photo: 20

Date Taken:
12/19/2025

Taken By:
Raymond Selke

Description:
LEFT STEERING
- 15/32"