

**PHOTOS ONLY — APPRAISAL REPORT**

Date:	<b>12/29/2025</b>	Client:	<b>Roanoke Valley Claims Service(RVCS)</b>
File #:	<b>267976</b>	Claim #:	<b>2025-58649</b>
Adjuster:	<b>Brian Wills</b>	Policy #:	<b>KPB-2024-441</b>
Appraiser:	<b>Jacob Todd</b>	Date of Loss:	<b>12/09/2025</b>
Insured:	<b>Paragon Freight Inc.</b>	Claimant:	<b>Paragon Freight Inc.</b>
NADA:	<b>\$25,500.00</b>		

**Acknowledgement**

The above referenced loss was received on 12/23/2025 at which time we were asked to inspect a vehicle described as: Year **2023** Make **Vanguard** Model **trailer** VIN **5V8VC5324PM301409**.

**Damage Description**

The assignment indicated damage to: roof & structure, from overturn loss.

**Unit Inspection**

We inspected this loss at 19842 Highway 58 N, Crescent Lake, Oregon, 97733 on 12/29/2025 with nobody present. We found damage to the: Lt Side. **The vehicle does Not appear to be drivable because: Roof torn away / structure damages.** The damage that was observed did match the assignment instructions. No old damage was noted. Measurements were not taken. Mileage was unable to be confirmed because there was no power to vehicle.

**Unit Identification**

This unit was confirmed to be a 2023 Vanguard trailer with a confirmed VIN reading 5V8VC5324PM301409. The VIN was verified by box side tag, and was photographed. The Registration was not available because unable to locate.

**Additional Comments**

Per assignment, we have provided a 'photos-only' inspection of the loss unit.

Unit matches in identification with the make / model / year as presented. Please find our full Photo Inspection, attached. Damages appear consistent with the report of overturn. Thank you for the assignment

## Claim Information

Customer Claim Number	Reference Number	Loss Date	Type of Loss	Prior Damage/Other Ded.
2025-58649		12/09/2025	Comprehensive	\$5,000

## Claim Rep

Company	Roanoke Valley Claims Service(RVCS)	Claim Rep Name	Brian Wills
---------	-------------------------------------	----------------	-------------

## Owner /Insured

Owner Name	Insured Name	Owner Phone	Owner Email
Paragon Freight Inc.		630.506.6782	duke@paragonfreight.net
Owner Address	16W285 83RD ST SUITE C		
Owner City	Owner State	Owner Zip	Sales Tax Rate %
BURR RIDGE	Illinois	60527	

## Vehicle / Asset

VIN	Year	Make	Model	Overall Condition	Series	Body Type	Axle Config	GVWR
5V8VC5324PM301409	2023	Vanguard	trailer	Average	VXP	53' Composite Dry Van	2	68000

## Trailer Type

Type	Dry Freight Closed No Tilt 5th Wheel							
Length	Width	Side Wall Height	Capacity	# of Compartments	Contents Hauled			
53	102"	110" Inside / 13.5' Outside		Single	Dry Freight			
Reefer Unit Year	Reefer Unit Make		Reefer Unit Model	Reefer Hours		Suspension		
						Air Ride		

## Tires/Axles

I/S Wheel Type	Qty	O/S WHeel Type	Qty	Super Single	Rear Tire Size	Qty	Rear Tire Tread Remaining	Tag Axle Rating	# of Axles
Steel	4	Steel	4	No	22.5	8	70%		Sliding Tandem
Tag Axle Wheel Type	Qty	Super Single	Tag Axle Tire Size			Tire Tread Remaining		Tag Axle Rating	
								Tag Axle Configuration	

## Truck/Trailer Body Options

Composition	Deck	Lining	Trailer Body Features
Composite Panels	Wood	Composite	Spare Tire and Rear Door Swing and Barn Doors
Paint Condition	Repainted	Date	Cost
Average			

## Exterior / Interior Features

Accessories	Interior Condition	Tarp System	Tool Boxes	Qty / Size	Date	Cost
Side Skirts and Inflation System, Logistics Posts	Average					

Comments/Additional Info

HEA Appraisal

PO Box 5058  
Oceanside, CA 92052  
951-261-8195  
accounting@hea-appraisal.com

## Vehicle Information

Vehicle: 2023 Trailers Dry Van Composite Van 53'x102"  
Period: December 30, 2025  
Mileage: 0  
Base MSRP: \$47,200  
GVW: 0  
GCW: 0

J.D. POWER  
No Image Available

## J.D. POWER Commercial Trucks Values

	Base	Mileage Adj.	Option Adj.	Adjusted Value
Wholesale	\$19,175	N/A	N/A	<b>\$19,175</b>
Loan	\$17,275	N/A	N/A	<b>\$17,275</b>
Retail	\$25,500	N/A	N/A	<b>\$25,500</b>

## VIN Decoder



Version: 3.63 last updated on 8/16/2025

[Release Notes](#)

[Subscribe/Unsubscribe](#)

NHTSA's VIN decoder allows you to query a particular vehicle's VIN to identify specific information encoded in the number.

**VIN**

5V8VC5324PM301409

**Model Year**

Vehicle's Model Year

Please refer to page 16 of the New Manufacturer's Handbook for specific instructions and/or CFR 49 Part 565 for questions regarding the calculation of the VIN Check Digit at position 9.

2023 VANGUARD NATIONAL TRAILER CORPORATION (VNTC) - TRAILER

**Error Text:** 0 - VIN decoded clean. Check Digit (9th position) is correct

The Model Year decoded for this VIN may be incorrect. If you know the Model year, please enter it and decode again to get more accurate information.

**Manufacturer:** VANGUARD NATIONAL TRAILER CORPORATION

**DBAs:**


**Vehicle Type:** TRAILER

**Model Year:** 2023

**Make:** VANGUARD NATIONAL TRAILER CORPORATION (VNTC)

**Model:** VANGUARD NATIONAL TRAILER CORPORATION (VNTC)

**Body Class:** Trailer



## Other Information

Information provided below is based on the details provided by the manufacturer of this vehicle to NHTSA in the part 565 submittal

**Gross Vehicle Weight Rating:**

**Trailer Body Type:** Box or Van Enclosed Trailer

**Trailer Type Connection:** Kingpin

**Trailer Length:** 53

**Primary Fuel Type:** Not Applicable

**Secondary Fuel Type:** Not Applicable

**Electrification Level:** Not Applicable

**Axles:**

**Axle Configuration:** Tandem

**Other Trailer Information:** Composite Plate Semitrailer (VXP), Dry Freight Trailer

**Plant Information:** MONON, INDIANA, UNITED STATES (USA)



12/29/25 1:49 PM

LICENSE PLATE

This trailer IS NOT to be loaded or  
permitted to exceed the GVWR or  
GAWR on the VIN plate.

MANUFACTURED BY / FABRIQUÉ PAR:	VANGUARD NATIONAL TRAILER CORP.		
DATE:	09/2022		
GAWR / PNEU	9091 KG (20000 LB)	TIRE / PNEU	295/75R22.5 (G)
		RIM / JANTE	8.25 X 22.5
FR/AV			COLD INFL. PRESS. / PRESS. DE GONFL. À FROID
1ST INT/INT			KPA (PSI / LPC)
2ND INT/INT			758 KPA (110 PSI) DUAL
RR/AR	9091 KG (20000 LB)	295/75R22.5 (G)	8.25 X 22.5
			758 KPA (110 PSI) DUAL
THIS VEHICLE CONFORMS TO ALL APPLICABLE STANDARDS PRESCRIBED UNDER THE CANADIAN MOTOR VEHICLE SAFETY REGULATIONS IN EFFECT ON THE DATE OF MANUFACTURE. / CE VÉHICULE EST CONFORME À TOUTES LES NORMES QUI LUI SONT APPLICABLES EN VERTU DU RÈGLEMENT SUR LA SÉCURITÉ DES VÉHICULES AUTOMOBILES DU CANADA EN VIGUEUR À LA DATE DE SA FABRICATION.			
THIS VEHICLE CONFORMS TO ALL APPLICABLE U.S. FEDERAL MOTOR VEHICLE SAFETY STANDARDS IN EFFECT ON THE DATE OF MANUFACTURE SHOWN ABOVE.			
V.I.N. / N.I.V.	5V8VC5324PM301409	TYPE:	TRAILER / REM VXP 53'

ONE OR MORE OF THE FOLLOWING LISTED PATENTS  
& OTHER FOREIGN & U.S. PATENTS MAY APPLY:  
AU MOINS UN DES BREVETS CI-DESSOUS PAUT S'APPUOUPER:  
UNO O MÁS DE LOS SIGUIENTES PATENTES LISTADOS Y OTROS  
PATENTES EXTRANJEROS Y PATENTES DE ESTADOS UNIDOS  
PUEDEN APLICAR:

4,685,721

7,568,856

12/29/25 1:50 PM

VIN



12/29/25 1:48 PM

LT FR



12/29/25 1:48 PM

FRONT



RT FR



RT RR



REAR



LT RR



12/29/25 1:49 PM

LT SIDE



12/29/25 1:50 PM

LT SIDE DAMAGE



12/29/25 1:50 PM

LT SIDE DAMAGE



12/29/25 1:50 PM

LT SIDE DAMAGE



12/29/25 1:51 PM  
Crescent Lake Junction

RT SIDE DAMAGE



12/29/25 1:51 PM  
Crescent Lake Junction

RT SIDE DAMAGE



12/29/25 1:51 PM  
Crescent Lake Junction

RT SIDE DAMAGE



12/29/25 1:51 PM  
Crescent Lake Junction

RT SIDE DAMAGE



RT SIDE DAMAGE



RT SIDE DAMAGE



12/29/25 1:51 PM  
Crescent Lake Junction

RT SIDE DAMAGE



12/29/25 1:51 PM  
Crescent Lake Junction

RT SIDE DAMAGE



12/29/25 1:51 PM  
Crescent Lake Junction

RT SIDE DAMAGE



12/29/25 1:51 PM  
Crescent Lake Junction


RT SIDE DAMAGE



ROOF DAMAGE



RT SIDE DAMAGE



12/29/25 1:52 PM

RT SIDE DAMAGE



12/29/25 1:52 PM

RR DOORS DAMAGE



RR DOORS DAMAGE



RR DOORS DAMAGE



12/29/25 1:52 PM

RR DOORS DAMAGE



12/29/25 1:52 PM

INTERIOR



INTERIOR



INTERIOR



12/29/25 1:53 PM

RR CORNER DAMAGE