




Team One No: 341570D/021126 (H1-HE)
Policy Number: ABP3271638-23
Adjuster: Michael Baker
Carrier: Continental Western Group
CWG
Assignment: 02/11/2026

Claim Number: 40 PC 497941
Date of Loss: 01/12/2026
Examiner: Mike Benton




Faas Feed & Grain, Inc.
105 Hallett St
Keswick, IA 50136

GPS Coordinates:
41.4540186, -92.2400964

User Location:
UNKNOWN

User Distance:
UNKNOWN



Faas Feed & Grain, Inc.
105 Hallett St
Keswick, IA 50136

GPS Coordinates:
41.4540186, -92.2400964

User Location:
UNKNOWN

User Distance:
UNKNOWN



Team One No: 341570D/021126 (H1-HE)
Policy Number: ABP3271638-23
Adjuster: Michael Baker
Carrier: Continental Western Group
CWG
Assignment: 02/11/2026

Claim Number: 40 PC 497941
Date of Loss: 01/12/2026
Examiner: Mike Benton



Photo 1

Serial number tag.jpeg

Date Taken:

2/13/2026 12:59:51 AM



Photo 2

Machine hours.jpeg

Date Taken:

2/13/2026 12:59:50 AM



Photo 3

Cab interior.jpeg

Date Taken:

2/13/2026 12:59:33 AM




Photo 4

Front.jpeg

Date Taken:

2/13/2026 12:59:33 AM



Team One No: 341570D/021126 (H1-HE)
Policy Number: ABP3271638-23
Adjuster: Michael Baker
Carrier: Continental Western Group
CWG
Assignment: 02/11/2026

Claim Number: 40 PC 497941
Date of Loss: 01/12/2026
Examiner: Mike Benton




Photo 5
Left side.jpeg

Date Taken:
2/13/2026 12:59:50 AM



Photo 6
Rear.jpeg

Date Taken:
2/13/2026 12:59:51 AM



Photo 7

Right side.jpeg

Date Taken:
2/13/2026 12:59:51 AM



Photo 8

Damage - draining fluids.jpeg

Date Taken:
2/13/2026 12:59:33 AM



Photo 9

Damage - other material in oil.jpeg

Date Taken:

2/13/2026 12:59:33 AM



Photo 10

Damage - white chunks.jpeg

Date Taken:

2/13/2026 12:59:33 AM