

## PHOTOGRAPHS



Insured trailer



Insured trailer. Note twisted frame.



## PHOTOGRAPHS



ID Tag



Damaged step supports



## PHOTOGRAPHS



Trailer tag. Arrow indicates missing leaf spring support that failed.  
Note the two supports on left side.



Damaged steps

## PHOTOGRAPHS



Insured trailer



Cracked frame



## PHOTOGRAPHS



Cracked frame



Twisted frame

## PHOTOGRAPHS



Insured trailer



Insured trailer

