

## Claim Photo

**Our File Number:** 297-017643  
**Adjuster:** Scott Syner  
**Insured:** Daher Contracting  
**Date of Loss:** 11/25/2025  
**Customer File Number:** 25AQ1-03610  
**Policy Number:**



### Photo: 1

**Date Taken:**  
12/12/2025

**Taken By:**  
Brianna Messer

**Description:**  
Front view of the  
insured tractor



### Photo: 2

**Date Taken:**  
12/12/2025

**Taken By:**  
Brianna Messer

**Description:**  
Front left side view

## Claim Photo

**Our File Number:** 297-017643  
**Adjuster:** Scott Syner  
**Insured:** Daher Contracting  
**Date of Loss:** 11/25/2025  
**Customer File Number:** 25AQ1-03610  
**Policy Number:**



**Photo: 3**

**Date Taken:**  
12/12/2025

**Taken By:**  
Brianna Messer

**Description:**  
Front right side  
damaged side



**Photo: 4**

**Date Taken:**  
12/12/2025

**Taken By:**  
Brianna Messer

**Description:**  
Damages to the  
door, mirror,  
windshield and  
stairs



## Claim Photo

**Our File Number:** 297-017643  
**Adjuster:** Scott Syner  
**Insured:** Daher Contracting  
**Date of Loss:** 11/25/2025  
**Customer File Number:** 25AQ1-03610  
**Policy Number:**



**Photo: 5**

**Date Taken:**  
12/12/2025

**Taken By:**  
Brianna Messer

**Description:**  
View of the  
damaged area



**Photo: 6**

**Date Taken:**  
12/12/2025

**Taken By:**  
Brianna Messer

**Description:**  
View of damages

## Claim Photo

**Our File Number:** 297-017643  
**Adjuster:** Scott Syner  
**Insured:** Daher Contracting  
**Date of Loss:** 11/25/2025  
**Customer File Number:** 25AQ1-03610  
**Policy Number:**



**Photo: 7**

**Date Taken:**  
12/12/2025

**Taken By:**  
Brianna Messer

**Description:**  
Rear view of the tractor



**Photo: 8**

**Date Taken:**  
12/12/2025

**Taken By:**  
Brianna Messer

**Description:**  
Rear right side view of tractor



## Claim Photo

**Our File Number:** 297-017643  
**Adjuster:** Scott Syner  
**Insured:** Daher Contracting  
**Date of Loss:** 11/25/2025  
**Customer File Number:** 25AQ1-03610  
**Policy Number:**




**Photo: 9**

**Date Taken:**  
12/12/2025

**Taken By:**  
Brianna Messer

**Description:**  
Rear left side view



**Photo: 10**


**Date Taken:**  
12/12/2025

**Taken By:**  
Brianna Messer

**Description:**  
Tire tread rear tires

## Claim Photo

**Our File Number:** 297-017643  
**Adjuster:** Scott Syner  
**Insured:** Daher Contracting  
**Date of Loss:** 11/25/2025  
**Customer File Number:** 25AQ1-03610  
**Policy Number:**



**Photo: 11**

**Date Taken:**  
12/12/2025

**Taken By:**  
Brianna Messer

**Description:**  
Tire tread for front  
rear tires



**Photo: 12**

**Date Taken:**  
12/12/2025

**Taken By:**  
Brianna Messer

**Description:**  
View of damages



## Claim Photo

**Our File Number:** 297-017643  
**Adjuster:** Scott Syner  
**Insured:** Daher Contracting  
**Date of Loss:** 11/25/2025  
**Customer File Number:** 25AQ1-03610  
**Policy Number:**



**Photo: 13**

**Date Taken:**  
12/12/2025

**Taken By:**  
Brianna Messer

**Description:**  
View of damages  
on the drivers side



**Photo: 14**

**Date Taken:**  
12/12/2025

**Taken By:**  
Brianna Messer

**Description:**  
Stairs damaged

## Claim Photo

**Our File Number:** 297-017643  
**Adjuster:** Scott Syner  
**Insured:** Daher Contracting  
**Date of Loss:** 11/25/2025  
**Customer File Number:** 25AQ1-03610  
**Policy Number:**



**Photo: 15**

**Date Taken:**  
12/12/2025

**Taken By:**  
Brianna Messer

**Description:**  
View of the  
damages area  
drivers side door  
will not open



**Photo: 16**

**Date Taken:**  
12/12/2025

**Taken By:**  
Brianna Messer

**Description:**  
View of damages



## Claim Photo

**Our File Number:** 297-017643  
**Adjuster:** Scott Syner  
**Insured:** Daher Contracting  
**Date of Loss:** 11/25/2025  
**Customer File Number:** 25AQ1-03610  
**Policy Number:**



**Photo: 17**

**Date Taken:**  
12/12/2025

**Taken By:**  
Brianna Messer

**Description:**  
Front tire tread



**Photo: 18**

**Date Taken:**  
12/12/2025

**Taken By:**  
Brianna Messer

**Description:**  
Damages to the  
hood



## Claim Photo

**Our File Number:** 297-017643  
**Adjuster:** Scott Syner  
**Insured:** Daher Contracting  
**Date of Loss:** 11/25/2025  
**Customer File Number:** 25AQ1-03610  
**Policy Number:**



**Photo: 19**

**Date Taken:**  
12/12/2025

**Taken By:**  
Brianna Messer

**Description:**  
Damaged side view



**Photo: 20**

**Date Taken:**  
12/12/2025

**Taken By:**  
Brianna Messer

**Description:**  
View of the  
damaged mirror  
and windshield



## Claim Photo

**Our File Number:** 297-017643  
**Adjuster:** Scott Syner  
**Insured:** Daher Contracting  
**Date of Loss:** 11/25/2025  
**Customer File Number:** 25AQ1-03610  
**Policy Number:**



**Photo: 21**

**Date Taken:**  
12/12/2025

**Taken By:**  
Brianna Messer

**Description:**  
Closer view of  
some of the  
damages



**Photo: 22**

**Date Taken:**  
12/12/2025

**Taken By:**  
Brianna Messer

**Description:**  
View of the  
passenger side



## Claim Photo

**Our File Number:** 297-017643  
**Adjuster:** Scott Syner  
**Insured:** Daher Contracting  
**Date of Loss:** 11/25/2025  
**Customer File Number:** 25AQ1-03610  
**Policy Number:**



**Photo: 23**

**Date Taken:**  
12/12/2025

**Taken By:**  
Brianna Messer

**Description:**  
Side view, the  
damaged side.



**Photo: 24**

**Date Taken:**  
12/12/2025

**Taken By:**  
Brianna Messer

**Description:**  
View of the  
damaged area



## Claim Photo

**Our File Number:** 297-017643  
**Adjuster:** Scott Syner  
**Insured:** Daher Contracting  
**Date of Loss:** 11/25/2025  
**Customer File Number:** 25AQ1-03610  
**Policy Number:**



**Photo: 25**

**Date Taken:**  
12/12/2025

**Taken By:**  
Brianna Messer

**Description:**  
Side view of  
damaged area



**Photo: 26**

**Date Taken:**  
12/12/2025

**Taken By:**  
Brianna Messer

**Description:**  
View of the  
damages -  
windshield

## Claim Photo

**Our File Number:** 297-017643  
**Adjuster:** Scott Syner  
**Insured:** Daher Contracting  
**Date of Loss:** 11/25/2025  
**Customer File Number:** 25AQ1-03610  
**Policy Number:**



**Photo: 27**

**Date Taken:**  
12/12/2025

**Taken By:**  
Brianna Messer

**Description:**  
Damaged on the  
front drivers side



**Photo: 28**

**Date Taken:**  
12/12/2025

**Taken By:**  
Brianna Messer

**Description:**  
View of the  
damaged area on  
the tractors drivers  
side



Claim Photo

Our File Number: 297-017643  
Adjuster: Scott Syner  
Insured: Daher Contracting  
Date of Loss: 11/25/2025  
Customer File Number: 25AQ1-03610  
Policy Number:



INSTRUCTIONS FOR ATTACHING DECAL

1. Clean area where new annual decal is to be affixed.
2. Peel decal from this document.
3. Affix decal in the upper right corner of license plate.

12-25

Mail To:  
DAHER CONTRACTING INC  
105 BEACH DR STE B2  
FT WALTON BEACH, FL 32547

IMPORTANT INFORMATION

Section 316.613, Florida Statutes, requires every operator of a motor vehicle transporting a child in a passenger car, van, motorcycle or pickup truck registered in this state and operated on the highways of this state, shall, if the child is 5 years of age or younger, provide the protection of the child by properly using a crash-tested, federally approved child restraint device. For children aged through 3 years, such restraint device must be a separate carrier or a vehicle manufacturer's integrated child seat. For children aged 4 through 5 years, a separate carrier, an integrated child seat, or a child booster seat may be used. For limited exceptions, see s. 316.613, F.S.

S. 320.0605, F.S., requires the registration certificate, or true copy of a rental or lease agreement, issued for any motor vehicle to be in the possession of the operator or carried in the vehicle while the vehicle is being used or operated on roads of this state.

S. 320.02 and 627.733, F.S., requires personal injury protection and property damage liability to be continuously maintained throughout the registration period. Failure to maintain the mandatory coverage may result in the suspension of your driver's license and registration.

Important note: If you cancel the insurance for this vehicle, immediately return the license plate from this registration to a Florida driver license or tax collector office or mail it to: DHSMV, Return Tags, 2900 Apalachee Parkway, Tallahassee, FL 32399. Surrendering the plate will prevent your driving privilege from being suspended.

CO/AGY 43 / 2 TR 2061993985  
BF 1824408

FLORIDA TRUCK/TRACTOR REGISTRATION

PLATE	06CHIE	DECAL	20248995	Expires	Midnight Wed 12/31/2025
YR/MK	2011/PRHT	BODY	TR	COLOR	LBL
VIN	1FLJLPDR5BDA9142	NET WT	17800	TITLE	121782493
Plate Type	RGR			Q/VW	80000
DL#UID	010895100-01				
Date Issued	12/26/2024	Plate Issued	12/26/2023		

DAHER CONTRACTING INC  
105 BEACH DR STE B2  
FT WALTON BEACH, FL 32547

*Blue  
Freightliner  
Tractor  
#19*

RGR - FLORIDA REGULAR

IMPORTANT INFORMATION

1. The Florida license plate must remain with the registrant upon sale of vehicle.
2. The registration must be delivered to a Tax Collector or Tag Agent for transfer to a replacement vehicle.
3. Your registration must be updated to your new address within 30 days of moving.
4. Registration renewals are the responsibility of the registrant and shall occur during the 30-day period prior to the expiration date shown on this registration. Renewal notices are provided as a courtesy and are not required for renewal purposes.
5. I understand that my driver license and registrations will be suspended immediately if the insurer denies the insurance information submitted for this registration.

Photo: 29

Date Taken:  
12/12/2025

Taken By:  
Brianna Messer

Description:  
Vin #  
1FUJGPDR5BDA  
X9142