

Claim Photo

Our File Number:

Adjuster:

Insured:

Date of Loss:

Customer File Number:

Policy Number:



Photo: 1

Date Taken:
12/29/2025

Taken By:
Anthony Hunter

Description:
Vehicle: 2025
Bitdeer Scissor Lift
SN: 17304504
right front



Photo: 2

Date Taken:
12/29/2025

Taken By:
Anthony Hunter

Description:
Vehicle: 2025
Bitdeer Scissor Lift
SN: 17304504 front

Claim Photo

Our File Number:

Adjuster:

Insured:

Date of Loss:

Customer File Number:

Policy Number:



Photo: 3

Date Taken:
12/29/2025

Taken By:
Anthony Hunter

Description:
Vehicle: 2025
Bitdeer Scissor Lift
SN: 17304504 left
front



Photo: 4

Date Taken:
12/29/2025

Taken By:
Anthony Hunter

Description:
Vehicle: 2025
Bitdeer Scissor Lift
SN: 17304504 left
rear

Claim Photo

Our File Number:

Adjuster:

Insured:

Date of Loss:

Customer File Number:

Policy Number:



Photo: 5

Date Taken:
12/29/2025

Taken By:
Anthony Hunter

Description:
Vehicle: 2025
Bitdeer Scissor Lift
SN: 17304504 rear



Photo: 6

Date Taken:
12/29/2025

Taken By:
Anthony Hunter

Description:
Vehicle: 2025
Bitdeer Scissor Lift
SN: 17304504 right
rear

Claim Photo

Our File Number:

Adjuster:

Insured:

Date of Loss:

Customer File Number:

Policy Number:



Photo: 7

Date Taken:
12/29/2025

Taken By:
Anthony Hunter

Description:
Vehicle: 2025
Bitdeer Scissor Lift
SN: 17304504 ID



Photo: 8

Date Taken:
12/29/2025

Taken By:
Anthony Hunter

Description:
Vehicle: 2025
Bitdeer Scissor Lift
SN: 17304504

Claim Photo

Our File Number:

Adjuster:

Insured:

Date of Loss:

Customer File Number:

Policy Number:



Photo: 9

Date Taken:
12/29/2025

Taken By:
Anthony Hunter

Description:
Vehicle: 2025
Bitdeer Scissor Lift
SN: 17304504 hour
meter burned



Photo: 10

Date Taken:
12/29/2025

Taken By:
Anthony Hunter

Description:
Vehicle: 2025
Bitdeer Scissor Lift
SN: 17304504

Claim Photo

Our File Number:

Adjuster:

Insured:

Date of Loss:

Customer File Number:

Policy Number:



Photo: 11

Date Taken:
12/29/2025

Taken By:
Anthony Hunter

Description:
Vehicle: 2025
Bitdeer Scissor Lift
SN: 17304504
batteries



Photo: 12

Date Taken:
12/29/2025

Taken By:
Anthony Hunter

Description:
Vehicle: 2025
Bitdeer Scissor Lift
SN: 17304504
batteries

Claim Photo

Our File Number:

Adjuster:

Insured:

Date of Loss:

Customer File Number:

Policy Number:



Photo: 13

Date Taken:
12/29/2025

Taken By:
Anthony Hunter

Description:
Vehicle: 2025
Bitdeer Scissor Lift
SN: 17304504
batteries



Photo: 14

Date Taken:
12/29/2025

Taken By:
Anthony Hunter

Description:
Vehicle: 2025
Bitdeer Scissor Lift
SN: 17304504 ID

Claim Photo

Our File Number:

Adjuster:

Insured:

Date of Loss:

Customer File Number:

Policy Number:



Photo: 15

Date Taken:
12/29/2025

Taken By:
Anthony Hunter

Description:
Vehicle: 2025
Bitdeer Scissor Lift
SN: 17304504 front extensions



Photo: 16

Date Taken:
12/29/2025

Taken By:
Anthony Hunter

Description:
Vehicle: 2025
Bitdeer Scissor Lift
SN: 17304504
front extensions

Claim Photo

Our File Number:

Adjuster:

Insured:

Date of Loss:

Customer File Number:

Policy Number:



Photo: 17

Date Taken:
12/29/2025

Taken By:
Anthony Hunter

Description:
Vehicle: 2025
Bitdeer Scissor Lift
SN: 17304504



Photo: 18

Date Taken:
12/29/2025

Taken By:
Anthony Hunter

Description:
Vehicle: 2025
Bitdeer Scissor Lift
SN: 17304504 VIN

Claim Photo

Our File Number:

Adjuster:

Insured:

Date of Loss:

Customer File Number:

Policy Number:




Photo: 19

Date Taken:
12/29/2025

Taken By:
Anthony Hunter

Description:
Vehicle: 2025
Bitdeer Scissor Lift
SN: 17304504 VIN
plate