Our File Number: 277-065357 Adjuster: Jeff Meurer

Insured: SIMS GROUP USA HOLDINGS CORPORATION

Date of Loss: 09/16/2025

Customer File Number: 009117-001174-AP-01

Policy Number:






Photo: 1

Date Taken: 12/09/2025

Taken By: Matthew Claeys

Description:

trailer

VIN of damaged

Date Taken:
12/09/2025

Taken By:
Matthew Claeys

Description:

Photo: 2



Description:Sticker on frame of damaged trailer

Our File Number: 277-065357 Adjuster: Jeff Meurer

Insured: SIMS GROUP USA HOLDINGS CORPORATION

Date of Loss: 09/16/2025

Customer File Number: 009117-001174-AP-01

Policy Number:






Photo: 3

Date Taken: 12/09/2025

Taken By: Matthew Claeys

Description:Front left corner of damaged trailer



Photo: 4

Date Taken: 12/09/2025

Taken By: Matthew Claeys

Description: Front right corner of damaged trailer

Our File Number: 277-065357 Adjuster: Jeff Meurer

Insured: SIMS GROUP USA HOLDINGS CORPORATION

Date of Loss: 09/16/2025

Customer File Number: 009117-001174-AP-01

Policy Number:





Photo: 5

Date Taken: 12/09/2025

Taken By: Matthew Claeys

Description: Right rear croner of damaged trailer



Photo: 6

Date Taken: 12/09/2025

Taken By: Matthew Claeys

Description:Left rear corner of damaged trailer

Our File Number: 277-065357 Adjuster: Jeff Meurer

Insured: SIMS GROUP USA HOLDINGS CORPORATION

Date of Loss: 09/16/2025

Customer File Number: 009117-001174-AP-01

Policy Number:





Photo: 7

Date Taken: 12/09/2025

Taken By: Matthew Claeys

Description:

Damage to rear door of damaged trailer, from right side



Photo: 8

Date Taken: 12/09/2025

Taken By: Matthew Claeys

Description:

Damage to rear door from right side of damaged trailer

Our File Number: 277-065357 Adjuster: Jeff Meurer

Insured: SIMS GROUP USA HOLDINGS CORPORATION

Date of Loss: 09/16/2025

Customer File Number: 009117-001174-AP-01

Policy Number:






Photo: 9

Date Taken: 12/09/2025

Taken By: Matthew Claeys

·

Description:Damage to tarp arm of damaged trailer




Photo: 10

Date Taken:

12/09/2025

Taken By: Matthew Claeys

Description:

Damage to tarp arm of damaged trailer

Our File Number: 277-065357 Adjuster: Jeff Meurer

Insured: SIMS GROUP USA HOLDINGS CORPORATION

Date of Loss: 09/16/2025

Customer File Number: 009117-001174-AP-01

Policy Number:






Photo: 11

Date Taken: 12/09/2025

Taken By: Matthew Claeys

Description:

Damage to tarp arm at top right corner of damaged trailer




Photo: 12

Date Taken:

12/09/2025

Taken By: Matthew Claeys

Description:

Damage to tarp arm at top right corner of damaged trailer

Our File Number: 277-065357 Adjuster: Jeff Meurer

Insured: SIMS GROUP USA HOLDINGS CORPORATION

Date of Loss: 09/16/2025

Customer File Number: 009117-001174-AP-01

Policy Number:





Photo: 13

Date Taken: 12/09/2025

Taken By: Matthew Claeys

Description:

Damage to tarp, front right corner of damaged trailer




Photo: 14

Date Taken: 12/09/2025

Taken By: Matthew Claeys

Description:

Frame from right side front of damaged trailer

Our File Number: 277-065357 Adjuster: Jeff Meurer

Insured: SIMS GROUP USA HOLDINGS CORPORATION

Date of Loss: 09/16/2025

Customer File Number: 009117-001174-AP-01

Policy Number:





Photo: 15

Date Taken: 12/09/2025

Taken By: Matthew Claeys

Description: Frame from front of damaged trailer



Photo: 16

Date Taken:

12/09/2025

Taken By: Matthew Claeys

Description:

Frame fron front left side of damaged trailer

Our File Number: 277-065357 Adjuster: Jeff Meurer

Insured: SIMS GROUP USA HOLDINGS CORPORATION

Date of Loss: 09/16/2025

Customer File Number: 009117-001174-AP-01

Policy Number:





Photo: 17

Date Taken:

12/09/2025

Taken By: Matthew Claeys

Description:

Damage to cylinder of damaged trailer



Photo: 18

Date Taken:

12/09/2025

Taken By:

Matthew Claeys

Description:

Damage to frame, left side of damaged trailer

Our File Number: 277-065357 Adjuster: Jeff Meurer

Insured: SIMS GROUP USA HOLDINGS CORPORATION

Date of Loss: 09/16/2025

Customer File Number: 009117-001174-AP-01

Policy Number:





Photo: 19

Date Taken: 12/09/2025

Taken By: Matthew Claeys

Description:
Damage to frame,
left side of
damaged trailer




Photo: 20

Date Taken: 12/09/2025

Taken By: Matthew Claeys

Description:

Damage to frame, left side, from rear to front of damaged trailer

Our File Number: 277-065357 Adjuster: Jeff Meurer

Insured: SIMS GROUP USA HOLDINGS CORPORATION

Date of Loss: 09/16/2025

Customer File Number: 009117-001174-AP-01

Policy Number:





Photo: 21

Date Taken: 12/09/2025

Taken By: Matthew Claeys

Description:Damage to frame, left side, from rear to front of damaged trailer




Photo: 22

Date Taken:

12/09/2025

Taken By: Matthew Claeys

Description:

Damage to frame, left side, from rear to front of damaged trailer

Our File Number: 277-065357 Adjuster: Jeff Meurer

Insured: SIMS GROUP USA HOLDINGS CORPORATION

Date of Loss: 09/16/2025

Customer File Number: 009117-001174-AP-01

Policy Number:





Photo: 23

Date Taken: 12/09/2025

Taken By: Matthew Claeys

Description: Axle 4, left side, outside tire tread depth of damaged

trailer




Photo: 24

Date Taken: 12/09/2025

Taken By: Matthew Claeys

Description:

Axle 4, left side, inside tire tread depth of damaged trailer

Our File Number: 277-065357 Adjuster: Jeff Meurer

Insured: SIMS GROUP USA HOLDINGS CORPORATION

Date of Loss: 09/16/2025

Customer File Number: 009117-001174-AP-01

Policy Number:





Photo: 25

Date Taken: 12/09/2025

Taken By: Matthew Claeys

Description: Axle 5, left side, outside tire tread depth of damaged

trailer




Photo: 26

Date Taken: 12/09/2025

Taken By: Matthew Claeys

Description:

Axle 5, left side, inside tire tread depth of damaged trailer

Our File Number: 277-065357 Adjuster: Jeff Meurer

Insured: SIMS GROUP USA HOLDINGS CORPORATION

Date of Loss: 09/16/2025

Customer File Number: 009117-001174-AP-01

Policy Number:






Photo: 27

Date Taken: 12/09/2025

Taken By: Matthew Claeys

Description: Axle 5, right side, outside tire tread depth of damaged trailer



Photo: 28

Date Taken: 12/09/2025

Taken By:

Matthew Claeys

Description: Axle 5, right side, inside tire tread depth of damaged trailer

Our File Number: 277-065357 Adjuster: Jeff Meurer

Insured: SIMS GROUP USA HOLDINGS CORPORATION

Date of Loss: 09/16/2025

Customer File Number: 009117-001174-AP-01

Policy Number:





Photo: 29

Date Taken: 12/09/2025

Taken By: Matthew Claeys

Description: Axle 4, right side, outside tire tread depth of damaged trailer




Photo: 30

Date Taken: 12/09/2025

Taken By: Matthew Claeys

Description:Axle 4, right side, inside tire tread depth of damaged trailer

Our File Number: 277-065357 Adjuster: Jeff Meurer

Insured: SIMS GROUP USA HOLDINGS CORPORATION

Date of Loss: 09/16/2025

Customer File Number: 009117-001174-AP-01

Policy Number:





Photo: 31

Date Taken: 12/09/2025

Taken By: Matthew Claeys

Description:Brakes, drum, of damaged trailer




Photo: 32

Date Taken: 12/09/2025

Taken By: Matthew Claeys

Description: Rear dual wheels, both steel, of damaged trailer