

MANUFACTURED BY: DAIMLER VEH. COMERC. MEXICO

DATE OF MFR: 10/18

GVWR/PNBV-KG: 24,131

GVWR/PNBV-LBS: 53,200

THIS VEHICLE COMPLIES WITH ALL  
APPLICABLE FEDERAL MOTOR VEHICLE

SAFETY STANDARDS IN EFFECT AT THE DATE  
OF MANUFACTURE SHOWN ABOVE

VEHICLE ID NO: 3AKJHHR8KSKX6686

TYPE: TRUCK/TRACTOR TT/CT

COUNTRY OF ORIGIN: MEXICO

	GAWR/PNBE KGS	GAWR/PNBE LBS	TIRES	RIMS	KPA COLD	PSI COLD	"S"
FRONT AXLE:	5,987	13,200	295/75R22.5(H)	22.5X8.25	827	120	S
1ST INT AXLE:	9,072	20,000	295/75R22.5(G)	22.5X8.25	758	110	D
2ND INT AXLE:							
3RD INT AXLE:							
4TH INT AXLE:							
5TH INT AXLE:							
6TH INT AXLE:							
REAR AXLE:	9,072	20,000	295/75R22.5(G)	22.5X8.25	758	110	D







