

Claim Photo

Our File Number: 277-066314
Adjuster: Mike Hogan
Insured: SHELDON MOORE
Date of Loss: 01/13/2026
Customer File Number: 000786-091987-AP-01
Policy Number:




Photo: 1

Date Taken:
01/21/2026

Taken By:
Timothy Davis

Description:
2018 Freightliner
VIN:
3AKJHHD7JSJU
2671




Photo: 2

Date Taken:
01/21/2026

Taken By:
Timothy Davis

Description:
right side door
sticker

Claim Photo

Our File Number: 277-066314
Adjuster: Mike Hogan
Insured: SHELDON MOORE
Date of Loss: 01/13/2026
Customer File Number: 000786-091987-AP-01
Policy Number:



Photo: 3

Date Taken:
01/21/2026

Taken By:
Timothy Davis

Description:
right side door
stickers




Photo: 4

Date Taken:
01/21/2026

Taken By:
Timothy Davis

Description:
would not power up
for mileage

Claim Photo

Our File Number: 277-066314
Adjuster: Mike Hogan
Insured: SHELDON MOORE
Date of Loss: 01/13/2026
Customer File Number: 000786-091987-AP-01
Policy Number:



Photo: 5

Date Taken:
01/21/2026

Taken By:
Timothy Davis

Description:
dash area




Photo: 6

Date Taken:
01/21/2026

Taken By:
Timothy Davis

Description:
passenger area

Claim Photo

Our File Number: 277-066314
Adjuster: Mike Hogan
Insured: SHELDON MOORE
Date of Loss: 01/13/2026
Customer File Number: 000786-091987-AP-01
Policy Number:



Photo: 7

Date Taken:
01/21/2026

Taken By:
Timothy Davis

Description:
sleeper right side




Photo: 8

Date Taken:
01/21/2026

Taken By:
Timothy Davis

Description:
Sleeper left side

Claim Photo

Our File Number: 277-066314
Adjuster: Mike Hogan
Insured: SHELDON MOORE
Date of Loss: 01/13/2026
Customer File Number: 000786-091987-AP-01
Policy Number:



Photo: 9

Date Taken:
01/21/2026

Taken By:
Timothy Davis

Description:
sleep area



Photo: 10

Date Taken:
01/21/2026

Taken By:
Timothy Davis

Description:
dash area

Claim Photo

Our File Number: 277-066314
Adjuster: Mike Hogan
Insured: SHELDON MOORE
Date of Loss: 01/13/2026
Customer File Number: 000786-091987-AP-01
Policy Number:



Photo: 11

Date Taken:
01/21/2026

Taken By:
Timothy Davis

Description:
dash area




Photo: 12

Date Taken:
01/21/2026

Taken By:
Timothy Davis

Description:
2018 Freightliner
Cascadia
Front view

Claim Photo

Our File Number: 277-066314
Adjuster: Mike Hogan
Insured: SHELDON MOORE
Date of Loss: 01/13/2026
Customer File Number: 000786-091987-AP-01
Policy Number:




Photo: 13

Date Taken:
01/21/2026

Taken By:
Timothy Davis

Description:
2018 Freightliner
Cascadia
Left side front to
back



Photo: 14

Date Taken:
01/21/2026

Taken By:
Timothy Davis

Description:
2018 Freightliner
Cascadia
left side

Claim Photo

Our File Number: 277-066314
Adjuster: Mike Hogan
Insured: SHELDON MOORE
Date of Loss: 01/13/2026
Customer File Number: 000786-091987-AP-01
Policy Number:



Photo: 15

Date Taken:
01/21/2026

Taken By:
Timothy Davis

Description:
2018 Freightliner
Cascadia
left side back to
front



Photo: 16

Date Taken:
01/21/2026

Taken By:
Timothy Davis

Description:
2018 Freightliner
Cascadia
rear view

Claim Photo

Our File Number: 277-066314
Adjuster: Mike Hogan
Insured: SHELDON MOORE
Date of Loss: 01/13/2026
Customer File Number: 000786-091987-AP-01
Policy Number:



Photo: 17

Date Taken:
01/21/2026

Taken By:
Timothy Davis

Description:
2018 Freightliner
Cascadia
right side back to
front




Photo: 18

Date Taken:
01/21/2026

Taken By:
Timothy Davis

Description:
2018 Freightliner
Cascadia
right side

Claim Photo

Our File Number: 277-066314
Adjuster: Mike Hogan
Insured: SHELDON MOORE
Date of Loss: 01/13/2026
Customer File Number: 000786-091987-AP-01
Policy Number:




Photo: 19

Date Taken:
01/21/2026

Taken By:
Timothy Davis

Description:
2018 Freightliner
Cascadia
right side front to
back




Photo: 20

Date Taken:
01/21/2026

Taken By:
Timothy Davis

Description:
right front damage

Claim Photo

Our File Number: 277-066314
Adjuster: Mike Hogan
Insured: SHELDON MOORE
Date of Loss: 01/13/2026
Customer File Number: 000786-091987-AP-01
Policy Number:




Photo: 21

Date Taken:
01/21/2026

Taken By:
Timothy Davis

Description:
right front




Photo: 22

Date Taken:
01/21/2026

Taken By:
Timothy Davis

Description:
right front

Claim Photo

Our File Number: 277-066314
Adjuster: Mike Hogan
Insured: SHELDON MOORE
Date of Loss: 01/13/2026
Customer File Number: 000786-091987-AP-01
Policy Number:



Photo: 23

Date Taken:
01/21/2026

Taken By:
Timothy Davis

Description:
right front above
wheel




Photo: 24

Date Taken:
01/21/2026

Taken By:
Timothy Davis

Description:
right front

Claim Photo

Our File Number: 277-066314
Adjuster: Mike Hogan
Insured: SHELDON MOORE
Date of Loss: 01/13/2026
Customer File Number: 000786-091987-AP-01
Policy Number:




Photo: 25

Date Taken:
01/21/2026

Taken By:
Timothy Davis

Description:
right front under
hood. Hood would
not open



Photo: 26

Date Taken:
01/21/2026

Taken By:
Timothy Davis

Description:
right front of grill
area

Claim Photo

Our File Number: 277-066314
Adjuster: Mike Hogan
Insured: SHELDON MOORE
Date of Loss: 01/13/2026
Customer File Number: 000786-091987-AP-01
Policy Number:




Photo: 27

Date Taken:
01/21/2026

Taken By:
Timothy Davis

Description:
grill area




Photo: 28

Date Taken:
01/21/2026

Taken By:
Timothy Davis

Description:
left front

Claim Photo

Our File Number: 277-066314
Adjuster: Mike Hogan
Insured: SHELDON MOORE
Date of Loss: 01/13/2026
Customer File Number: 000786-091987-AP-01
Policy Number:




Photo: 29

Date Taken:
01/21/2026

Taken By:
Timothy Davis

Description:
left front damage



Photo: 30

Date Taken:
01/21/2026

Taken By:
Timothy Davis

Description:
above left front
wheel

Claim Photo

Our File Number: 277-066314
Adjuster: Mike Hogan
Insured: SHELDON MOORE
Date of Loss: 01/13/2026
Customer File Number: 000786-091987-AP-01
Policy Number:




Photo: 31

Date Taken:
01/21/2026

Taken By:
Timothy Davis

Description:
behind left front
wheel area




Photo: 32

Date Taken:
01/21/2026

Taken By:
Timothy Davis

Description:
left front damage

Claim Photo

Our File Number: 277-066314
Adjuster: Mike Hogan
Insured: SHELDON MOORE
Date of Loss: 01/13/2026
Customer File Number: 000786-091987-AP-01
Policy Number:



Photo: 33

Date Taken:
01/21/2026

Taken By:
Timothy Davis

Description:
panel broke left
side




Photo: 34

Date Taken:
01/21/2026

Taken By:
Timothy Davis

Description:
under hood right
side

Claim Photo

Our File Number: 277-066314
Adjuster: Mike Hogan
Insured: SHELDON MOORE
Date of Loss: 01/13/2026
Customer File Number: 000786-091987-AP-01
Policy Number:



Photo: 35

Date Taken:
01/21/2026

Taken By:
Timothy Davis

Description:
under hood right
side



Photo: 36

Date Taken:
01/21/2026

Taken By:
Timothy Davis

Description:
engine area

Claim Photo

Our File Number: 277-066314
Adjuster: Mike Hogan
Insured: SHELDON MOORE
Date of Loss: 01/13/2026
Customer File Number: 000786-091987-AP-01
Policy Number:




Photo: 37

Date Taken:
01/21/2026

Taken By:
Timothy Davis

Description:
engine area



Photo: 38

Date Taken:
01/21/2026

Taken By:
Timothy Davis

Description:
broken windshield

Claim Photo

Our File Number: 277-066314
Adjuster: Mike Hogan
Insured: SHELDON MOORE
Date of Loss: 01/13/2026
Customer File Number: 000786-091987-AP-01
Policy Number:



Photo: 39

Date Taken:
01/21/2026

Taken By:
Timothy Davis

Description:
right side damage




Photo: 40

Date Taken:
01/21/2026

Taken By:
Timothy Davis

Description:
under hood/broken
windshield

Claim Photo

Our File Number: 277-066314
Adjuster: Mike Hogan
Insured: SHELDON MOORE
Date of Loss: 01/13/2026
Customer File Number: 000786-091987-AP-01
Policy Number:




Photo: 41

Date Taken:
01/21/2026

Taken By:
Timothy Davis

Description:
under hood/engine
area



Photo: 42

Date Taken:
01/21/2026

Taken By:
Timothy Davis

Description:
engine area

Claim Photo

Our File Number: 277-066314
Adjuster: Mike Hogan
Insured: SHELDON MOORE
Date of Loss: 01/13/2026
Customer File Number: 000786-091987-AP-01
Policy Number:



Photo: 43

Date Taken:
01/21/2026

Taken By:
Timothy Davis

Description:
engine area



Photo: 44

Date Taken:
01/21/2026

Taken By:
Timothy Davis

Description:
broken windshield

Claim Photo

Our File Number: 277-066314
Adjuster: Mike Hogan
Insured: SHELDON MOORE
Date of Loss: 01/13/2026
Customer File Number: 000786-091987-AP-01
Policy Number:



Photo: 45

Date Taken:
01/21/2026

Taken By:
Timothy Davis

Description:
Landstar
USDOT 216939



Photo: 46

Date Taken:
01/21/2026

Taken By:
Timothy Davis

Description:
left front wheel

Claim Photo

Our File Number: 277-066314
Adjuster: Mike Hogan
Insured: SHELDON MOORE
Date of Loss: 01/13/2026
Customer File Number: 000786-091987-AP-01
Policy Number:



Photo: 47

Date Taken:
01/21/2026

Taken By:
Timothy Davis

Description:
left side 1st double
set



Photo: 48

Date Taken:
01/21/2026

Taken By:
Timothy Davis

Description:
inside set

Claim Photo

Our File Number: 277-066314
Adjuster: Mike Hogan
Insured: SHELDON MOORE
Date of Loss: 01/13/2026
Customer File Number: 000786-091987-AP-01
Policy Number:



Photo: 49

Date Taken:
01/21/2026

Taken By:
Timothy Davis

Description:
behind left rear
wheel




Photo: 50

Date Taken:
01/21/2026

Taken By:
Timothy Davis

Description:
left side rear 1st
double set inside
11/32

Claim Photo

Our File Number: 277-066314
Adjuster: Mike Hogan
Insured: SHELDON MOORE
Date of Loss: 01/13/2026
Customer File Number: 000786-091987-AP-01
Policy Number:



Photo: 51

Date Taken:
01/21/2026

Taken By:
Timothy Davis

Description:
left side 1st double
set outside
11/32



Photo: 52

Date Taken:
01/21/2026

Taken By:
Timothy Davis

Description:
left side 2nd double
set

Claim Photo

Our File Number: 277-066314
Adjuster: Mike Hogan
Insured: SHELDON MOORE
Date of Loss: 01/13/2026
Customer File Number: 000786-091987-AP-01
Policy Number:



Photo: 53

Date Taken:
01/21/2026

Taken By:
Timothy Davis

Description:
left side 2nd double
set inside
22/32



Photo: 54

Date Taken:
01/21/2026

Taken By:
Timothy Davis

Description:
left side 2nd double
set outside
28/32

Claim Photo

Our File Number: 277-066314
Adjuster: Mike Hogan
Insured: SHELDON MOORE
Date of Loss: 01/13/2026
Customer File Number: 000786-091987-AP-01
Policy Number:



Photo: 55

Date Taken:
01/21/2026

Taken By:
Timothy Davis

Description:
right side front



Photo: 56

Date Taken:
01/21/2026

Taken By:
Timothy Davis

Description:
right side front
16/32

Claim Photo

Our File Number: 277-066314
Adjuster: Mike Hogan
Insured: SHELDON MOORE
Date of Loss: 01/13/2026
Customer File Number: 000786-091987-AP-01
Policy Number:




Photo: 57

Date Taken:
01/21/2026

Taken By:
Timothy Davis

Description:
right side 1st
double set



Photo: 58

Date Taken:
01/21/2026

Taken By:
Timothy Davis

Description:
right side 1st
double set inside
10/32

Claim Photo

Our File Number: 277-066314
Adjuster: Mike Hogan
Insured: SHELDON MOORE
Date of Loss: 01/13/2026
Customer File Number: 000786-091987-AP-01
Policy Number:



Photo: 59

Date Taken:
01/21/2026

Taken By:
Timothy Davis

Description:
right side 1st
double set outside
11/32



Photo: 60

Date Taken:
01/21/2026

Taken By:
Timothy Davis

Description:
right side 2nd
double set

Claim Photo

Our File Number: 277-066314
Adjuster: Mike Hogan
Insured: SHELDON MOORE
Date of Loss: 01/13/2026
Customer File Number: 000786-091987-AP-01
Policy Number:



Photo: 61

Date Taken:
01/21/2026

Taken By:
Timothy Davis

Description:
right side 2nd
double set inside
28/32



Photo: 62

Date Taken:
01/21/2026

Taken By:
Timothy Davis

Description:
right side 2nd
double set outside
28/32

Claim Photo

Our File Number: 277-066314
Adjuster: Mike Hogan
Insured: SHELDON MOORE
Date of Loss: 01/13/2026
Customer File Number: 000786-091987-AP-01
Policy Number:




Photo: 63

Date Taken:
01/21/2026

Taken By:
Timothy Davis

Description:
behind cab right
side



Photo: 64

Date Taken:
01/21/2026

Taken By:
Timothy Davis

Description:
hitch area

Claim Photo

Our File Number: 277-066314
Adjuster: Mike Hogan
Insured: SHELDON MOORE
Date of Loss: 01/13/2026
Customer File Number: 000786-091987-AP-01
Policy Number:




Photo: 65

Date Taken:
01/21/2026

Taken By:
Timothy Davis

Description:
behind cab left side



Photo: 66

Date Taken:
01/21/2026

Taken By:
Timothy Davis

Description:
right front corner

Claim Photo

Our File Number: 277-066314
Adjuster: Mike Hogan
Insured: SHELDON MOORE
Date of Loss: 01/13/2026
Customer File Number: 000786-091987-AP-01
Policy Number:




Photo: 67

Date Taken:
01/21/2026

Taken By:
Timothy Davis

Description:
under engine area




Photo: 68

Date Taken:
01/21/2026

Taken By:
Timothy Davis

Description:
Tow Bill

Claim Photo

Our File Number: 277-066314
Adjuster: Mike Hogan
Insured: SHELDON MOORE
Date of Loss: 01/13/2026
Customer File Number: 000786-091987-AP-01
Policy Number:




Photo: 69

Date Taken:
01/21/2026

Taken By:
Timothy Davis

Description:
Tow Bill (her
printer would not
work)



Photo: 70

Date Taken:
01/21/2026

Taken By:
Timothy Davis

Description:
Last oil change 5-9-
25
Mileage: 768,984

Claim Photo

Our File Number: 277-066314
Adjuster: Mike Hogan
Insured: SHELDON MOORE
Date of Loss: 01/13/2026
Customer File Number: 000786-091987-AP-01
Policy Number:



Photo: 71

Date Taken:
01/21/2026

Taken By:
Timothy Davis

Description:
left front
16/32



Photo: 72

Date Taken:
01/21/2026

Taken By:
Timothy Davis

Description:
under engine area

Claim Photo

Our File Number: 277-066314
Adjuster: Mike Hogan
Insured: SHELDON MOORE
Date of Loss: 01/13/2026
Customer File Number: 000786-091987-AP-01
Policy Number:



Photo: 73

Date Taken:
01/21/2026

Taken By:
Timothy Davis

Description:
under right corner



Photo: 74

Date Taken:
01/21/2026

Taken By:
Timothy Davis

Description:
under bumper area

Claim Photo

Our File Number: 277-066314
Adjuster: Mike Hogan
Insured: SHELDON MOORE
Date of Loss: 01/13/2026
Customer File Number: 000786-091987-AP-01
Policy Number:



Photo: 75

Date Taken:
01/21/2026

Taken By:
Timothy Davis

Description:
under bumper area




Photo: 76

Date Taken:
01/21/2026

Taken By:
Timothy Davis

Description:
under bumper area

Claim Photo

Our File Number: 277-066314
Adjuster: Mike Hogan
Insured: SHELDON MOORE
Date of Loss: 01/13/2026
Customer File Number: 000786-091987-AP-01
Policy Number:




Photo: 77

Date Taken:
01/21/2026

Taken By:
Timothy Davis

Description:
behind left front
wheel



Photo: 78

Date Taken:
01/21/2026

Taken By:
Timothy Davis

Description:
under left side front
to back

Claim Photo

Our File Number: 277-066314
Adjuster: Mike Hogan
Insured: SHELDON MOORE
Date of Loss: 01/13/2026
Customer File Number: 000786-091987-AP-01
Policy Number:




Photo: 79

Date Taken:
01/21/2026

Taken By:
Timothy Davis

Description:
underneath straight
back



Photo: 80

Date Taken:
01/21/2026

Taken By:
Timothy Davis

Description:
behind right wheel

Claim Photo

Our File Number: 277-066314
Adjuster: Mike Hogan
Insured: SHELDON MOORE
Date of Loss: 01/13/2026
Customer File Number: 000786-091987-AP-01
Policy Number:




Photo: 81
Date Taken: 01/21/2026
Taken By: Timothy Davis
Description: underneath right side front to back