

7600 Crescent Lake Ct.
Fort Worth, TX 76137

- 1 1-2015 Bandit 2550 Stump
Grinder | S/N: 251438
Date Taken: 9/4/2024
Taken By: VIS - Garrett Cox
Front Overview



- 2 2-2015 Bandit 2550 Stump
Grinder | S/N: 251438
Date Taken: 9/4/2024
Taken By: VIS - Garrett Cox
Front Right Corner



7600 Crescent Lake Ct.
Fort Worth, TX 76137

- 3 3-2015 Bandit 2550 Stump
Grinder | S/N: 251438
Date Taken: 9/4/2024
Taken By: VIS - Garrett Cox
Front Left Corner




- 4 4-2015 Bandit 2550 Stump
Grinder | S/N: 251438
Date Taken: 9/4/2024
Taken By: VIS - Garrett Cox
Left Side View




7600 Crescent Lake Ct.
Fort Worth, TX 76137

- 5 5-2015 Bandit 2550 Stump
Grinder | S/N: 251438
Date Taken: 9/4/2024
Taken By: VIS - Garrett Cox
Damage To Frame & Axle



- 6 6-2015 Bandit 2550 Stump
Grinder | S/N: 251438
Date Taken: 9/4/2024
Taken By: VIS - Garrett Cox
Damage To Alternator & Oil Filter



7600 Crescent Lake Ct.
Fort Worth, TX 76137

- 7 7-2015 Bandit 2550 Stump
Grinder | S/N: 251438
Date Taken: 9/4/2024
Taken By: VIS - Garrett Cox
Diesel Tank



- 8 8-2015 Bandit 2550 Stump
Grinder | S/N: 251438
Date Taken: 9/4/2024
Taken By: VIS - Garrett Cox
Equipment Information



7600 Crescent Lake Ct.
Fort Worth, TX 76137

- 9 9-2015 Bandit 2550 Stump
Grinder | S/N: 251438
Date Taken: 9/4/2024
Taken By: VIS - Garrett Cox
Serial Number Tag



- 10 10-2015 Bandit 2550 Stump
Grinder | S/N: 251438
Date Taken: 9/4/2024
Taken By: VIS - Garrett Cox
2015 Bandit 2550 Stump Grinder |
S/N: 251438



7600 Crescent Lake Ct.
Fort Worth, TX 76137

- 11 11-2015 Bandit 2550 Stump
Grinder | S/N: 251438
Date Taken: 9/4/2024
Taken By: VIS - Garrett Cox
Front View Of Machine



- 12 12-2015 Bandit 2550 Stump
Grinder | S/N: 251438
Date Taken: 9/4/2024
Taken By: VIS - Garrett Cox
Hyd. Motor Damaged That Turns The
Grinder Head



7600 Crescent Lake Ct.
Fort Worth, TX 76137

- 13 13-2015 Bandit 2550 Stump
Grinder | S/N: 251438
Date Taken: 9/4/2024
Taken By: VIS - Garrett Cox
Number Welded On Unit



- 14 14-2015 Bandit 2550 Stump
Grinder | S/N: 251438
Date Taken: 9/4/2024
Taken By: VIS - Garrett Cox
Front Right Corner



7600 Crescent Lake Ct.
Fort Worth, TX 76137

- 15 15-2015 Bandit 2550 Stump
Grinder | S/N: 251438
Date Taken: 9/4/2024
Taken By: VIS - Garrett Cox
Front Left Corner



- 16 16-2015 Bandit 2550 Stump
Grinder | S/N: 251438
Date Taken: 9/4/2024
Taken By: VIS - Garrett Cox
Front View



7600 Crescent Lake Ct.
Fort Worth, TX 76137

- 17 17-2015 Bandit 2550 Stump
Grinder | S/N: 251438
Date Taken: 9/4/2024
Taken By: VIS - Garrett Cox
Left Side View



- 18 18-2015 Bandit 2550 Stump
Grinder | S/N: 251438
Date Taken: 9/4/2024
Taken By: VIS - Garrett Cox
254 Hours




7600 Crescent Lake Ct.
Fort Worth, TX 76137

- 19 19-2015 Bandit 2550 Stump
Grinder | S/N: 251438
Date Taken: 9/4/2024
Taken By: VIS - Garrett Cox
254 Hours



- 20 20-2015 Bandit 2550 Stump
Grinder | S/N: 251438
Date Taken: 9/4/2024
Taken By: VIS - Garrett Cox
Engine Damage



7600 Crescent Lake Ct.
Fort Worth, TX 76137

- 21 21-2015 Bandit 2550 Stump
Grinder | S/N: 251438
Date Taken: 9/4/2024
Taken By: VIS - Garrett Cox
Front Frame & Axel Damage



- 22 22-2015 Bandit 2550 Stump
Grinder | S/N: 251438
Date Taken: 9/4/2024
Taken By: VIS - Garrett Cox
Alternator Damaged



7600 Crescent Lake Ct.
Fort Worth, TX 76137

- 23 23-2015 Bandit 2550 Stump
Grinder | S/N: 251438
Date Taken: 9/4/2024
Taken By: VIS - Garrett Cox
Front Engine Damage



- 24 24-2015 Bandit 2550 Stump
Grinder | S/N: 251438
Date Taken: 9/4/2024
Taken By: VIS - Garrett Cox
Fan Damaged



7600 Crescent Lake Ct.
Fort Worth, TX 76137

- 25 25-2015 Bandit 2550 Stump
Grinder | S/N: 251438
Date Taken: 9/4/2024
Taken By: VIS - Garrett Cox
Damage To Front Of Engine & Fan



- 26 26-2015 Bandit 2550 Stump
Grinder | S/N: 251438
Date Taken: 9/4/2024
Taken By: VIS - Garrett Cox
Guard Damage



7600 Crescent Lake Ct.
Fort Worth, TX 76137

- 27 27-2015 Bandit 2550 Stump
Grinder | S/N: 251438
Date Taken: 9/4/2024
Taken By: VIS - Garrett Cox
Electrical Damage



- 28 28-2015 Bandit 2550 Stump
Grinder | S/N: 251438
Date Taken: 9/4/2024
Taken By: VIS - Garrett Cox
Left Side Overview



7600 Crescent Lake Ct.
Fort Worth, TX 76137

- 29 29-2015 Bandit 2550 Stump
Grinder | S/N: 251438
Date Taken: 9/4/2024
Taken By: VIS - Garrett Cox
Damage To Front Of Unit



- 30 30-2015 Bandit 2550 Stump
Grinder | S/N: 251438
Date Taken: 9/4/2024
Taken By: VIS - Garrett Cox
Grinder Head Is Damaged



7600 Crescent Lake Ct.
Fort Worth, TX 76137

- 31 31-2015 Bandit 2550 Stump
Grinder | S/N: 251438
Date Taken: 9/4/2024
Taken By: VIS - Garrett Cox
Grinder Head Connection Is Damaged



- 32 32-2015 Bandit 2550 Stump
Grinder | S/N: 251438
Date Taken: 9/4/2024
Taken By: VIS - Garrett Cox
Hyd. Tank & Hoses Are Damaged



7600 Crescent Lake Ct.
Fort Worth, TX 76137

- 33 33-2015 Bandit 2550 Stump
Grinder | S/N: 251438
Date Taken: 9/4/2024
Taken By: VIS - Garrett Cox
Guard Damaged



- 34 34-2015 Bandit 2550 Stump
Grinder | S/N: 251438
Date Taken: 9/4/2024
Taken By: VIS - Garrett Cox
Left Side Engine Damage



7600 Crescent Lake Ct.
Fort Worth, TX 76137

- 35 35-2015 Bandit 2550 Stump
Grinder | S/N: 251438
Date Taken: 9/4/2024
Taken By: VIS - Garrett Cox
Axle & Frame Damage



- 36 36-2015 Bandit 2550 Stump
Grinder | S/N: 251438
Date Taken: 9/4/2024
Taken By: VIS - Garrett Cox
Tires Are About Half Worn



7600 Crescent Lake Ct.
Fort Worth, TX 76137

- 37 37-2015 Bandit 2550 Stump
Grinder | S/N: 251438
Date Taken: 9/4/2024
Taken By: VIS - Garrett Cox
Front Frame Damage



- 38 38-2015 Bandit 2550 Stump
Grinder | S/N: 251438
Date Taken: 9/4/2024
Taken By: VIS - Garrett Cox
Showing Frame Is Twisted



7600 Crescent Lake Ct.
Fort Worth, TX 76137

- 39 39-2015 Bandit 2550 Stump
Grinder | S/N: 251438
Date Taken: 9/4/2024
Taken By: VIS - Garrett Cox
Front Left Corner




- 40 40-2015 Bandit 2550 Stump
Grinder | S/N: 251438
Date Taken: 9/4/2024
Taken By: VIS - Garrett Cox
Axle & Frame Damage



7600 Crescent Lake Ct.
Fort Worth, TX 76137

- 41 41-2015 Bandit 2550 Stump
Grinder | S/N: 251438
Date Taken: 9/4/2024
Taken By: VIS - Garrett Cox
Frame Is Twisted



- 42 42-2015 Bandit 2550 Stump
Grinder | S/N: 251438
Date Taken: 9/4/2024
Taken By: VIS - Garrett Cox
Engine Damage



7600 Crescent Lake Ct.
Fort Worth, TX 76137

- 43 43-2015 Bandit 2550 Stump
Grinder | S/N: 251438
Date Taken: 9/4/2024
Taken By: VIS - Garrett Cox
Engine Block Is Damged



- 44 44-2015 Bandit 2550 Stump
Grinder | S/N: 251438
Date Taken: 9/4/2024
Taken By: VIS - Garrett Cox
Electrical & Cover Damage



7600 Crescent Lake Ct.
Fort Worth, TX 76137

- 45 45-2015 Bandit 2550 Stump
Grinder | S/N: 251438
Date Taken: 9/4/2024
Taken By: VIS - Garrett Cox
Fuel Tank Damage



- 46 46-2015 Bandit 2550 Stump
Grinder | S/N: 251438
Date Taken: 9/4/2024
Taken By: VIS - Garrett Cox
Top Overview



7600 Crescent Lake Ct.
Fort Worth, TX 76137

- 47 47-2015 Bandit 2550 Stump
Grinder | S/N: 251438
Date Taken: 9/4/2024
Taken By: VIS - Garrett Cox
Overview



- 48 48-2015 Bandit 2550 Stump
Grinder | S/N: 251438
Date Taken: 9/4/2024
Taken By: VIS - Garrett Cox
Overview




7600 Crescent Lake Ct.
Fort Worth, TX 76137

- 49 49-2015 Bandit 2550 Stump
Grinder | S/N: 251438
Date Taken: 9/4/2024
Taken By: VIS - Garrett Cox
Overview



- 50 50-2015 Bandit 2550 Stump
Grinder | S/N: 251438
Date Taken: 9/4/2024
Taken By: VIS - Garrett Cox
No Oil On The Dipstick



7600 Crescent Lake Ct.
Fort Worth, TX 76137

- 51 51-2015 Bandit 2550 Stump
Grinder | S/N: 251438
Date Taken: 9/4/2024
Taken By: VIS - Garrett Cox
No Oil On The Dip Stick



- 52 52-2015 Bandit 2550 Stump
Grinder | S/N: 251438
Date Taken: 9/4/2024
Taken By: VIS - Garrett Cox
Hyd. Tank Doesn't Show Any Fluid



7600 Crescent Lake Ct.
Fort Worth, TX 76137

- 53 53-2015 Bandit 2550 Stump
Grinder | S/N: 251438
Date Taken: 9/4/2024
Taken By: VIS - Garrett Cox
Hyd Oil Site Glass



- 54 54-2015 Bandit 2550 Stump
Grinder | S/N: 251438
Date Taken: 9/4/2024
Taken By: VIS - Garrett Cox
Tire Life Is 50%



7600 Crescent Lake Ct.
Fort Worth, TX 76137

55 55-2015 Bandit 2550 Stump
Grinder | S/N: 251438
Date Taken: 9/4/2024
Taken By: VIS - Garrett Cox
Tire Life Is 50%



56 56-2015 Bandit 2550 Stump
Grinder | S/N: 251438
Date Taken: 9/4/2024
Taken By: VIS - Garrett Cox
Tire Life Is 50%



7600 Crescent Lake Ct.
Fort Worth, TX 76137

- 57 57-2015 Bandit 2550 Stump
Grinder | S/N: 251438
Date Taken: 9/4/2024
Taken By: VIS - Garrett Cox
Tire Life Is 50%



- 58 58-2015 Bandit 2550 Stump
Grinder | S/N: 251438
Date Taken: 9/4/2024
Taken By: VIS - Garrett Cox
Info Tag



7600 Crescent Lake Ct.
Fort Worth, TX 76137

- 59 59-2015 Bandit 2550 Stump
Grinder | S/N: 251438
Date Taken: 9/4/2024
Taken By: VIS - Garrett Cox
Damage TO Body



- 60 60-2015 Bandit 2550 Stump
Grinder | S/N: 251438
Date Taken: 9/4/2024
Taken By: VIS - Garrett Cox
Body Damage



7600 Crescent Lake Ct.
Fort Worth, TX 76137

61 61-2015 Bandit 2550 Stump
Grinder | S/N: 251438
Date Taken: 9/4/2024
Taken By: VIS - Garrett Cox
Info



62 62-2015 Bandit 2550 Stump
Grinder | S/N: 251438
Date Taken: 9/4/2024
Taken By: VIS - Garrett Cox
Info



7600 Crescent Lake Ct.
Fort Worth, TX 76137

63 63-2015 Bandit 2550 Stump
Grinder | S/N: 251438
Date Taken: 9/4/2024
Taken By: VIS - Garrett Cox
Info



64 64-2015 Bandit 2550 Stump
Grinder | S/N: 251438
Date Taken: 9/4/2024
Taken By: VIS - Garrett Cox
Info Decal



7600 Crescent Lake Ct.
Fort Worth, TX 76137

- 65 65-2015 Bandit 2550 Stump
Grinder | S/N: 251438
Date Taken: 9/4/2024
Taken By: VIS - Garrett Cox
Info Decal



- 66 66-2015 Bandit 2550 Stump
Grinder | S/N: 251438
Date Taken: 9/4/2024
Taken By: VIS - Garrett Cox
Info Decals



7600 Crescent Lake Ct.
Fort Worth, TX 76137

67 67-2015 Bandit 2550 Stump
Grinder | S/N: 251438
Date Taken: 9/4/2024
Taken By: VIS - Garrett Cox
Frame Damage



68 68-2015 Bandit 2550 Stump
Grinder | S/N: 251438
Date Taken: 9/4/2024
Taken By: VIS - Garrett Cox
Info Decal



7600 Crescent Lake Ct.
Fort Worth, TX 76137

69 69-2015 Bandit 2550 Stump
Grinder | S/N: 251438
Date Taken: 9/4/2024
Taken By: VIS - Garrett Cox
Info Decal



70 70-2015 Bandit 2550 Stump
Grinder | S/N: 251438
Date Taken: 9/4/2024
Taken By: VIS - Garrett Cox
Serial Number Tag



7600 Crescent Lake Ct.
Fort Worth, TX 76137

71 71-2015 Bandit 2550 Stump
Grinder | S/N: 251438

Taken By: Insured

Photo Provided By The Insured



72 72-2015 Bandit 2550 Stump
Grinder | S/N: 251438

Taken By: Insured

Photo Provided By The Insured



7600 Crescent Lake Ct.
Fort Worth, TX 76137

73 73-2015 Bandit 2550 Stump
Grinder | S/N: 251438

Taken By: Insured

Photo Provided By The Insured

