



MANUFACTURED BY: DAIMLER VEH. COMERC. MEXICO

DATE OF MFR: 12/19

GVWR/PNBV-KG: 23,587

GVWR/PNBV-LBS: 52,000

THIS VEHICLE COMPLIES WITH ALL
APPLICABLE FEDERAL MOTOR VEHICLE
SAFETY STANDARDS IN EFFECT AT THE DATE
OF MANUFACTURE SHOWN ABOVE.

VEHICLE ID NO: 3AKJHHFG3LSLS0722

TYPE: TRUCK/TRACTOR TT/CT

COUNTRY OF ORIGIN: MEXICO

GAWR/PN
KGS

FRONT AXLE: 5,670

1ST INT AXLE: 9,072

2ND INT AXLE:

3RD INT AXLE:

4TH INT AXLE:

5TH INT AXLE:

6TH INT AXLE:

REAR AXLE: 9,072



RPM
x100



PSI

OIL



FUEL

DEF



MPH



PSI

AIR



°F

WATER

ULTRA LOW SULFUR
DIESEL FUEL ONLY



Extinguisher Inside



UNIT #102

USDOT#3460505

MC #1129403

GVW 80,000

Designated
artWay
Tractor



































A WARNING
Do not cut, weld or drill through this plate.
Refer to the Freightliner Service Manual, M Group for attachment instructions.

Freightliner





























WILLYS




































EQUIPMENT CLAIM SERVICES, INC.

TRUCK IDENTIFICATION

OWNER: ROSE PDX TRANSPORTATION LLC				PHONE: 971-716-2319			
INSURED: SAME				COMPANY: K2 CLAIMS SERVICES LLC			
LOCATION OF INSPECTION: STONE MOUNTAIN, GEORGIA				CLAIM / POLICY #: 12221091954			
APPRAISER / ADJUSTER: DENNIS DURHAM				DATE RECEIVED: 01/21/2026		DATE INSPECTED: 01/22/2026	

YEAR 2020	MAKE FREIGHTLINER	MODEL CASCADIA	MFG. DATE 12/2019	SERIAL 3AKJHHFG3LSLS0722	UNIT # 102
---------------------	-----------------------------	--------------------------	-----------------------------	------------------------------------	----------------------

LICENSE/STATE YAKK959 / OR	MILEAGE APPROX 460,000	HOURS N/A	HUBOMETER N/A	GLIDER KIT N/A	SERIAL # N/A
--------------------------------------	----------------------------------	---------------------	-------------------------	--------------------------	------------------------

☐ CAB OVER ☐ VAN BODY ☐ DAY CAB ☐ STEEL ☐ ALUMINUM ☒ CONVENTIONAL ☒ SLEEPER 73" ☐ DUMP ☒ FIBERGLASS ☒ CAB LENGTH 36"	INTERIOR CONDITION ☐ EXCELLENT ☐ GOOD ☒ AVERAGE ☐ POOR
---	--

RADIO: ☐ GPS ☒ AM/FM ☐ TAPE ☐ CB ☐ CD	☒ AIR RIDE SEAT(S) ☐ DELUXE INTERIOR TRIM	☐ EXT. SUN VISOR ☒ A/C	BUMPER: ☐ ALUMINUM ☐ STEEL ☒ PLASTIC ☐ FBRGLS ☒ COVERS ☐ AFTER MKT ☐ CHROME ☐ PAINTED ☐ TEXAS T
---	---	--	---

PAINT	☐ EXCELLENT ☐ GOOD ☒ AVERAGE ☐ POOR	PAINT COLOR: BLACK
-------	--	---------------------------

SPECIAL EQUIPMENT:	
--------------------	--

ENGINE MAKE: CUMMINS DIESEL	MODEL: 450 HP ISX	OVERHAULED ☐ YES ☐ NO ☒ UNK	DATE OVERHAULED: N/A	MILEAGE SINCE OVERHAUL: N/A
---------------------------------------	--------------------------	--	--------------------------------	---------------------------------------

ENGINE RUN AFTER UPSET? ☒ YES ☐ NO	ENGINE BRAKE? ☒ YES ☐ NO	TRANSMISSION MAKE EATON FULLER	MODEL FAOM-15810S-EC3	SPEEDS 10	PTO? ☐ YES ☒ NO	WET LINE KIT? ☐ YES ☒ NO
--	--	--	---------------------------------	---------------------	---	--

REAR AXLE MAKE: MERITOR	MODEL: MT-40-14X	RATIO: 2.64	☐ SINGLE ☐ PUSHER ☒ TWIN SCREW ☐ TRI ☐ TAG
-----------------------------------	----------------------------	-----------------------	--

FRAME	☒ STEEL ☐ ALUMINUM ☐ EXTENDED ☐ DOUBLE WALL WHEEL BASE INCHES: 230"
-------	--

5 TH WHEEL	☒ FONTAINE ☐ HOLLAND ☐ JOST ☐ SIMPLEX : ☐ MANUAL ☒ AIR SLIDE ☐ FIXED
-----------------------	---

FUEL TANKS	QTY: 2 MAKE: EQUIFLO ☐ STEEL ☒ ALUMINUM ☐ PAINTED ☐ POLISHED	☐ W/STEPS L/GALS: 120	R/GALS: 120
------------	--	--	--------------------

SUSPENSION	FRONT AXLE WEIGHT: 12,000 LBS	STEERING: ☐ MANUAL ☒ POWER	☐ SPRING ☒ AIR BAG ☐ TORSION ☐ HENDRICKSON ☐ AIR LEAF ☒ OTHER AIRLINER	BRAKES: ☒ AIR ☐ HYDRAULIC
------------	---	--	--	---

WHEELS	FRONT: ☒ BUDD ☐ DAYTON ☐ STEEL ☐ PAINTED ☐ CHROME ☒ ALUMINUM ☒ POLISHED ☐ SIMULATORS REAR: ☒ BUDD ☐ DAYTON ☒ STEEL4 ☒ PAINTED ☐ CHROME ☒ ALUMINUM 4 ☒ POLISHED ☐ SIMULATORS
--------	--

TIRE	TIRE DAMAGE	MAKE/MODEL	SIZE	/32	TIRE DAMAGE	MAKE/MODEL	SIZE	/32
	☐ LF	YOKOHAMA 617	295/75R22.5	14/32	☐ RF	FIRESTONE 591	295/75R22.5	15/32
	☐ LRFO	CASUMINA 852	295/75R22.5	13/32	☐ RFO	CASUMINA 852	295/75R22.5	13/32
	☐ LFI	CASUMINA 852	295/75R22.5	13/32	☐ RFI	CASUMINA 852	295/75R22.5	13/32
	☐ LFFO	CASUMINA 852	295/75R22.5	12/32	☐ RRRO	CASUMINA 852	295/75R22.5	12/32
	☐ LRRI	CASUMINA 852	295/75R22.5	12/32	☐ RRRI	CASUMINA 852	295/75R22.5	12/32

OLD DAMAGE:	RIGHT SIDE FRONT BUMPER AND RIGHT-SIDE FRONT FENDER
COMMENTS:	