


## Claim Photo

**Our File Number:** 285-000701  
**Adjuster:** Kevin Parker  
**Insured:** FedEx Corporation  
**Date of Loss:** 12/03/2025  
**Customer File Number:** 015556-738493-AD-01  
**Policy Number:**




### Photo: 1

**Date Taken:**  
12/31/2025

**Taken By:**  
Kevin Parker

**Description:**  
VIN:  
527SR5328NM028  
064



### Photo: 2


**Date Taken:**  
12/31/2025

**Taken By:**  
Kevin Parker

**Description:**  
VIN label

## Claim Photo

**Our File Number:** 285-000701  
**Adjuster:** Kevin Parker  
**Insured:** FedEx Corporation  
**Date of Loss:** 12/03/2025  
**Customer File Number:** 015556-738493-AD-01  
**Policy Number:**



**Photo: 3**

**Date Taken:**  
12/31/2025

**Taken By:**  
Kevin Parker

**Description:**  
VIN label

**RECORD OF ANNUAL INSPECTION**  
(49 CFR 396.17-23)  
Prepare Separate Report for Each Vehicle Inspected

DATE: 10-17-24  
D10702647

VEHICLE TYPE  
☐ TRUCK ☐ TRACTOR ☒ TRAILER ☐ CONVERTER DOLLY

VEHICLE MAKE: Vanguard MODEL: Reefer YEAR: 2021

ZIP: 50113 VEHICLE IDENTIFICATION (Company No., State Tag No. or VIN): 527SR5328NM028064

EMPLOYEE NO.: 8017

Additional Information on Inspection Procedures see FMCSR Part 396, Appendix A)

	OK	REPAIR		OK	REPAIR		OK	REPAIR
<b>STEERING</b>			<b>FRAME</b>					
Adjustment			Members					
Column/Gear			Clearance					
Axle			Rear Impact Guard					
Linkage			<b>TIRES</b>					
Power Steering			Tread					
Other			Inflation					
<b>FUEL SYSTEM</b>			Damage					
Tank(s)/Cap(s)			Speed Restrictions					
Lines			Other					
			<b>WHEELS</b>					

**Photo: 4**

**Date Taken:**  
12/31/2025

**Taken By:**  
Kevin Parker

**Description:**  
Inspection

## Claim Photo

**Our File Number:** 285-000701  
**Adjuster:** Kevin Parker  
**Insured:** FedEx Corporation  
**Date of Loss:** 12/03/2025  
**Customer File Number:** 015556-738493-AD-01  
**Policy Number:**



**Photo: 5**

**Date Taken:**  
12/31/2025

**Taken By:**  
Kevin Parker

**Description:**  
Inspection



**Photo: 6**

**Date Taken:**  
12/31/2025

**Taken By:**  
Kevin Parker

**Description:**  
Unit 15827

## Claim Photo

**Our File Number:** 285-000701  
**Adjuster:** Kevin Parker  
**Insured:** FedEx Corporation  
**Date of Loss:** 12/03/2025  
**Customer File Number:** 015556-738493-AD-01  
**Policy Number:**



**Photo: 7**

**Date Taken:**  
12/31/2025

**Taken By:**  
Kevin Parker

**Description:**  
Reefer no power



**Photo: 8**

**Date Taken:**  
12/31/2025

**Taken By:**  
Kevin Parker

**Description:**  
Reefer

## Claim Photo

**Our File Number:** 285-000701  
**Adjuster:** Kevin Parker  
**Insured:** FedEx Corporation  
**Date of Loss:** 12/03/2025  
**Customer File Number:** 015556-738493-AD-01  
**Policy Number:**



**Photo: 9**

**Date Taken:**  
12/31/2025

**Taken By:**  
Kevin Parker

**Description:**  
Mkae & model



**Photo: 10**

**Date Taken:**  
12/31/2025

**Taken By:**  
Kevin Parker

**Description:**  
Left front

## Claim Photo

**Our File Number:** 285-000701  
**Adjuster:** Kevin Parker  
**Insured:** FedEx Corporation  
**Date of Loss:** 12/03/2025  
**Customer File Number:** 015556-738493-AD-01  
**Policy Number:**



**Photo: 11**

**Date Taken:**  
12/31/2025

**Taken By:**  
Kevin Parker

**Description:**  
Left rear



**Photo: 12**

**Date Taken:**  
12/31/2025

**Taken By:**  
Kevin Parker

**Description:**  
Righ front

## Claim Photo

**Our File Number:** 285-000701  
**Adjuster:** Kevin Parker  
**Insured:** FedEx Corporation  
**Date of Loss:** 12/03/2025  
**Customer File Number:** 015556-738493-AD-01  
**Policy Number:**



**Photo: 13**

**Date Taken:**  
12/31/2025

**Taken By:**  
Kevin Parker

**Description:**  
Right rear



**Photo: 14**

**Date Taken:**  
12/31/2025

**Taken By:**  
Kevin Parker

**Description:**  
Damage side panels

## Claim Photo

**Our File Number:** 285-000701  
**Adjuster:** Kevin Parker  
**Insured:** FedEx Corporation  
**Date of Loss:** 12/03/2025  
**Customer File Number:** 015556-738493-AD-01  
**Policy Number:**



**Photo: 15**

**Date Taken:**  
12/31/2025

**Taken By:**  
Kevin Parker

**Description:**  
Damage lower rail



**Photo: 16**

**Date Taken:**  
12/31/2025

**Taken By:**  
Kevin Parker

**Description:**  
Damage floor

## Claim Photo

**Our File Number:** 285-000701  
**Adjuster:** Kevin Parker  
**Insured:** FedEx Corporation  
**Date of Loss:** 12/03/2025  
**Customer File Number:** 015556-738493-AD-01  
**Policy Number:**



**Photo: 17**

**Date Taken:**  
12/31/2025

**Taken By:**  
Kevin Parker

**Description:**  
Damage  
crossmembers



**Photo: 18**

**Date Taken:**  
12/31/2025

**Taken By:**  
Kevin Parker

**Description:**  
Damage door frame

## Claim Photo

**Our File Number:** 285-000701  
**Adjuster:** Kevin Parker  
**Insured:** FedEx Corporation  
**Date of Loss:** 12/03/2025  
**Customer File Number:** 015556-738493-AD-01  
**Policy Number:**



**Photo: 19**

**Date Taken:**  
12/31/2025

**Taken By:**  
Kevin Parker

**Description:**  
Damage insulation



**Photo: 20**


**Date Taken:**  
12/31/2025

**Taken By:**  
Kevin Parker

**Description:**  
Damage floor

## Claim Photo

**Our File Number:** 285-000701  
**Adjuster:** Kevin Parker  
**Insured:** FedEx Corporation  
**Date of Loss:** 12/03/2025  
**Customer File Number:** 015556-738493-AD-01  
**Policy Number:**




**Photo: 21**

**Date Taken:**  
12/31/2025

**Taken By:**  
Kevin Parker

**Description:**  
Damage floor



**Photo: 22**


**Date Taken:**  
12/31/2025

**Taken By:**  
Kevin Parker

**Description:**  
Damage roof

## Claim Photo

**Our File Number:** 285-000701  
**Adjuster:** Kevin Parker  
**Insured:** FedEx Corporation  
**Date of Loss:** 12/03/2025  
**Customer File Number:** 015556-738493-AD-01  
**Policy Number:**




**Photo: 23**

**Date Taken:**  
12/31/2025

**Taken By:**  
Kevin Parker

**Description:**  
Damage inner



**Photo: 24**


**Date Taken:**  
12/31/2025

**Taken By:**  
Kevin Parker

**Description:**  
Damage roof  
handling

## Claim Photo

**Our File Number:** 285-000701  
**Adjuster:** Kevin Parker  
**Insured:** FedEx Corporation  
**Date of Loss:** 12/03/2025  
**Customer File Number:** 015556-738493-AD-01  
**Policy Number:**



**Photo: 25**

**Date Taken:**  
12/31/2025

**Taken By:**  
Kevin Parker

**Description:**  
Damage door frame



**Photo: 26**

**Date Taken:**  
12/31/2025

**Taken By:**  
Kevin Parker

**Description:**  
Damage left side

## Claim Photo

**Our File Number:** 285-000701  
**Adjuster:** Kevin Parker  
**Insured:** FedEx Corporation  
**Date of Loss:** 12/03/2025  
**Customer File Number:** 015556-738493-AD-01  
**Policy Number:**



**Photo: 27**

**Date Taken:**  
12/31/2025

**Taken By:**  
Kevin Parker

**Description:**  
Tread depth



**Photo: 28**

**Date Taken:**  
12/31/2025

**Taken By:**  
Kevin Parker

**Description:**  
Tread depth

## Claim Photo

**Our File Number:** 285-000701  
**Adjuster:** Kevin Parker  
**Insured:** FedEx Corporation  
**Date of Loss:** 12/03/2025  
**Customer File Number:** 015556-738493-AD-01  
**Policy Number:**




**Photo: 29**

**Date Taken:**  
12/31/2025

**Taken By:**  
Kevin Parker

**Description:**  
Tread depth



**Photo: 30**

**Date Taken:**  
12/31/2025

**Taken By:**  
Kevin Parker

**Description:**  
Tread depth