

Claim Photo

Our File Number: 277-065239
Adjuster: David Crans
Insured: California Hauling Trucking Corp.
Date of Loss: 11/20/2025
Customer File Number: 2511AT781772
Policy Number:



Photo: 1

Date Taken:
12/05/2025

Taken By:
Adrienne Adame

Description:
VIN label




Photo: 2

Date Taken:
12/05/2025

Taken By:
Adrienne Adame

Description:
Close-up view of
VIN

Claim Photo

Our File Number:

277-065239

Adjuster:

David Crans

Insured:

California Hauling Trucking Corp.

Date of Loss:

11/20/2025

Customer File Number:

2511AT781772

Policy Number:



Photo: 3

Date Taken:
12/05/2025

Taken By:
Adrienne Adame

Description:
License plate



Photo: 4

Date Taken:
12/05/2025

Taken By:
Adrienne Adame

Description:
Gauge

Claim Photo

Our File Number: 277-065239

Adjuster: David Crans

Insured: California Hauling Trucking Corp.

Date of Loss: 11/20/2025

Customer File Number: 2511AT781772

Policy Number:

cia
CUSTARD
INSURANCE ADJUSTERS



Photo: 5

Date Taken:
12/05/2025

Taken By:
Adrienne Adame

Description:
Front view



Photo: 6

Date Taken:
12/05/2025

Taken By:
Adrienne Adame

Description:
Driver-side front view

Claim Photo

Our File Number: 277-065239

Adjuster: David Crans

Insured: California Hauling Trucking Corp.

Date of Loss: 11/20/2025

Customer File Number: 2511AT781772

Policy Number:

cia
CUSTARD
INSURANCE ADJUSTERS



Photo: 7

Date Taken:
12/05/2025

Taken By:
Adrienne Adame

Description:
Driver-side



Photo: 8

Date Taken:
12/05/2025

Taken By:
Adrienne Adame

Description:
Driver-side rear view

Claim Photo

Our File Number: 277-065239

Adjuster: David Crans

Insured: California Hauling Trucking Corp.

Date of Loss: 11/20/2025

Customer File Number: 2511AT781772

Policy Number:

cia
CUSTARD
INSURANCE ADJUSTERS



Photo: 9

Date Taken:
12/05/2025

Taken By:
Adrienne Adame

Description:
Passenger-side
front



Photo: 10

Date Taken:
12/05/2025

Taken By:
Adrienne Adame

Description:
Passenger-side

Claim Photo

Our File Number: 277-065239

Adjuster: David Crans

Insured: California Hauling Trucking Corp.

Date of Loss: 11/20/2025

Customer File Number: 2511AT781772

Policy Number:



Photo: 11

Date Taken:
12/05/2025

Taken By:
Adrienne Adame

Description:
Passenger-side rear



Photo: 12

Date Taken:
12/05/2025

Taken By:
Adrienne Adame

Description:
Rear

Claim Photo

Our File Number: 277-065239
Adjuster: David Crans
Insured: California Hauling Trucking Corp.
Date of Loss: 11/20/2025
Customer File Number: 2511AT781772
Policy Number:



Photo: 13

Date Taken:
12/05/2025

Taken By:
Adrienne Adame

Description:
Driver-side front
damage



Photo: 14

Date Taken:
12/05/2025

Taken By:
Adrienne Adame

Description:
Close-up view of
driver-side front
damage

Claim Photo

Our File Number: 277-065239
Adjuster: David Crans
Insured: California Hauling Trucking Corp.
Date of Loss: 11/20/2025
Customer File Number: 2511AT781772
Policy Number:



Photo: 15

Date Taken:
12/05/2025

Taken By:
Adrienne Adame

Description:
Additional view of
driver-side front
damage




Photo: 16

Date Taken:
12/05/2025

Taken By:
Adrienne Adame

Description:
Driver-side front
damage

Claim Photo

Our File Number: 277-065239

Adjuster: David Crans

Insured: California Hauling Trucking Corp.

Date of Loss: 11/20/2025

Customer File Number: 2511AT781772

Policy Number:

cia
CUSTARD
INSURANCE ADJUSTERS



Photo: 17

Date Taken:
12/05/2025

Taken By:
Adrienne Adame

Description:
Close-up view of
driver-side front
damage



Photo: 18

Date Taken:
12/05/2025

Taken By:
Adrienne Adame

Description:
Additional view of
driver-side front
damage

Claim Photo

Our File Number: 277-065239

Adjuster: David Crans

Insured: California Hauling Trucking Corp.

Date of Loss: 11/20/2025

Customer File Number: 2511AT781772

Policy Number:

cia
CUSTARD
INSURANCE ADJUSTERS



Photo: 19

Date Taken:
12/05/2025

Taken By:
Adrienne Adame

Description:
Close-up view of
driver-side front
damage




Photo: 20

Date Taken:
12/05/2025

Taken By:
Adrienne Adame

Description:
Driver-side front
damage

Claim Photo

Our File Number: 277-065239

Adjuster: David Crans

Insured: California Hauling Trucking Corp.

Date of Loss: 11/20/2025

Customer File Number: 2511AT781772

Policy Number:

cia
CUSTARD
INSURANCE ADJUSTERS



Photo: 21

Date Taken:
12/05/2025

Taken By:
Adrienne Adame

Description:
Additional driver-side front damage



Photo: 22

Date Taken:
12/05/2025

Taken By:
Adrienne Adame

Description:
Driver-side damage

Claim Photo

Our File Number: 277-065239
Adjuster: David Crans
Insured: California Hauling Trucking Corp.
Date of Loss: 11/20/2025
Customer File Number: 2511AT781772
Policy Number:



Photo: 23

Date Taken:
12/05/2025

Taken By:
Adrienne Adame

Description:
Additional driver-side damage



Photo: 24

Date Taken:
12/05/2025

Taken By:
Adrienne Adame

Description:
Additional driver-side damage

Claim Photo

Our File Number: 277-065239

Adjuster: David Crans

Insured: California Hauling Trucking Corp.

Date of Loss: 11/20/2025

Customer File Number: 2511AT781772

Policy Number:

cia
CUSTARD
INSURANCE ADJUSTERS



Photo: 25

Date Taken:
12/05/2025

Taken By:
Adrienne Adame

Description:
Additional driver-side damage



Photo: 26

Date Taken:
12/05/2025

Taken By:
Adrienne Adame

Description:
Additional view of driver-side damage

Claim Photo

Our File Number: 277-065239

Adjuster: David Crans

Insured: California Hauling Trucking Corp.

Date of Loss: 11/20/2025

Customer File Number: 2511AT781772

Policy Number:

cia
CUSTARD
INSURANCE ADJUSTERS



Photo: 27

Date Taken:
12/05/2025

Taken By:
Adrienne Adame

Description:
Additional view of
driver-side damage



Photo: 28

Date Taken:
12/05/2025

Taken By:
Adrienne Adame

Description:
Additional view of
driver-side damage

Claim Photo

Our File Number: 277-065239
Adjuster: David Crans
Insured: California Hauling Trucking Corp.
Date of Loss: 11/20/2025
Customer File Number: 2511AT781772
Policy Number:




Photo: 29

Date Taken:
12/05/2025

Taken By:
Adrienne Adame

Description:
Close-up view of
driver-side damage



Photo: 30

Date Taken:
12/05/2025

Taken By:
Adrienne Adame

Description:
Additional driver-
side damage

Claim Photo

Our File Number: 277-065239
Adjuster: David Crans
Insured: California Hauling Trucking Corp.
Date of Loss: 11/20/2025
Customer File Number: 2511AT781772
Policy Number:



Photo: 31

Date Taken:
12/05/2025

Taken By:
Adrienne Adame

Description:
Additional driver-side damage



Photo: 32

Date Taken:
12/05/2025

Taken By:
Adrienne Adame

Description:
Additional driver-side damage

Claim Photo

Our File Number: 277-065239

Adjuster: David Crans

Insured: California Hauling Trucking Corp.

Date of Loss: 11/20/2025

Customer File Number: 2511AT781772

Policy Number:

cia
CUSTARD
INSURANCE ADJUSTERS



Photo: 33

Date Taken:
12/05/2025

Taken By:
Adrienne Adame

Description:
Additional driver-side damage



Photo: 34

Date Taken:
12/05/2025

Taken By:
Adrienne Adame

Description:
Additional view of driver-side damage

Claim Photo

Our File Number: 277-065239

Adjuster: David Crans

Insured: California Hauling Trucking Corp.

Date of Loss: 11/20/2025

Customer File Number: 2511AT781772

Policy Number:



Photo: 35

Date Taken:
12/05/2025

Taken By:
Adrianne Adame

Description:
Driver-side rear
damage



Photo: 36

Date Taken:
12/05/2025

Taken By:
Adrianne Adame

Description:
Close-up view of
driver-side rear
damage

Claim Photo

Our File Number: 277-065239
Adjuster: David Crans
Insured: California Hauling Trucking Corp.
Date of Loss: 11/20/2025
Customer File Number: 2511AT781772
Policy Number:



Photo: 37

Date Taken:
12/05/2025

Taken By:
Adrienne Adame

Description:
Additional close-up view of driver-side rear damage



Photo: 38

Date Taken:
12/05/2025

Taken By:
Adrienne Adame

Description:
Additional close-up view of driver-side rear damage

Claim Photo

Our File Number: 277-065239

Adjuster: David Crans

Insured: California Hauling Trucking Corp.

Date of Loss: 11/20/2025

Customer File Number: 2511AT781772

Policy Number:

cia
CUSTARD
INSURANCE ADJUSTERS



Photo: 39

Date Taken:
12/05/2025

Taken By:
Adrienne Adame

Description:
Additional view of
driver-side rear
damage



Photo: 40

Date Taken:
12/05/2025

Taken By:
Adrienne Adame

Description:
View of under
carriage damage

Claim Photo

Our File Number: 277-065239

Adjuster: David Crans

Insured: California Hauling Trucking Corp.

Date of Loss: 11/20/2025

Customer File Number: 2511AT781772

Policy Number:

cia
CUSTARD
INSURANCE ADJUSTERS



Photo: 41

Date Taken:
12/05/2025

Taken By:
Adrienne Adame

Description:
Driver-side view of
under carriage
damage



Photo: 42

Date Taken:
12/05/2025

Taken By:
Adrienne Adame

Description:
Driver-side view of
under carriage
damage

Claim Photo

Our File Number: 277-065239

Adjuster: David Crans

Insured: California Hauling Trucking Corp.

Date of Loss: 11/20/2025

Customer File Number: 2511AT781772

Policy Number:



Photo: 43

Date Taken:
12/05/2025

Taken By:
Adrienne Adame

Description:
Driver-side view of
under carriage
damage



Photo: 44

Date Taken:
12/05/2025

Taken By:
Adrienne Adame

Description:
Additional view of
driver-side under
carriage damage

Claim Photo

Our File Number: 277-065239

Adjuster: David Crans

Insured: California Hauling Trucking Corp.

Date of Loss: 11/20/2025

Customer File Number: 2511AT781772

Policy Number:



Photo: 45

Date Taken:
12/05/2025

Taken By:
Adrienne Adame

Description:
Additional driver-side view of under carriage damage



Photo: 46

Date Taken:
12/05/2025

Taken By:
Adrienne Adame

Description:
Additional view of driver-side view of under carriage damage

Claim Photo

Our File Number: 277-065239

Adjuster: David Crans

Insured: California Hauling Trucking Corp.

Date of Loss: 11/20/2025

Customer File Number: 2511AT781772

Policy Number:



Photo: 47

Date Taken:
12/05/2025

Taken By:
Adrianne Adame

Description:
Additional view of
driver-side view of
under carriage
damage



Photo: 48

Date Taken:
12/05/2025

Taken By:
Adrianne Adame

Description:
Close-up view of
driver-side under
carriage damage

Claim Photo

Our File Number: 277-065239

Adjuster: David Crans

Insured: California Hauling Trucking Corp.

Date of Loss: 11/20/2025

Customer File Number: 2511AT781772

Policy Number:

cia
CUSTARD
INSURANCE ADJUSTERS



Photo: 49

Date Taken:
12/05/2025

Taken By:
Adrienne Adame

Description:
Passenger-side
front damage



Photo: 50

Date Taken:
12/05/2025

Taken By:
Adrienne Adame

Description:
Close-up view of
passenger-side
front damage

Claim Photo

Our File Number: 277-065239
Adjuster: David Crans
Insured: California Hauling Trucking Corp.
Date of Loss: 11/20/2025
Customer File Number: 2511AT781772
Policy Number:



Photo: 51

Date Taken:
12/05/2025

Taken By:
Adrienne Adame

Description:
Additional view of
passenger-side
front damage



Photo: 52

Date Taken:
12/05/2025

Taken By:
Adrienne Adame

Description:
Additional view of
passenger-side
front damage

Claim Photo

Our File Number: 277-065239

Adjuster: David Crans

Insured: California Hauling Trucking Corp.

Date of Loss: 11/20/2025

Customer File Number: 2511AT781772

Policy Number:

cia
CUSTARD
INSURANCE ADJUSTERS



Photo: 53

Date Taken:
12/05/2025

Taken By:
Adrienne Adame

Description:
Additional view of
passenger-side
front damage



Photo: 54

Date Taken:
12/05/2025

Taken By:
Adrienne Adame

Description:
Close-up view of
passenger-side
front damage

Claim Photo

Our File Number:

277-065239

Adjuster:

David Crans

Insured:

California Hauling Trucking Corp.

Date of Loss:

11/20/2025

Customer File Number:

2511AT781772

Policy Number:

cia
CUSTARD
INSURANCE ADJUSTERS



Photo: 55

Date Taken:
12/05/2025

Taken By:
Adrienne Adame

Description:
Additional view of
passenger-side
front damage



Photo: 56

Date Taken:
12/05/2025

Taken By:
Adrienne Adame

Description:
Close-up view of
passenger-side
front damage

Claim Photo

Our File Number: 277-065239
Adjuster: David Crans
Insured: California Hauling Trucking Corp.
Date of Loss: 11/20/2025
Customer File Number: 2511AT781772
Policy Number:



Photo: 57

Date Taken:
12/05/2025

Taken By:
Adrienne Adame

Description:
Additional close-up view of passenger-side front damage



Photo: 58

Date Taken:
12/05/2025

Taken By:
Adrienne Adame

Description:
Passenger-side front damage

Claim Photo

Our File Number: 277-065239

Adjuster: David Crans

Insured: California Hauling Trucking Corp.

Date of Loss: 11/20/2025

Customer File Number: 2511AT781772

Policy Number:



Photo: 59

Date Taken:
12/05/2025

Taken By:
Adrienne Adame

Description:
Passenger-side
damage



Photo: 60

Date Taken:
12/05/2025

Taken By:
Adrienne Adame

Description:
Additional
passenger-side
damage

Claim Photo

Our File Number: 277-065239

Adjuster: David Crans

Insured: California Hauling Trucking Corp.

Date of Loss: 11/20/2025

Customer File Number: 2511AT781772

Policy Number:

cia
CUSTARD
INSURANCE ADJUSTERS



Photo: 61

Date Taken:
12/05/2025

Taken By:
Adrienne Adame

Description:
Additional
passenger-side
damage



Photo: 62

Date Taken:
12/05/2025

Taken By:
Adrienne Adame

Description:
Additional
passenger-side
damage

Claim Photo

Our File Number:

277-065239

Adjuster:

David Crans

Insured:

California Hauling Trucking Corp.

Date of Loss:

11/20/2025

Customer File Number:

2511AT781772

Policy Number:

cia
CUSTARD
INSURANCE ADJUSTERS



Photo: 63

Date Taken:
12/05/2025

Taken By:
Adrianne Adame

Description:
Additional
passenger-side
damage



Photo: 64

Date Taken:
12/05/2025

Taken By:
Adrianne Adame

Description:
Additional
passenger-side
damage

Claim Photo

Our File Number:

277-065239

Adjuster:

David Crans

Insured:

California Hauling Trucking Corp.

Date of Loss:

11/20/2025

Customer File Number:

2511AT781772

Policy Number:

cia
CUSTARD
INSURANCE ADJUSTERS



Photo: 65

Date Taken:
12/05/2025

Taken By:
Adrienne Adame

Description:
Additional
passenger-side
damage



Photo: 66

Date Taken:
12/05/2025

Taken By:
Adrienne Adame

Description:
Close-up view of
passenger-side
damage

Claim Photo

Our File Number:

277-065239

Adjuster:

David Crans

Insured:

California Hauling Trucking Corp.

Date of Loss:

11/20/2025

Customer File Number:

2511AT781772

Policy Number:

cia
CUSTARD
INSURANCE ADJUSTERS



Photo: 67

Date Taken:
12/05/2025

Taken By:
Adrienne Adame

Description:
Passenger-side view of interior damage of trailer



Photo: 68

Date Taken:
12/05/2025

Taken By:
Adrienne Adame

Description:
Additional view of passenger-side interior damage

Claim Photo

Our File Number: 277-065239
Adjuster: David Crans
Insured: California Hauling Trucking Corp.
Date of Loss: 11/20/2025
Customer File Number: 2511AT781772
Policy Number:

cia
CUSTARD
INSURANCE ADJUSTERS



Photo: 69

Date Taken:
12/05/2025

Taken By:
Adrianne Adame

Description:
Additional
passenger-side
damage




Photo: 70

Date Taken:
12/05/2025

Taken By:
Adrianne Adame

Description:
Additional
passenger-side
damage

Claim Photo

Our File Number: 277-065239
Adjuster: David Crans
Insured: California Hauling Trucking Corp.
Date of Loss: 11/20/2025
Customer File Number: 2511AT781772
Policy Number:




Photo: 71

Date Taken:
12/05/2025

Taken By:
Adrienne Adame

Description:
Additional
passenger-side
damage



Photo: 72

Date Taken:
12/05/2025

Taken By:
Adrienne Adame

Description:
Additional
passenger-side
damage

Claim Photo

Our File Number: 277-065239
Adjuster: David Crans
Insured: California Hauling Trucking Corp.
Date of Loss: 11/20/2025
Customer File Number: 2511AT781772
Policy Number:



Photo: 73

Date Taken:
12/05/2025

Taken By:
Adrienne Adame

Description:
Additional
passenger-side
damage



Photo: 74

Date Taken:
12/05/2025

Taken By:
Adrienne Adame

Description:
Additional
passenger-side
damage

Claim Photo

Our File Number: 277-065239

Adjuster: David Crans

Insured: California Hauling Trucking Corp.

Date of Loss: 11/20/2025

Customer File Number: 2511AT781772

Policy Number:



Photo: 75

Date Taken:
12/05/2025

Taken By:
Adrienne Adame

Description:
Close-up view of passenger-side damage



Photo: 76

Date Taken:
12/05/2025

Taken By:
Adrienne Adame

Description:
Additional passenger-side damage

Claim Photo

Our File Number: 277-065239
Adjuster: David Crans
Insured: California Hauling Trucking Corp.
Date of Loss: 11/20/2025
Customer File Number: 2511AT781772
Policy Number:



Photo: 77

Date Taken:
12/05/2025

Taken By:
Adrienne Adame

Description:
Passenger-side rear
damage



Photo: 78

Date Taken:
12/05/2025

Taken By:
Adrienne Adame

Description:
Passenger-side
under carriage
damage

Claim Photo

Our File Number: 277-065239

Adjuster: David Crans

Insured: California Hauling Trucking Corp.

Date of Loss: 11/20/2025

Customer File Number: 2511AT781772

Policy Number:

cia
CUSTARD
INSURANCE ADJUSTERS



Photo: 79

Date Taken:
12/05/2025

Taken By:
Adrienne Adame

Description:
Additional view of
passenger-side
under carriage
damage



Photo: 80

Date Taken:
12/05/2025

Taken By:
Adrienne Adame

Description:
Additional
passenger-side
under carriage
damage

Claim Photo

Our File Number: 277-065239
Adjuster: David Crans
Insured: California Hauling Trucking Corp.
Date of Loss: 11/20/2025
Customer File Number: 2511AT781772
Policy Number:

cia
CUSTARD
INSURANCE ADJUSTERS



Photo: 81

Date Taken:
12/05/2025

Taken By:
Adrienne Adame

Description:
Additional view of passenger-side under carriage damage



Photo: 82

Date Taken:
12/05/2025

Taken By:
Adrienne Adame

Description:
Driver-side rear damage

Claim Photo

Our File Number: 277-065239
Adjuster: David Crans
Insured: California Hauling Trucking Corp.
Date of Loss: 11/20/2025
Customer File Number: 2511AT781772
Policy Number:



Photo: 83

Date Taken:
12/05/2025

Taken By:
Adrianne Adame

Description:
Close-up view of
driver-side rear
damage



Photo: 84

Date Taken:
12/05/2025

Taken By:
Adrianne Adame

Description:
Additional view of
driver-side rear
damage

Claim Photo

Our File Number: 277-065239
Adjuster: David Crans
Insured: California Hauling Trucking Corp.
Date of Loss: 11/20/2025
Customer File Number: 2511AT781772
Policy Number:



Photo: 85

Date Taken:
12/05/2025

Taken By:
Adrienne Adame

Description:
Close-up view of
driver-side rear
damage



Photo: 86

Date Taken:
12/05/2025

Taken By:
Adrienne Adame

Description:
Close-up view of
driver-side damage

Claim Photo

Our File Number: 277-065239
Adjuster: David Crans
Insured: California Hauling Trucking Corp.
Date of Loss: 11/20/2025
Customer File Number: 2511AT781772
Policy Number:



Photo: 87

Date Taken:
12/05/2025

Taken By:
Adrienne Adame

Description:
View of rear
damage



Photo: 88

Date Taken:
12/05/2025

Taken By:
Adrienne Adame

Description:
Close-up view of
rear damage

Claim Photo

Our File Number: 277-065239
Adjuster: David Crans
Insured: California Hauling Trucking Corp.
Date of Loss: 11/20/2025
Customer File Number: 2511AT781772
Policy Number:



Photo: 89

Date Taken:
12/05/2025

Taken By:
Adrienne Adame

Description:
Additional view of
rear damage



Photo: 90

Date Taken:
12/05/2025

Taken By:
Adrienne Adame

Description:
Additional rear
damage

Claim Photo

Our File Number: 277-065239

Adjuster: David Crans

Insured: California Hauling Trucking Corp.

Date of Loss: 11/20/2025

Customer File Number: 2511AT781772

Policy Number:



Photo: 91

Date Taken:
12/05/2025

Taken By:
Adrienne Adame

Description:
Additional rear
damage



Photo: 92

Date Taken:
12/05/2025

Taken By:
Adrienne Adame

Description:
Passenger-side rear
damage

Claim Photo

Our File Number: 277-065239
Adjuster: David Crans
Insured: California Hauling Trucking Corp.
Date of Loss: 11/20/2025
Customer File Number: 2511AT781772
Policy Number:



Photo: 93

Date Taken:
12/05/2025

Taken By:
Adrienne Adame

Description:
Additional view of passenger-side rear damage



Photo: 94

Date Taken:
12/05/2025

Taken By:
Adrienne Adame

Description:
Close-up view of passenger-side rear damage

Claim Photo

Our File Number: 277-065239
Adjuster: David Crans
Insured: California Hauling Trucking Corp.
Date of Loss: 11/20/2025
Customer File Number: 2511AT781772
Policy Number:



Photo: 95

Date Taken:
12/05/2025

Taken By:
Adrienne Adame

Description:
Close-up view of passenger-side rear damage




Photo: 96

Date Taken:
12/05/2025

Taken By:
Adrienne Adame

Description:
Close-up view of passenger-side rear damage

Claim Photo

Our File Number:

277-065239

Adjuster:

David Crans

Insured:

California Hauling Trucking Corp.

Date of Loss:

11/20/2025

Customer File Number:

2511AT781772

Policy Number:

cia
CUSTARD
INSURANCE ADJUSTERS



Photo: 97

Date Taken:
12/05/2025

Taken By:
Adrienne Adame

Description:
Additional view of
rear damage



Photo: 98

Date Taken:
12/05/2025

Taken By:
Adrienne Adame

Description:
Close-up view of
driver-side rear
mud flap

Claim Photo

Our File Number: 277-065239

Adjuster: David Crans

Insured: California Hauling Trucking Corp.

Date of Loss: 11/20/2025

Customer File Number: 2511AT781772

Policy Number:

cia
CUSTARD
INSURANCE ADJUSTERS



Photo: 99

Date Taken:
12/05/2025

Taken By:
Adrienne Adame

Description:
Close-up view of passenger-side rear mud flap



Photo: 100

Date Taken:
12/05/2025

Taken By:
Adrienne Adame

Description:
View of damage rear doors

Claim Photo

Our File Number: 277-065239

Adjuster: David Crans

Insured: California Hauling Trucking Corp.

Date of Loss: 11/20/2025

Customer File Number: 2511AT781772

Policy Number:

cia
CUSTARD
INSURANCE ADJUSTERS



Photo: 101

Date Taken:
12/05/2025

Taken By:
Adrienne Adame

Description:
Additional view of
driver-side rear
door damage



Photo: 102

Date Taken:
12/05/2025

Taken By:
Adrienne Adame

Description:
View of trailer
interior

Claim Photo

Our File Number: 277-065239

Adjuster: David Crans

Insured: California Hauling Trucking Corp.

Date of Loss: 11/20/2025

Customer File Number: 2511AT781772

Policy Number:

cia
CUSTARD
INSURANCE ADJUSTERS



Photo: 103

Date Taken:
12/05/2025

Taken By:
Adrienne Adame

Description:
Additional driver-side rear damage



Photo: 104

Date Taken:
12/05/2025

Taken By:
Adrienne Adame

Description:
View of interior floor

Claim Photo

Our File Number: 277-065239
Adjuster: David Crans
Insured: California Hauling Trucking Corp.
Date of Loss: 11/20/2025
Customer File Number: 2511AT781772
Policy Number:



Photo: 105

Date Taken:
12/05/2025

Taken By:
Adrianne Adame

Description:
View of trailer interior roof



Photo: 106

Date Taken:
12/05/2025

Taken By:
Adrianne Adame

Description:
Additional view of passenger-side rear door

Claim Photo

Our File Number: 277-065239

Adjuster: David Crans

Insured: California Hauling Trucking Corp.

Date of Loss: 11/20/2025

Customer File Number: 2511AT781772

Policy Number:



Photo: 107

Date Taken:
12/05/2025

Taken By:
Adrienne Adame

Description:
Driver-side rear
tires



Photo: 108

Date Taken:
12/05/2025

Taken By:
Adrienne Adame

Description:
View between
Driver-side rear
tires

Claim Photo

Our File Number: 277-065239

Adjuster: David Crans

Insured: California Hauling Trucking Corp.

Date of Loss: 11/20/2025

Customer File Number: 2511AT781772

Policy Number:



Photo: 109

Date Taken:
12/05/2025

Taken By:
Adrienne Adame

Description:
Close-up view of
driver-side rear
tires (1st set)



Photo: 110

Date Taken:
12/05/2025

Taken By:
Adrienne Adame

Description:
Driver-side rear
tires (1st set) out -
Tread depth
measurement:
08/32

Claim Photo

Our File Number: 277-065239
Adjuster: David Crans
Insured: California Hauling Trucking Corp.
Date of Loss: 11/20/2025
Customer File Number: 2511AT781772
Policy Number:



Photo: 111

Date Taken:
12/05/2025

Taken By:
Adrienne Adame

Description:
Driver-side rear
tires (1st set) in -
Tread depth
measurement:
03/32



Photo: 112

Date Taken:
12/05/2025

Taken By:
Adrienne Adame

Description:
Driver-side rear
tires (2nd set)

Claim Photo

Our File Number: 277-065239

Adjuster: David Crans

Insured: California Hauling Trucking Corp.

Date of Loss: 11/20/2025

Customer File Number: 2511AT781772

Policy Number:



Photo: 113

Date Taken:
12/05/2025

Taken By:
Adrianne Adame

Description:
Close-up view of
driver-side rear
tires (2nd set)



Photo: 114

Date Taken:
12/05/2025

Taken By:
Adrianne Adame

Description:
Driver-side rear
tires (2nd set) out -
Tread depth
measurement:
03/32

Claim Photo

Our File Number: 277-065239
Adjuster: David Crans
Insured: California Hauling Trucking Corp.
Date of Loss: 11/20/2025
Customer File Number: 2511AT781772
Policy Number:



Photo: 115

Date Taken:
12/05/2025

Taken By:
Adrienne Adame

Description:
Driver-side rear tires (2nd set) in -
Tread depth measurement:
04/32



Photo: 116

Date Taken:
12/05/2025

Taken By:
Adrienne Adame

Description:
View of passenger-side rear tires

Claim Photo

Our File Number: 277-065239

Adjuster: David Crans

Insured: California Hauling Trucking Corp.

Date of Loss: 11/20/2025

Customer File Number: 2511AT781772

Policy Number:



Photo: 117

Date Taken:
12/05/2025

Taken By:
Adrienne Adame

Description:
View between
passenger-side rear
tires



Photo: 118

Date Taken:
12/05/2025

Taken By:
Adrienne Adame

Description:
Close-up view of
passenger-side rear
tires (1st set)

Claim Photo

Our File Number: 277-065239

Adjuster: David Crans

Insured: California Hauling Trucking Corp.

Date of Loss: 11/20/2025

Customer File Number: 2511AT781772

Policy Number:

cia
CUSTARD
INSURANCE ADJUSTERS



Photo: 119

Date Taken:
12/05/2025

Taken By:
Adrienne Adame

Description:
Passenger-side rear
tires (1st set) out -
Tread depth
measurement:
06/32



Photo: 120

Date Taken:
12/05/2025

Taken By:
Adrienne Adame

Description:
Passenger-side rear
tires (1st set) in -
Tread depth
measurement:
02/32

Claim Photo

Our File Number: 277-065239
Adjuster: David Crans
Insured: California Hauling Trucking Corp.
Date of Loss: 11/20/2025
Customer File Number: 2511AT781772
Policy Number:



Photo: 121

Date Taken:
12/05/2025

Taken By:
Adrienne Adame

Description:
Passenger-side rear
tires (2nd set)



Photo: 122

Date Taken:
12/05/2025

Taken By:
Adrienne Adame

Description:
Close-up view of
passenger-side rear
tires (2nd set)

Claim Photo

Our File Number: 277-065239

Adjuster: David Crans

Insured: California Hauling Trucking Corp.

Date of Loss: 11/20/2025

Customer File Number: 2511AT781772

Policy Number:



Photo: 123

Date Taken:
12/05/2025

Taken By:
Adrienne Adame

Description:
Passenger-side rear
tires (2nd set) out -
Tread depth
measurement:
14/32



Photo: 124

Date Taken:
12/05/2025

Taken By:
Adrienne Adame

Description:
Passenger-side rear
tires (2nd set) in -
Tread depth
measurement:
12/32

Claim Photo

Our File Number: 277-065239
Adjuster: David Crans
Insured: California Hauling Trucking Corp.
Date of Loss: 11/20/2025
Customer File Number: 2511AT781772
Policy Number:



Photo: 125

Date Taken:
12/05/2025

Taken By:
Adrianne Adame

Description:
View of driver-side
rear tire drum
brakes