

Claim Photo

Our File Number: 297-018741
Adjuster: Scott Syner
Insured: Nunn Transportation and Delivery
Date of Loss: 02/06/2026
Customer File Number: BRIT-0125
Policy Number:



Photo: 1

Date Taken:
02/11/2026

Taken By:
Client

Description:



Photo: 2

Date Taken:
02/11/2026

Taken By:
Client

Description:

Claim Photo

Our File Number: 297-018741
Adjuster: Scott Syner
Insured: Nunn Transportation and Delivery
Date of Loss: 02/06/2026
Customer File Number: BRIT-0125
Policy Number:



Photo: 3

Date Taken:
02/16/2026

Taken By:
Travis Tellez

Description:
LT front




Photo: 4

Date Taken:
02/16/2026

Taken By:
Travis Tellez

Description:
RT front

Claim Photo

Our File Number: 297-018741
Adjuster: Scott Syner
Insured: Nunn Transportation and Delivery
Date of Loss: 02/06/2026
Customer File Number: BRIT-0125
Policy Number:




Photo: 5

Date Taken:
02/16/2026

Taken By:
Travis Tellez

Description:
RT rear




Photo: 6

Date Taken:
02/16/2026

Taken By:
Travis Tellez

Description:
LT rear

Claim Photo

Our File Number: 297-018741
Adjuster: Scott Syner
Insured: Nunn Transportation and Delivery
Date of Loss: 02/06/2026
Customer File Number: BRIT-0125
Policy Number:




Photo: 7
Date Taken: 02/16/2026
Taken By: Travis Tellez
Description: VIN tag



Photo: 8
Date Taken: 02/16/2026
Taken By: Travis Tellez
Description: Mileage estimate

Claim Photo

Our File Number: 297-018741
Adjuster: Scott Syner
Insured: Nunn Transportation and Delivery
Date of Loss: 02/06/2026
Customer File Number: BRIT-0125
Policy Number:



Photo: 9
Date Taken: 02/16/2026
Taken By: Travis Tellez
Description: Info label




Photo: 10
Date Taken: 02/16/2026
Taken By: Travis Tellez
Description: Info label

Claim Photo

Our File Number: 297-018741
Adjuster: Scott Syner
Insured: Nunn Transportation and Delivery
Date of Loss: 02/06/2026
Customer File Number: BRIT-0125
Policy Number:



Photo: 11

Date Taken:
02/16/2026

Taken By:
Travis Tellez

Description:
Shift lever




Photo: 12

Date Taken:
02/16/2026

Taken By:
Travis Tellez

Description:
Passenger interior

Claim Photo

Our File Number: 297-018741
Adjuster: Scott Syner
Insured: Nunn Transportation and Delivery
Date of Loss: 02/06/2026
Customer File Number: BRIT-0125
Policy Number:



Photo: 13

Date Taken:
02/16/2026

Taken By:
Travis Tellez

Description:
RT rear cabin




Photo: 14

Date Taken:
02/16/2026

Taken By:
Travis Tellez

Description:
LT rear cabin

Claim Photo

Our File Number: 297-018741
Adjuster: Scott Syner
Insured: Nunn Transportation and Delivery
Date of Loss: 02/06/2026
Customer File Number: BRIT-0125
Policy Number:



Photo: 15

Date Taken:
02/16/2026

Taken By:
Travis Tellez

Description:
Front damage



Photo: 16

Date Taken:
02/16/2026

Taken By:
Travis Tellez

Description:
RT front damage

Claim Photo

Our File Number: 297-018741
Adjuster: Scott Syner
Insured: Nunn Transportation and Delivery
Date of Loss: 02/06/2026
Customer File Number: BRIT-0125
Policy Number:




Photo: 17

Date Taken:
02/16/2026

Taken By:
Travis Tellez

Description:
RT front damage




Photo: 18

Date Taken:
02/16/2026

Taken By:
Travis Tellez

Description:
RT front damage

Claim Photo

Our File Number: 297-018741
Adjuster: Scott Syner
Insured: Nunn Transportation and Delivery
Date of Loss: 02/06/2026
Customer File Number: BRIT-0125
Policy Number:



Photo: 19

Date Taken:
02/16/2026

Taken By:
Travis Tellez

Description:
RT front damage




Photo: 20

Date Taken:
02/16/2026

Taken By:
Travis Tellez

Description:
RT rear tire/rims

Claim Photo

Our File Number: 297-018741
Adjuster: Scott Syner
Insured: Nunn Transportation and Delivery
Date of Loss: 02/06/2026
Customer File Number: BRIT-0125
Policy Number:



Photo: 21

Date Taken:
02/16/2026

Taken By:
Travis Tellez

Description:
Rear axle




Photo: 22

Date Taken:
02/16/2026

Taken By:
Travis Tellez

Description:
Rear axle

Claim Photo

Our File Number: 297-018741
Adjuster: Scott Syner
Insured: Nunn Transportation and Delivery
Date of Loss: 02/06/2026
Customer File Number: BRIT-0125
Policy Number:



Photo: 23

Date Taken:
02/16/2026

Taken By:
Travis Tellez

Description:
LT rear tire/rims




Photo: 24

Date Taken:
02/16/2026

Taken By:
Travis Tellez

Description:
LT front damage

Claim Photo

Our File Number: 297-018741
Adjuster: Scott Syner
Insured: Nunn Transportation and Delivery
Date of Loss: 02/06/2026
Customer File Number: BRIT-0125
Policy Number:



Photo: 25

Date Taken:
02/16/2026

Taken By:
Travis Tellez

Description:
LT front damage




Photo: 26

Date Taken:
02/16/2026

Taken By:
Travis Tellez

Description:
LT engine
compartment

Claim Photo

Our File Number: 297-018741
Adjuster: Scott Syner
Insured: Nunn Transportation and Delivery
Date of Loss: 02/06/2026
Customer File Number: BRIT-0125
Policy Number:



Photo: 27

Date Taken:
02/16/2026

Taken By:
Travis Tellez

Description:
LT engine
compartment




Photo: 28

Date Taken:
02/16/2026

Taken By:
Travis Tellez

Description:
RT engine
compartment

Claim Photo

Our File Number: 297-018741
Adjuster: Scott Syner
Insured: Nunn Transportation and Delivery
Date of Loss: 02/06/2026
Customer File Number: BRIT-0125
Policy Number:




Photo: 29

Date Taken:
02/16/2026

Taken By:
Travis Tellez

Description:
RT engine
compartment



Photo: 30

Date Taken:
02/16/2026

Taken By:
Travis Tellez

Description:
RT front rim
damage

Claim Photo

Our File Number: 297-018741
Adjuster: Scott Syner
Insured: Nunn Transportation and Delivery
Date of Loss: 02/06/2026
Customer File Number: BRIT-0125
Policy Number:



Photo: 31

Date Taken:
02/16/2026

Taken By:
Travis Tellez

Description:
RT front steering
damage



Photo: 32

Date Taken:
02/16/2026

Taken By:
Travis Tellez

Description:
RT front steering
damage

Claim Photo

Our File Number: 297-018741
Adjuster: Scott Syner
Insured: Nunn Transportation and Delivery
Date of Loss: 02/06/2026
Customer File Number: BRIT-0125
Policy Number:



Photo: 33

Date Taken:
02/16/2026

Taken By:
Travis Tellez

Description:
LT front tire
reading 11/32



Photo: 34

Date Taken:
02/16/2026

Taken By:
Travis Tellez

Description:
LT fwd rear tire
reading 12/32

Claim Photo

Our File Number: 297-018741
Adjuster: Scott Syner
Insured: Nunn Transportation and Delivery
Date of Loss: 02/06/2026
Customer File Number: BRIT-0125
Policy Number:



Photo: 35

Date Taken:
02/16/2026

Taken By:
Travis Tellez

Description:
LT fwd rear inboard
tire reading 12/32



Photo: 36

Date Taken:
02/16/2026

Taken By:
Travis Tellez

Description:
LT rear inboard tire
reading 09/32

Claim Photo

Our File Number: 297-018741
Adjuster: Scott Syner
Insured: Nunn Transportation and Delivery
Date of Loss: 02/06/2026
Customer File Number: BRIT-0125
Policy Number:



Photo: 37

Date Taken:
02/16/2026

Taken By:
Travis Tellez

Description:
RT rear tire reading
07/32



Photo: 38

Date Taken:
02/16/2026

Taken By:
Travis Tellez

Description:
RT fwd rear
inboard tire reading
15/32

Claim Photo

Our File Number: 297-018741
Adjuster: Scott Syner
Insured: Nunn Transportation and Delivery
Date of Loss: 02/06/2026
Customer File Number: BRIT-0125
Policy Number:



Photo: 39

Date Taken:
02/16/2026

Taken By:
Travis Tellez

Description:
LT front tire
damage