

VIN of 2018 CAT Skid Steer . One image provided by Mr. Sellers, as arm was blocking my view of sticker



VIN of 2018 CAT Skid Steer . One image provided by Mr. Sellers, as arm was blocking my view of sticker



VIN of 2018 CAT Skid Steer . One image provided by Mr. Sellers, as arm was blocking my view of sticker





Driver side of vehicle of 2018 CAT Skid Steer .





Driver side of vehicle of 2018 CAT Skid Steer .





Driver side of vehicle of 2018 CAT Skid Steer .





Passenger side of vehicle of 2018 CAT Skid Steer .





Passenger side of vehicle of 2018 CAT Skid Steer .





Passenger side of vehicle of 2018 CAT Skid Steer .





Front of vehicle of 2018 CAT Skid Steer .





Rear of vehicle of 2018 CAT Skid Steer .





Wheels of 2018 CAT Skid Steer .





Wheels of 2018 CAT Skid Steer .





Wheels of 2018 CAT Skid Steer .





Wheels of 2018 CAT Skid Steer .





Wheels of 2018 CAT Skid Steer . Best views of undercarriage I could obtain.





Wheels of 2018 CAT Skid Steer . Best views of undercarriage I could obtain.





Wheels of 2018 CAT Skid Steer . Best views of undercarriage I could obtain.





Seat, dashboard, gear shifter, paint condition of 2018 CAT Skid Steer . Cab interior photos.





Seat, dashboard, gear shifter, paint condition of 2018 CAT Skid Steer . Cab interior photos.





Seat, dashboard, gear shifter, paint condition of 2018 CAT Skid Steer . Cab interior photos.





Damage noted to rear of vehicle of 2018 CAT Skid Steer .





Damage noted to rear of vehicle of 2018 CAT Skid Steer .





Damage noted to rear of vehicle of 2018 CAT Skid Steer .





Damage noted to rear of vehicle of 2018 CAT Skid Steer .





Damage noted to rear of vehicle of 2018 CAT Skid Steer .





Damage noted to rear of vehicle of 2018 CAT Skid Steer .





Damage noted to rear of vehicle of 2018 CAT Skid Steer .





Damage noted to rear of vehicle of 2018 CAT Skid Steer .





Damage noted to rear of vehicle of 2018 CAT Skid Steer .





Damage noted to rear of vehicle of 2018 CAT Skid Steer .





Damage noted to rear of vehicle of 2018 CAT Skid Steer .





Damage noted to rear of vehicle of 2018 CAT Skid Steer .





Damage noted to rear of vehicle of 2018 CAT Skid Steer .





Damage noted to rear of vehicle of 2018 CAT Skid Steer .





Damage noted to rear of vehicle of 2018 CAT Skid Steer .





Date of inspection: 12/02/25. Skid steer caught fire while he was clearing out area on his property. Unable to get hours off machine as it is heavily damaged and cannot power up. POC Joshua Sellers stated machine was at 3240 hours or so at last check. Engine compartment was heavily damaged by fire, including melting away top portion of fuel tank. There is no shop estimate for repairs.