

Claim Photo

Our File Number: 277-065211
Adjuster: Don Tatone
Insured: KSM Carrier Group Inc
Date of Loss: 11/11/2025
Customer File Number: 2025032710
Policy Number:




Photo: 1
Date Taken: 12/03/2025
Taken By: Donald Tatone
Description: DS front



Photo: 2
Date Taken: 12/03/2025
Taken By: Donald Tatone
Description: PS front

Claim Photo

Our File Number: 277-065211
Adjuster: Don Tatone
Insured: KSM Carrier Group Inc
Date of Loss: 11/11/2025
Customer File Number: 2025032710
Policy Number:



Photo: 3
Date Taken: 12/03/2025
Taken By: Donald Tatone
Description: DS rear



Photo: 4
Date Taken: 12/03/2025
Taken By: Donald Tatone
Description: PS rear

Claim Photo

Our File Number: 277-065211
Adjuster: Don Tatone
Insured: KSM Carrier Group Inc
Date of Loss: 11/11/2025
Customer File Number: 2025032710
Policy Number:



Photo: 5

Date Taken:
12/03/2025

Taken By:
Donald Tatone

Description:
DS rear axle / tires
- all rear the same
make/model/tread




Photo: 6

Date Taken:
12/03/2025

Taken By:
Donald Tatone

Description:
DS rear axle / tires
- all rear the same
make/model/tread

Claim Photo

Our File Number: 277-065211
Adjuster: Don Tatone
Insured: KSM Carrier Group Inc
Date of Loss: 11/11/2025
Customer File Number: 2025032710
Policy Number:




Photo: 7
Date Taken: 12/03/2025
Taken By: Donald Tatone
Description: DS rear axle / tires - all rear the same make/model/tread




Photo: 8
Date Taken: 12/03/2025
Taken By: Donald Tatone
Description: DS rear axle / tires - all rear the same make/model/tread

Claim Photo

Our File Number: 277-065211
Adjuster: Don Tatone
Insured: KSM Carrier Group Inc
Date of Loss: 11/11/2025
Customer File Number: 2025032710
Policy Number:




Photo: 9
Date Taken: 12/03/2025
Taken By: Donald Tatone
Description: PS rear axle / tires - all rear the same make/model/tread



Photo: 10
Date Taken: 12/03/2025
Taken By: Donald Tatone
Description: VIN info

Claim Photo

Our File Number: 277-065211
Adjuster: Don Tatone
Insured: KSM Carrier Group Inc
Date of Loss: 11/11/2025
Customer File Number: 2025032710
Policy Number:




Photo: 11
Date Taken: 12/03/2025
Taken By: Donald Tatone
Description: Inspection label



Photo: 12
Date Taken: 12/03/2025
Taken By: Donald Tatone
Description: DS top cab

Claim Photo

Our File Number: 277-065211
Adjuster: Don Tatone
Insured: KSM Carrier Group Inc
Date of Loss: 11/11/2025
Customer File Number: 2025032710
Policy Number:



Photo: 13

Date Taken:
12/03/2025

Taken By:
Donald Tatone

Description:
DS cab




Photo: 14

Date Taken:
12/03/2025

Taken By:
Donald Tatone

Description:
DS cab

Claim Photo

Our File Number: 277-065211
Adjuster: Don Tatone
Insured: KSM Carrier Group Inc
Date of Loss: 11/11/2025
Customer File Number: 2025032710
Policy Number:




Photo: 15

Date Taken:
12/03/2025

Taken By:
Donald Tatone

Description:
DS cab




Photo: 16

Date Taken:
12/03/2025

Taken By:
Donald Tatone

Description:
DS front

Claim Photo

Our File Number: 277-065211
Adjuster: Don Tatone
Insured: KSM Carrier Group Inc
Date of Loss: 11/11/2025
Customer File Number: 2025032710
Policy Number:



Photo: 17

Date Taken:
12/03/2025

Taken By:
Donald Tatone

Description:
DS cab / door




Photo: 18

Date Taken:
12/03/2025

Taken By:
Donald Tatone

Description:
DS steer tire

Claim Photo

Our File Number: 277-065211
Adjuster: Don Tatone
Insured: KSM Carrier Group Inc
Date of Loss: 11/11/2025
Customer File Number: 2025032710
Policy Number:




Photo: 19
Date Taken: 12/03/2025
Taken By: Donald Tatone
Description: DS steer tire




Photo: 20
Date Taken: 12/03/2025
Taken By: Donald Tatone
Description: DS steer tire tread

Claim Photo

Our File Number: 277-065211
Adjuster: Don Tatone
Insured: KSM Carrier Group Inc
Date of Loss: 11/11/2025
Customer File Number: 2025032710
Policy Number:




Photo: 21

Date Taken:
12/03/2025

Taken By:
Donald Tatone

Description:
Plate




Photo: 22

Date Taken:
12/03/2025

Taken By:
Donald Tatone

Description:
PS steer tire, same
as DS

Claim Photo

Our File Number: 277-065211
Adjuster: Don Tatone
Insured: KSM Carrier Group Inc
Date of Loss: 11/11/2025
Customer File Number: 2025032710
Policy Number:




Photo: 23
Date Taken: 12/03/2025
Taken By: Donald Tatone
Description: PS steer tire tread



Photo: 24
Date Taken: 12/03/2025
Taken By: Donald Tatone
Description: Unit number

Claim Photo

Our File Number: 277-065211
Adjuster: Don Tatone
Insured: KSM Carrier Group Inc
Date of Loss: 11/11/2025
Customer File Number: 2025032710
Policy Number:




Photo: 25

Date Taken:
12/03/2025

Taken By:
Donald Tatone

Description:
DS front




Photo: 26

Date Taken:
12/03/2025

Taken By:
Donald Tatone

Description:
Engine area - hood
does not open

Claim Photo

Our File Number: 277-065211
Adjuster: Don Tatone
Insured: KSM Carrier Group Inc
Date of Loss: 11/11/2025
Customer File Number: 2025032710
Policy Number:



Photo: 27

Date Taken:
12/03/2025

Taken By:
Donald Tatone

Description:
Engine area - hood
does not open




Photo: 28

Date Taken:
12/03/2025

Taken By:
Donald Tatone

Description:
Engine area - wires
to power are
severed

Claim Photo

Our File Number: 277-065211
Adjuster: Don Tatone
Insured: KSM Carrier Group Inc
Date of Loss: 11/11/2025
Customer File Number: 2025032710
Policy Number:




Photo: 29

Date Taken:
12/03/2025

Taken By:
Donald Tatone

Description:
Engine area - hood
does not open




Photo: 30

Date Taken:
12/03/2025

Taken By:
Donald Tatone

Description:
Interior

Claim Photo

Our File Number: 277-065211
Adjuster: Don Tatone
Insured: KSM Carrier Group Inc
Date of Loss: 11/11/2025
Customer File Number: 2025032710
Policy Number:




Photo: 31

Date Taken:
12/03/2025

Taken By:
Donald Tatone

Description:
Cab




Photo: 32

Date Taken:
12/03/2025

Taken By:
Donald Tatone

Description:
Dash area

Claim Photo

Our File Number: 277-065211
Adjuster: Don Tatone
Insured: KSM Carrier Group Inc
Date of Loss: 11/11/2025
Customer File Number: 2025032710
Policy Number:




Photo: 33

Date Taken:
12/03/2025

Taken By:
Donald Tatone

Description:
Console



Photo: 34

Date Taken:
12/03/2025

Taken By:
Donald Tatone

Description:
No oil change /
mileage sticker

Claim Photo

Our File Number: 277-065211
Adjuster: Don Tatone
Insured: KSM Carrier Group Inc
Date of Loss: 11/11/2025
Customer File Number: 2025032710
Policy Number:




Photo: 35

Date Taken:
12/03/2025

Taken By:
Donald Tatone

Description:
DS door -exposed
to elements, door
does not open




Photo: 36

Date Taken:
12/03/2025

Taken By:
Donald Tatone

Description:
DS front

Claim Photo

Our File Number: 277-065211
Adjuster: Don Tatone
Insured: KSM Carrier Group Inc
Date of Loss: 11/11/2025
Customer File Number: 2025032710
Policy Number:




Photo: 37

Date Taken:
12/03/2025

Taken By:
Donald Tatone

Description:
DS front




Photo: 38

Date Taken:
12/03/2025

Taken By:
Donald Tatone

Description:
DS