

Claim Photo

Our File Number: 277-067076
Adjuster: David Crans
Insured: Cannonball Express
Date of Loss:
Customer File Number: IWL26004102
Policy Number:



Photo: 1
Date Taken: 02/18/2026
Taken By: Marshall Bare
Description: id tag



Photo: 2
Date Taken: 02/18/2026
Taken By: Marshall Bare
Description: VIN plate worn out

Claim Photo

Our File Number: 277-067076
Adjuster: David Crans
Insured: Cannonball Express
Date of Loss:
Customer File Number: IWL26004102
Policy Number:



Photo: 3
Date Taken: 02/18/2026
Taken By: Marshall Bare
Description: front left corner



Photo: 4
Date Taken: 02/18/2026
Taken By: Marshall Bare
Description: front right corner

Claim Photo

Our File Number: 277-067076
Adjuster: David Crans
Insured: Cannonball Express
Date of Loss:
Customer File Number: IWL26004102
Policy Number:



Photo: 5
Date Taken: 02/18/2026
Taken By: Marshall Bare
Description: rear right corner



Photo: 6
Date Taken: 02/18/2026
Taken By: Marshall Bare
Description: left rear corner

Claim Photo

Our File Number: 277-067076
Adjuster: David Crans
Insured: Cannonball Express
Date of Loss:
Customer File Number: IWL26004102
Policy Number:



Photo: 7
Date Taken: 02/18/2026
Taken By: Marshall Bare
Description: left rear corner closer



Photo: 8
Date Taken: 02/18/2026
Taken By: Marshall Bare
Description: front

Claim Photo

Our File Number: 277-067076
Adjuster: David Crans
Insured: Cannonball Express
Date of Loss:
Customer File Number: IWL26004102
Policy Number:




Photo: 9
Date Taken: 02/18/2026
Taken By: Marshall Bare
Description: front 2




Photo: 10
Date Taken: 02/18/2026
Taken By: Marshall Bare
Description: right, front

Claim Photo

Our File Number: 277-067076
Adjuster: David Crans
Insured: Cannonball Express
Date of Loss:
Customer File Number: IWL26004102
Policy Number:



Photo: 11

Date Taken:
02/18/2026

Taken By:
Marshall Bare

Description:
right, front 2



Photo: 12

Date Taken:
02/18/2026

Taken By:
Marshall Bare

Description:
right side

Claim Photo

Our File Number: 277-067076
Adjuster: David Crans
Insured: Cannonball Express
Date of Loss:
Customer File Number: IWL26004102
Policy Number:



Photo: 13

Date Taken:
02/18/2026

Taken By:
Marshall Bare

Description:
rear



Photo: 14

Date Taken:
02/18/2026

Taken By:
Marshall Bare

Description:
rear 2

Claim Photo

Our File Number: 277-067076
Adjuster: David Crans
Insured: Cannonball Express
Date of Loss:
Customer File Number: IWL26004102
Policy Number:



Photo: 15
Date Taken: 02/18/2026
Taken By: Marshall Bare
Description: left side, rear



Photo: 16
Date Taken: 02/18/2026
Taken By: Marshall Bare
Description: left side, rear 2

Claim Photo

Our File Number: 277-067076
Adjuster: David Crans
Insured: Cannonball Express
Date of Loss:
Customer File Number: IWL26004102
Policy Number:




Photo: 17
Date Taken: 02/18/2026
Taken By: Marshall Bare
Description: right side damage, rear top




Photo: 18
Date Taken: 02/18/2026
Taken By: Marshall Bare
Description: right side damage, center top

Claim Photo

Our File Number: 277-067076
Adjuster: David Crans
Insured: Cannonball Express
Date of Loss:
Customer File Number: IWL26004102
Policy Number:




Photo: 19
Date Taken: 02/18/2026
Taken By: Marshall Bare
Description: right side damage, looking forward




Photo: 20
Date Taken: 02/18/2026
Taken By: Marshall Bare
Description: right side damage, looking forward 2

Claim Photo

Our File Number: 277-067076
Adjuster: David Crans
Insured: Cannonball Express
Date of Loss:
Customer File Number: IWL26004102
Policy Number:




Photo: 21
Date Taken: 02/18/2026
Taken By: Marshall Bare
Description: right side damage, looking forward 3



Photo: 22
Date Taken: 02/18/2026
Taken By: Marshall Bare
Description: right side damage, front

Claim Photo

Our File Number: 277-067076
Adjuster: David Crans
Insured: Cannonball Express
Date of Loss:
Customer File Number: IWL26004102
Policy Number:



Photo: 23

Date Taken:
02/18/2026

Taken By:
Marshall Bare

Description:
right side damage,
front 2




Photo: 24

Date Taken:
02/18/2026

Taken By:
Marshall Bare

Description:
right side damage,
looking back

Claim Photo

Our File Number: 277-067076
Adjuster: David Crans
Insured: Cannonball Express
Date of Loss:
Customer File Number: IWL26004102
Policy Number:



Photo: 25

Date Taken:
02/18/2026

Taken By:
Marshall Bare

Description:
right side damage,
lower



Photo: 26

Date Taken:
02/18/2026

Taken By:
Marshall Bare

Description:
reefer hours

Claim Photo

Our File Number: 277-067076
Adjuster: David Crans
Insured: Cannonball Express
Date of Loss:
Customer File Number: IWL26004102
Policy Number:




Photo: 27

Date Taken:
02/18/2026

Taken By:
Marshall Bare

Description:
reefer hours 2



Photo: 28

Date Taken:
02/18/2026

Taken By:
Marshall Bare

Description:
spare tire

Claim Photo

Our File Number: 277-067076
Adjuster: David Crans
Insured: Cannonball Express
Date of Loss:
Customer File Number: IWL26004102
Policy Number:




Photo: 29
Date Taken: 02/18/2026
Taken By: Marshall Bare
Description: front axle, view from right side




Photo: 30
Date Taken: 02/18/2026
Taken By: Marshall Bare
Description: front, right tire

Claim Photo

Our File Number: 277-067076
Adjuster: David Crans
Insured: Cannonball Express
Date of Loss:
Customer File Number: IWL26004102
Policy Number:



Photo: 31
Date Taken: 02/18/2026
Taken By: Marshall Bare
Description: front, right tire 2




Photo: 32
Date Taken: 02/18/2026
Taken By: Marshall Bare
Description: DOT bumper

Claim Photo

Our File Number: 277-067076
Adjuster: David Crans
Insured: Cannonball Express
Date of Loss:
Customer File Number: IWL26004102
Policy Number:



Photo: 33

Date Taken:
02/18/2026

Taken By:
Marshall Bare

Description:
rear axle




Photo: 34

Date Taken:
02/18/2026

Taken By:
Marshall Bare

Description:
Left rear tire

Claim Photo

Our File Number: 277-067076
Adjuster: David Crans
Insured: Cannonball Express
Date of Loss:
Customer File Number: IWL26004102
Policy Number:



Photo: 35

Date Taken:
02/18/2026

Taken By:
Marshall Bare

Description:
gas tank, rear



Photo: 36

Date Taken:
02/18/2026

Taken By:
Marshall Bare

Description:
gas tank label

Claim Photo

Our File Number: 277-067076
Adjuster: David Crans
Insured: Cannonball Express
Date of Loss:
Customer File Number: IWL26004102
Policy Number:



Photo: 37

Date Taken:
02/18/2026

Taken By:
Marshall Bare

Description:
gas tank, front




Photo: 38

Date Taken:
02/18/2026

Taken By:
Marshall Bare

Description:
landing gear, left
side

Claim Photo

Our File Number: 277-067076
Adjuster: David Crans
Insured: Cannonball Express
Date of Loss:
Customer File Number: IWL26004102
Policy Number:




Photo: 39
Date Taken: 02/18/2026
Taken By: Marshall Bare
Description: landing gear, front




Photo: 40
Date Taken: 02/18/2026
Taken By: Marshall Bare
Description: landing gear, right side

Claim Photo

Our File Number: 277-067076
Adjuster: David Crans
Insured: Cannonball Express
Date of Loss:
Customer File Number: IWL26004102
Policy Number:



Photo: 41
Date Taken: 02/18/2026
Taken By: Marshall Bare
Description: king pin




Photo: 42
Date Taken: 02/18/2026
Taken By: Marshall Bare
Description: cross bars underneath, right side

Claim Photo

Our File Number: 277-067076
Adjuster: David Crans
Insured: Cannonball Express
Date of Loss:
Customer File Number: IWL26004102
Policy Number:




Photo: 43
Date Taken: 02/18/2026
Taken By: Marshall Bare
Description: bent cross bars in front of landing gear




Photo: 44
Date Taken: 02/18/2026
Taken By: Marshall Bare
Description: bent cross bars in front of landing gear 2