

Claim Photo

Our File Number: 277-065071
Adjuster: Devon Karnitz
Insured: Daily Express
Date of Loss:
Customer File Number: A0625501
Policy Number:



Photo: 1

Date Taken:
05/31/2025

Taken By:
Client

Description:




Photo: 2

Date Taken:
05/31/2025

Taken By:
Client


Description:

Claim Photo

Our File Number: 277-065071
Adjuster: Devon Karnitz
Insured: Daily Express
Date of Loss:
Customer File Number: A0625501
Policy Number:



	 A close-up photograph of a green vehicle door. The door has a black side mirror and a black handle. A logo is visible on the door, featuring the word "TAYLOR" in large, bold, black letters, with the word "DEFENSE" in smaller, bold, black letters below it. The logo is partially obscured by the door's edge.		<p>Photo: 3</p> <p>Date Taken: 05/31/2025</p> <p>Taken By: Client</p> <p>Description:</p>
--	---	--	---

	 A close-up photograph of a green vehicle door, similar to the one in the previous photo. The door has a black side mirror and a black handle. A logo is visible on the door, featuring the word "TAYLOR" in large, bold, black letters, with the word "DEFENSE" in smaller, bold, black letters below it. The logo is partially obscured by the door's edge. The background shows a blue sky and some greenery.		<p>Photo: 4</p> <p>Date Taken: 05/31/2025</p> <p>Taken By: Client</p> <p>Description:</p>
--	---	--	---

Claim Photo

Our File Number: 277-065071
Adjuster: Devon Karnitz
Insured: Daily Express
Date of Loss:
Customer File Number: A0625501
Policy Number:



Photo: 5

Date Taken:
05/31/2025

Taken By:
Client

Description:



Photo: 6

Date Taken:
11/21/2025

Taken By:
Donald Traweek

Description:
Serial Number tag
on left side lower
door frame.
PLEASE NOTE
THAT THE LAST
TWO DIGITS ARE
22 AND NOT 21
AS REPORTED

Claim Photo

Our File Number: 277-065071
Adjuster: Devon Karnitz
Insured: Daily Express
Date of Loss:
Customer File Number: A0625501
Policy Number:



Photo: 7

Date Taken:
11/21/2025

Taken By:
Donald Traweek

Description:
Right side of info tag on lower door frame



Photo: 8

Date Taken:
11/21/2025

Taken By:
Donald Traweek

Description:
Left side of info tag on lower door frame.

Claim Photo

Our File Number: 277-065071
Adjuster: Devon Karnitz
Insured: Daily Express
Date of Loss:
Customer File Number: A0625501
Policy Number:



Photo: 9

Date Taken:
11/21/2025

Taken By:
Donald Traweek

Description:
Dash panel on in
claimant vehicle.



Photo: 10

Date Taken:
11/21/2025

Taken By:
Donald Traweek

Description:
Instrument cluster
and auto shifter in
claimant vehicle.

Claim Photo

Our File Number: 277-065071
Adjuster: Devon Karnitz
Insured: Daily Express
Date of Loss:
Customer File Number: A0625501
Policy Number:



Photo: 11

Date Taken:
11/21/2025

Taken By:
Donald Traweek

Description:
Passenger side
interior in claimant
vehicle




Photo: 12

Date Taken:
11/21/2025

Taken By:
Donald Traweek

Description:
Driver side interior
in claimant vehicle.

Claim Photo

Our File Number: 277-065071
Adjuster: Devon Karnitz
Insured: Daily Express
Date of Loss:
Customer File Number: A0625501
Policy Number:



Photo: 13

Date Taken:
11/21/2025

Taken By:
Donald Traweek

Description:
Left front corner
view of claimant
vehicle.



Photo: 14

Date Taken:
11/21/2025

Taken By:
Donald Traweek

Description:
Left rear corner
view of claimant
vehicle.

Claim Photo

Our File Number: 277-065071
Adjuster: Devon Karnitz
Insured: Daily Express
Date of Loss:
Customer File Number: A0625501
Policy Number:



Photo: 15

Date Taken:
11/21/2025

Taken By:
Donald Traweek

Description:
Right rear corner
view of claimant
vesicle.



Photo: 16

Date Taken:
11/21/2025

Taken By:
Donald Traweek

Description:
Right front corner
view of claimant
vehicle.

Claim Photo

Our File Number: 277-065071
Adjuster: Devon Karnitz
Insured: Daily Express
Date of Loss:
Customer File Number: A0625501
Policy Number:



Photo: 17

Date Taken:
11/21/2025

Taken By:
Donald Traweek

Description:
Damage to driver
side door and a-
pillar on claimant
vehicle.



Photo: 18

Date Taken:
11/21/2025

Taken By:
Donald Traweek

Description:
Drivers a-pillar and
door damage on
claimant vehicle.

Claim Photo

Our File Number: 277-065071
Adjuster: Devon Karnitz
Insured: Daily Express
Date of Loss:
Customer File Number: A0625501
Policy Number:



Photo: 19

Date Taken:
11/21/2025

Taken By:
Donald Traweek

Description:
Driver side door
damage on
claimant vehicle.



Photo: 20

Date Taken:
11/21/2025

Taken By:
Donald Traweek

Description:
Driver side view of
door opening.

Claim Photo

Our File Number: 277-065071
Adjuster: Devon Karnitz
Insured: Daily Express
Date of Loss:
Customer File Number: A0625501
Policy Number:




Photo: 21

Date Taken:
11/21/2025

Taken By:
Donald Traweek

Description:
Information label
on claimant vehicle




Photo: 22

Date Taken:
11/21/2025

Taken By:
Donald Traweek

Description:
Load rating on
crane info.

Claim Photo

Our File Number: 277-065071
Adjuster: Devon Karnitz
Insured: Daily Express
Date of Loss:
Customer File Number: A0625501
Policy Number:



Photo: 23

Date Taken:
11/21/2025

Taken By:
Donald Traweek

Description:
Info label on left
door frame.




Photo: 24

Date Taken:
11/21/2025

Taken By:
Donald Traweek

Description:
Info label and what
appears to be 17
digit VIN on
claimant vehicle

Claim Photo

Our File Number: 277-065071
Adjuster: Devon Karnitz
Insured: Daily Express
Date of Loss:
Customer File Number: A0625501
Policy Number:



Photo: 25

Date Taken:
11/21/2025

Taken By:
Donald Traweek

Description:
Crack in left A-pillar at upper door hinge.



Photo: 26

Date Taken:
11/21/2025

Taken By:
Donald Traweek

Description:
Lower left side door hinge

Claim Photo

Our File Number: 277-065071
Adjuster: Devon Karnitz
Insured: Daily Express
Date of Loss:
Customer File Number: A0625501
Policy Number:



Photo: 27

Date Taken:
11/21/2025

Taken By:
Donald Traweek

Description:
Other sister units at
claimant facility



Photo: 28

Date Taken:
11/21/2025

Taken By:
Donald Traweek

Description:
What appears to be
A-pillar seem at
upper left marker
light on on roof.

Claim Photo

Our File Number: 277-065071
Adjuster: Devon Karnitz
Insured: Daily Express
Date of Loss:
Customer File Number: A0625501
Policy Number:



Photo: 29

Date Taken:
11/21/2025

Taken By:
Donald Traweek

Description:
Roof on left side at
marker light, no
seam showing.



Photo: 30

Date Taken:
11/21/2025

Taken By:
Donald Traweek

Description:
Roof on claimant
vehicle.

Claim Photo

Our File Number: 277-065071
Adjuster: Devon Karnitz
Insured: Daily Express
Date of Loss:
Customer File Number: A0625501
Policy Number:



Photo: 31

Date Taken:
11/21/2025

Taken By:
Donald Traweek

Description:
Looking forward
on left side of roof
on claimant
vehicle.



Photo: 32

Date Taken:
11/21/2025

Taken By:
Donald Traweek

Description:
Looking forward
on left side of roof
on claimant
vehicle.