

Claim Photo

Our File Number: 277-065584
Adjuster: Michael Cameron
Insured: AMCON DISTRIBUTING COMPANY
Date of Loss: 12/10/2025
Customer File Number: 011260-189171-AP-01
Policy Number:



Photo: 1

Date Taken:
01/02/2026

Taken By:
Curtis Murphy

Description:
2017 Volvo VNL,
VIN:
4V4N19DG1HN98
1652. VIN
confirmation.




Photo: 2

Date Taken:
01/02/2026


Taken By:
Curtis Murphy

Description:
Unit information
tag.

Our File Number: 277-065584
Adjuster: Michael Cameron
Insured: AMCON DISTRIBUTING COMPANY
Date of Loss: 12/10/2025
Customer File Number: 011260-189171-AP-01
Policy Number:



Description:
Additional unit
information.



Description:
VIN verification.

Claim Photo

Our File Number: 277-065584
Adjuster: Michael Cameron
Insured: AMCON DISTRIBUTING COMPANY
Date of Loss: 12/10/2025
Customer File Number: 011260-189171-AP-01
Policy Number:



Photo: 5

Date Taken:
01/02/2026

Taken By:
Curtis Murphy

Description:
Copart Lot number:
97028175.




Photo: 6

Date Taken:
01/02/2026

Taken By:
Curtis Murphy

Description:
Mileage, 520369.3

Claim Photo

Our File Number: 277-065584
Adjuster: Michael Cameron
Insured: AMCON DISTRIBUTING COMPANY
Date of Loss: 12/10/2025
Customer File Number: 011260-189171-AP-01
Policy Number:



Photo: 7

Date Taken:
01/02/2026

Taken By:
Curtis Murphy

Description:
Interior view.



Photo: 8

Date Taken:
01/02/2026

Taken By:
Curtis Murphy

Description:
Shift, automatic.

Claim Photo

Our File Number: 277-065584
Adjuster: Michael Cameron
Insured: AMCON DISTRIBUTING COMPANY
Date of Loss: 12/10/2025
Customer File Number: 011260-189171-AP-01
Policy Number:



Photo: 9

Date Taken:
01/02/2026

Taken By:
Curtis Murphy

Description:
Dash view.



Photo: 10

Date Taken:
01/02/2026

Taken By:
Curtis Murphy

Description:
Missing
windshield.

Claim Photo

Our File Number: 277-065584
Adjuster: Michael Cameron
Insured: AMCON DISTRIBUTING COMPANY
Date of Loss: 12/10/2025
Customer File Number: 011260-189171-AP-01
Policy Number:



Photo: 11

Date Taken:
01/02/2026

Taken By:
Curtis Murphy

Description:
Front driver side.



Photo: 12

Date Taken:
01/02/2026

Taken By:
Curtis Murphy

Description:
Rear driver side.

Claim Photo

Our File Number: 277-065584
Adjuster: Michael Cameron
Insured: AMCON DISTRIBUTING COMPANY
Date of Loss: 12/10/2025
Customer File Number: 011260-189171-AP-01
Policy Number:



Photo: 13

Date Taken:
01/02/2026

Taken By:
Curtis Murphy

Description:
Rear passenger
side.



Photo: 14

Date Taken:
01/02/2026

Taken By:
Curtis Murphy

Description:
Front passenger
side.

Claim Photo

Our File Number: 277-065584
Adjuster: Michael Cameron
Insured: AMCON DISTRIBUTING COMPANY
Date of Loss: 12/10/2025
Customer File Number: 011260-189171-AP-01
Policy Number:



Photo: 15

Date Taken:
01/02/2026

Taken By:
Curtis Murphy

Description:
Full front,
damages. Cattle
guard affected.



Photo: 16

Date Taken:
01/02/2026

Taken By:
Curtis Murphy

Description:
Rearview mirror
damages.

Claim Photo

Our File Number: 277-065584
Adjuster: Michael Cameron
Insured: AMCON DISTRIBUTING COMPANY
Date of Loss: 12/10/2025
Customer File Number: 011260-189171-AP-01
Policy Number:



Photo: 17

Date Taken:
01/02/2026

Taken By:
Curtis Murphy

Description:
Missing steer axle.
Hood damages.



Photo: 18

Date Taken:
01/02/2026

Taken By:
Curtis Murphy

Description:
Wheel well
damage, hood.

Claim Photo

Our File Number: 277-065584
Adjuster: Michael Cameron
Insured: AMCON DISTRIBUTING COMPANY
Date of Loss: 12/10/2025
Customer File Number: 011260-189171-AP-01
Policy Number:



Photo: 19

Date Taken:
01/02/2026

Taken By:
Curtis Murphy

Description:
Additional hood
damages.



Photo: 20

Date Taken:
01/02/2026

Taken By:
Curtis Murphy

Description:
Driver side door,
missing glass.

Claim Photo

Our File Number: 277-065584
Adjuster: Michael Cameron
Insured: AMCON DISTRIBUTING COMPANY
Date of Loss: 12/10/2025
Customer File Number: 011260-189171-AP-01
Policy Number:



Photo: 21

Date Taken:
01/02/2026

Taken By:
Curtis Murphy

Description:
Damages to driver
side mirror.



Photo: 22

Date Taken:
01/02/2026

Taken By:
Curtis Murphy

Description:
Close up, wheel
well damages.

Claim Photo

Our File Number: 277-065584
Adjuster: Michael Cameron
Insured: AMCON DISTRIBUTING COMPANY
Date of Loss: 12/10/2025
Customer File Number: 011260-189171-AP-01
Policy Number:



Photo: 23

Date Taken:
01/02/2026

Taken By:
Curtis Murphy

Description:
Step damages.




Photo: 24

Date Taken:
01/02/2026

Taken By:
Curtis Murphy

Description:
Air foil damages.

Claim Photo

Our File Number: 277-065584
Adjuster: Michael Cameron
Insured: AMCON DISTRIBUTING COMPANY
Date of Loss: 12/10/2025
Customer File Number: 011260-189171-AP-01
Policy Number:



Photo: 25

Date Taken:
01/02/2026

Taken By:
Curtis Murphy

Description:
View 2.



Photo: 26

Date Taken:
01/02/2026

Taken By:
Curtis Murphy

Description:
Rear step damages
above fuel tank.

Claim Photo

Our File Number: 277-065584
Adjuster: Michael Cameron
Insured: AMCON DISTRIBUTING COMPANY
Date of Loss: 12/10/2025
Customer File Number: 011260-189171-AP-01
Policy Number:



Photo: 27

Date Taken:
01/02/2026

Taken By:
Curtis Murphy

Description:
Lower step
damages.



Photo: 28

Date Taken:
01/02/2026

Taken By:
Curtis Murphy

Description:
Fifth wheel, bottom
of trailer damages.

Claim Photo

Our File Number: 277-065584
Adjuster: Michael Cameron
Insured: AMCON DISTRIBUTING COMPANY
Date of Loss: 12/10/2025
Customer File Number: 011260-189171-AP-01
Policy Number:



Photo: 29

Date Taken:
01/02/2026

Taken By:
Curtis Murphy

Description:
View of fifth
wheel.



Photo: 30

Date Taken:
01/02/2026

Taken By:
Curtis Murphy

Description:
Rear view, trailer
bottom attached.

Claim Photo

Our File Number: 277-065584
Adjuster: Michael Cameron
Insured: AMCON DISTRIBUTING COMPANY
Date of Loss: 12/10/2025
Customer File Number: 011260-189171-AP-01
Policy Number:



Photo: 31

Date Taken:
01/02/2026

Taken By:
Curtis Murphy

Description:
Rear axle damages.



Photo: 32

Date Taken:
01/02/2026

Taken By:
Curtis Murphy

Description:
Lower light
damages.

Claim Photo

Our File Number: 277-065584
Adjuster: Michael Cameron
Insured: AMCON DISTRIBUTING COMPANY
Date of Loss: 12/10/2025
Customer File Number: 011260-189171-AP-01
Policy Number:




Photo: 33

Date Taken:
01/02/2026

Taken By:
Curtis Murphy

Description:
Rear passenger side
axle view.



Photo: 34

Date Taken:
01/02/2026

Taken By:
Curtis Murphy

Description:
Missing exterior
tire, wheel
damages.

Claim Photo

Our File Number: 277-065584
Adjuster: Michael Cameron
Insured: AMCON DISTRIBUTING COMPANY
Date of Loss: 12/10/2025
Customer File Number: 011260-189171-AP-01
Policy Number:



Photo: 35

Date Taken:
01/02/2026

Taken By:
Curtis Murphy

Description:
Fuel tank,
passenger side.



Photo: 36

Date Taken:
01/02/2026

Taken By:
Curtis Murphy

Description:
Dent on top of tank.

Claim Photo

Our File Number: 277-065584
Adjuster: Michael Cameron
Insured: AMCON DISTRIBUTING COMPANY
Date of Loss: 12/10/2025
Customer File Number: 011260-189171-AP-01
Policy Number:



Photo: 37

Date Taken:
01/02/2026

Taken By:
Curtis Murphy

Description:
Close up of tank.



Photo: 38

Date Taken:
01/02/2026

Taken By:
Curtis Murphy

Description:
Step over, shifted.

Claim Photo

Our File Number: 277-065584
Adjuster: Michael Cameron
Insured: AMCON DISTRIBUTING COMPANY
Date of Loss: 12/10/2025
Customer File Number: 011260-189171-AP-01
Policy Number:



Photo: 39

Date Taken:
01/02/2026

Taken By:
Curtis Murphy

Description:
Passenger side step
damages.



Photo: 40

Date Taken:
01/02/2026

Taken By:
Curtis Murphy

Description:
Step damages close
up.

Claim Photo

Our File Number: 277-065584
Adjuster: Michael Cameron
Insured: AMCON DISTRIBUTING COMPANY
Date of Loss: 12/10/2025
Customer File Number: 011260-189171-AP-01
Policy Number:




Photo: 41

Date Taken:
01/02/2026

Taken By:
Curtis Murphy

Description:
Upper step
damages.



Photo: 42

Date Taken:
01/02/2026

Taken By:
Curtis Murphy

Description:
Air foil damages.

Claim Photo

Our File Number: 277-065584
Adjuster: Michael Cameron
Insured: AMCON DISTRIBUTING COMPANY
Date of Loss: 12/10/2025
Customer File Number: 011260-189171-AP-01
Policy Number:



Photo: 43

Date Taken:
01/02/2026

Taken By:
Curtis Murphy

Description:
Missing passenger
side air foil.



Photo: 44

Date Taken:
01/02/2026

Taken By:
Curtis Murphy

Description:
Passenger side door
and cab damages.

Claim Photo

Our File Number: 277-065584
Adjuster: Michael Cameron
Insured: AMCON DISTRIBUTING COMPANY
Date of Loss: 12/10/2025
Customer File Number: 011260-189171-AP-01
Policy Number:



Photo: 45

Date Taken:
01/02/2026

Taken By:
Curtis Murphy

Description:
Lower damage
view, door and cab.



Photo: 46

Date Taken:
01/02/2026

Taken By:
Curtis Murphy

Description:
Front view of
passenger side
door.

Claim Photo

Our File Number: 277-065584
Adjuster: Michael Cameron
Insured: AMCON DISTRIBUTING COMPANY
Date of Loss: 12/10/2025
Customer File Number: 011260-189171-AP-01
Policy Number:



Photo: 47

Date Taken:
01/02/2026

Taken By:
Curtis Murphy

Description:
Front axle missing.



Photo: 48

Date Taken:
01/02/2026

Taken By:
Curtis Murphy

Description:
View of
undercarriage and
missing axle.

Claim Photo

Our File Number: 277-065584
Adjuster: Michael Cameron
Insured: AMCON DISTRIBUTING COMPANY
Date of Loss: 12/10/2025
Customer File Number: 011260-189171-AP-01
Policy Number:



Photo: 49

Date Taken:
01/02/2026

Taken By:
Curtis Murphy

Description:
Frame damages.



Photo: 50

Date Taken:
01/02/2026

Taken By:
Curtis Murphy

Description:
Showing frame
damages.

Claim Photo

Our File Number: 277-065584
Adjuster: Michael Cameron
Insured: AMCON DISTRIBUTING COMPANY
Date of Loss: 12/10/2025
Customer File Number: 011260-189171-AP-01
Policy Number:



Photo: 51

Date Taken:
01/02/2026

Taken By:
Curtis Murphy

Description:
Bumper and hood
damages.




Photo: 52

Date Taken:
01/02/2026

Taken By:
Curtis Murphy

Description:
Missing passenger
side headlight.

Claim Photo

Our File Number: 277-065584
Adjuster: Michael Cameron
Insured: AMCON DISTRIBUTING COMPANY
Date of Loss: 12/10/2025
Customer File Number: 011260-189171-AP-01
Policy Number:



Photo: 53

Date Taken:
01/02/2026

Taken By:
Curtis Murphy

Description:
Missing
windshield.



Photo: 54

Date Taken:
01/02/2026

Taken By:
Curtis Murphy

Description:
Upper foil
damages.

Claim Photo

Our File Number: 277-065584
Adjuster: Michael Cameron
Insured: AMCON DISTRIBUTING COMPANY
Date of Loss: 12/10/2025
Customer File Number: 011260-189171-AP-01
Policy Number:



Photo: 55

Date Taken:
01/02/2026

Taken By:
Curtis Murphy

Description:
Steer tire
information.



Photo: 56

Date Taken:
01/02/2026

Taken By:
Curtis Murphy

Description:
Drive tire
information.

Claim Photo

Our File Number: 277-065584
Adjuster: Michael Cameron
Insured: AMCON DISTRIBUTING COMPANY
Date of Loss: 12/10/2025
Customer File Number: 011260-189171-AP-01
Policy Number:



Photo: 57

Date Taken:
01/02/2026

Taken By:
Curtis Murphy

Description:
Removed driver
side steer.



Photo: 58

Date Taken:
01/02/2026

Taken By:
Curtis Murphy

Description:
Passenger side
steer.

Claim Photo

Our File Number: 277-065584
Adjuster: Michael Cameron
Insured: AMCON DISTRIBUTING COMPANY
Date of Loss: 12/10/2025
Customer File Number: 011260-189171-AP-01
Policy Number:



Photo: 59

Date Taken:
01/02/2026

Taken By:
Curtis Murphy

Description:
Front exterior
driver side.



Photo: 60

Date Taken:
01/02/2026

Taken By:
Curtis Murphy

Description:

Claim Photo

Our File Number: 277-065584
Adjuster: Michael Cameron
Insured: AMCON DISTRIBUTING COMPANY
Date of Loss: 12/10/2025
Customer File Number: 011260-189171-AP-01
Policy Number:



Photo: 61

Date Taken:
01/02/2026

Taken By:
Curtis Murphy

Description:
Front interior driver
side.



Photo: 62

Date Taken:
01/02/2026

Taken By:
Curtis Murphy

Description:
Front exterior
passenger side.

Claim Photo

Our File Number: 277-065584
Adjuster: Michael Cameron
Insured: AMCON DISTRIBUTING COMPANY
Date of Loss: 12/10/2025
Customer File Number: 011260-189171-AP-01
Policy Number:




Photo: 63

Date Taken:
01/02/2026

Taken By:
Curtis Murphy

Description:
Front interior
passenger side.




Photo: 64

Date Taken:
01/02/2026

Taken By:
Curtis Murphy

Description:
View between drive
tires.

Claim Photo

Our File Number: 277-065584
Adjuster: Michael Cameron
Insured: AMCON DISTRIBUTING COMPANY
Date of Loss: 12/10/2025
Customer File Number: 011260-189171-AP-01
Policy Number:



Photo: 65

Date Taken:
01/02/2026

Taken By:
Curtis Murphy

Description:
Drive tire brake.



Photo: 66

Date Taken:
01/02/2026

Taken By:
Curtis Murphy

Description:
Steer tire brake.

Claim Photo

Our File Number: 277-065584
Adjuster: Michael Cameron
Insured: AMCON DISTRIBUTING COMPANY
Date of Loss: 12/10/2025
Customer File Number: 011260-189171-AP-01
Policy Number:



Photo: 67

Date Taken:
01/02/2026

Taken By:
Curtis Murphy

Description:
Undercarriage 1.



Photo: 68

Date Taken:
01/02/2026

Taken By:
Curtis Murphy

Description:
Undercarriage 2.

Claim Photo

Our File Number: 277-065584
Adjuster: Michael Cameron
Insured: AMCON DISTRIBUTING COMPANY
Date of Loss: 12/10/2025
Customer File Number: 011260-189171-AP-01
Policy Number:



Photo: 69

Date Taken:
01/02/2026

Taken By:
Curtis Murphy

Description:
Undercarriage 3.



Photo: 70

Date Taken:
01/02/2026

Taken By:
Curtis Murphy

Description:
Undercarriage 4.