

## Claim Photo

**Our File Number:** 277-065690  
**Adjuster:** Devon Karnitz  
**Insured:** Deluxe Transport LLC  
**Date of Loss:** 11/25/2025  
**Customer File Number:** 2025033801  
**Policy Number:**



### Photo: 1

**Date Taken:**  
12/29/2025

**Taken By:**  
Christopher Manuel

**Description:**  
View of the insured  
vehicle



### Photo: 2

**Date Taken:**  
12/29/2025

**Taken By:**  
Christopher Manuel

**Description:**  
View of the insured  
vehicle

## Claim Photo

**Our File Number:** 277-065690  
**Adjuster:** Devon Karnitz  
**Insured:** Deluxe Transport LLC  
**Date of Loss:** 11/25/2025  
**Customer File Number:** 2025033801  
**Policy Number:**



**Photo: 3**

**Date Taken:**  
12/29/2025

**Taken By:**  
Christopher Manuel

**Description:**  
View of the insured  
vehicle



**Photo: 4**

**Date Taken:**  
12/29/2025


**Taken By:**  
Christopher Manuel

**Description:**  
View of the insured  
vehicle



## Claim Photo

**Our File Number:** 277-065690  
**Adjuster:** Devon Karnitz  
**Insured:** Deluxe Transport LLC  
**Date of Loss:** 11/25/2025  
**Customer File Number:** 2025033801  
**Policy Number:**




**Photo: 5**

**Date Taken:**  
12/29/2025

**Taken By:**  
Christopher Manuel

**Description:**  
View of the insured  
vehicle VIN



**Photo: 6**

**Date Taken:**  
12/29/2025

**Taken By:**  
Christopher Manuel

**Description:**  
View of the insured  
vehicle VIN

## Claim Photo

**Our File Number:** 277-065690  
**Adjuster:** Devon Karnitz  
**Insured:** Deluxe Transport LLC  
**Date of Loss:** 11/25/2025  
**Customer File Number:** 2025033801  
**Policy Number:**



**Photo: 7**

**Date Taken:**  
12/29/2025

**Taken By:**  
Christopher Manuel

**Description:**  
View of the interior  
console



**Photo: 8**

**Date Taken:**  
12/29/2025

**Taken By:**  
Christopher Manuel

**Description:**  
View of the interior  
console



## Claim Photo

**Our File Number:** 277-065690  
**Adjuster:** Devon Karnitz  
**Insured:** Deluxe Transport LLC  
**Date of Loss:** 11/25/2025  
**Customer File Number:** 2025033801  
**Policy Number:**



**Photo: 9**

**Date Taken:**  
12/29/2025

**Taken By:**  
Christopher Manuel

**Description:**  
View of the interior  
console



**Photo: 10**

**Date Taken:**  
12/29/2025

**Taken By:**  
Christopher Manuel

**Description:**  
View of the interior  
console

## Claim Photo

**Our File Number:** 277-065690  
**Adjuster:** Devon Karnitz  
**Insured:** Deluxe Transport LLC  
**Date of Loss:** 11/25/2025  
**Customer File Number:** 2025033801  
**Policy Number:**



**Photo: 11**

**Date Taken:**  
12/29/2025

**Taken By:**  
Christopher Manuel

**Description:**  
View of the  
odometer, vehicle  
could not turn on to  
show the mileage



**Photo: 12**

**Date Taken:**  
12/29/2025

**Taken By:**  
Christopher Manuel

**Description:**  
Damage to the  
windshield



## Claim Photo

**Our File Number:** 277-065690  
**Adjuster:** Devon Karnitz  
**Insured:** Deluxe Transport LLC  
**Date of Loss:** 11/25/2025  
**Customer File Number:** 2025033801  
**Policy Number:**




**Photo: 13**

**Date Taken:**  
12/29/2025

**Taken By:**  
Christopher Manuel

**Description:**  
Damage to the  
windshield



**Photo: 14**

**Date Taken:**  
12/29/2025

**Taken By:**  
Christopher Manuel

**Description:**  
Damage to the  
driver side  
headlight

## Claim Photo

**Our File Number:** 277-065690  
**Adjuster:** Devon Karnitz  
**Insured:** Deluxe Transport LLC  
**Date of Loss:** 11/25/2025  
**Customer File Number:** 2025033801  
**Policy Number:**



**Photo: 15**

**Date Taken:**  
12/29/2025

**Taken By:**  
Christopher Manuel

**Description:**  
Damage to the  
driver side  
headlight



**Photo: 16**

**Date Taken:**  
12/29/2025

**Taken By:**  
Christopher Manuel

**Description:**  
Damage to the  
driver side  
headlight



## Claim Photo

**Our File Number:** 277-065690  
**Adjuster:** Devon Karnitz  
**Insured:** Deluxe Transport LLC  
**Date of Loss:** 11/25/2025  
**Customer File Number:** 2025033801  
**Policy Number:**



**Photo: 17**

**Date Taken:**  
12/29/2025

**Taken By:**  
Christopher Manuel

**Description:**  
Damage to the  
driver side  
headlight



**Photo: 18**

**Date Taken:**  
12/29/2025

**Taken By:**  
Christopher Manuel

**Description:**  
Damage to the  
driver side  
headlight

## Claim Photo

**Our File Number:** 277-065690  
**Adjuster:** Devon Karnitz  
**Insured:** Deluxe Transport LLC  
**Date of Loss:** 11/25/2025  
**Customer File Number:** 2025033801  
**Policy Number:**



**Photo: 19**

**Date Taken:**  
12/29/2025

**Taken By:**  
Christopher Manuel

**Description:**  
Damage to the  
hood



**Photo: 20**

**Date Taken:**  
12/29/2025

**Taken By:**  
Christopher Manuel

**Description:**  
Damage to the  
hood



## Claim Photo

**Our File Number:** 277-065690  
**Adjuster:** Devon Karnitz  
**Insured:** Deluxe Transport LLC  
**Date of Loss:** 11/25/2025  
**Customer File Number:** 2025033801  
**Policy Number:**




**Photo: 21**

**Date Taken:**  
12/29/2025

**Taken By:**  
Christopher Manuel

**Description:**  
Damage to the  
hood



**Photo: 22**

**Date Taken:**  
12/29/2025

**Taken By:**  
Christopher Manuel

**Description:**  
Damage to the  
hood

## Claim Photo

**Our File Number:** 277-065690  
**Adjuster:** Devon Karnitz  
**Insured:** Deluxe Transport LLC  
**Date of Loss:** 11/25/2025  
**Customer File Number:** 2025033801  
**Policy Number:**



**Photo: 23**

**Date Taken:**  
12/29/2025

**Taken By:**  
Christopher Manuel

**Description:**  
Damage to the  
hood



**Photo: 24**

**Date Taken:**  
12/29/2025

**Taken By:**  
Christopher Manuel

**Description:**  
Damage to the  
hood



## Claim Photo

**Our File Number:** 277-065690  
**Adjuster:** Devon Karnitz  
**Insured:** Deluxe Transport LLC  
**Date of Loss:** 11/25/2025  
**Customer File Number:** 2025033801  
**Policy Number:**



**Photo: 25**

**Date Taken:**  
12/29/2025

**Taken By:**  
Christopher Manuel

**Description:**  
Driver side rear  
view mirror was  
sheered off



**Photo: 26**

**Date Taken:**  
12/29/2025

**Taken By:**  
Christopher Manuel

**Description:**  
Driver side rear  
view mirror was  
sheered off

## Claim Photo

**Our File Number:** 277-065690  
**Adjuster:** Devon Karnitz  
**Insured:** Deluxe Transport LLC  
**Date of Loss:** 11/25/2025  
**Customer File Number:** 2025033801  
**Policy Number:**



**Photo: 27**

**Date Taken:**  
12/29/2025

**Taken By:**  
Christopher Manuel

**Description:**  
Damage to the rear  
of driver side of the  
cab



**Photo: 28**

**Date Taken:**  
12/29/2025

**Taken By:**  
Christopher Manuel

**Description:**  
Damage to the rear  
of driver side of the  
cab



## Claim Photo

**Our File Number:** 277-065690  
**Adjuster:** Devon Karnitz  
**Insured:** Deluxe Transport LLC  
**Date of Loss:** 11/25/2025  
**Customer File Number:** 2025033801  
**Policy Number:**



**Photo: 29**

**Date Taken:**  
12/29/2025

**Taken By:**  
Christopher Manuel

**Description:**  
Damage to the rear  
of driver side of the  
cab



**Photo: 30**

**Date Taken:**  
12/29/2025

**Taken By:**  
Christopher Manuel

**Description:**  
Damage to the rear  
of driver side of the  
cab

## Claim Photo

**Our File Number:** 277-065690  
**Adjuster:** Devon Karnitz  
**Insured:** Deluxe Transport LLC  
**Date of Loss:** 11/25/2025  
**Customer File Number:** 2025033801  
**Policy Number:**




**Photo: 31**

**Date Taken:**  
12/29/2025

**Taken By:**  
Christopher Manuel

**Description:**  
Damage to the rear  
of driver side of the  
cab



**Photo: 32**

**Date Taken:**  
12/29/2025

**Taken By:**  
Christopher Manuel

**Description:**  
View of the driver  
side tire tread  
measurements



## Claim Photo

**Our File Number:** 277-065690  
**Adjuster:** Devon Karnitz  
**Insured:** Deluxe Transport LLC  
**Date of Loss:** 11/25/2025  
**Customer File Number:** 2025033801  
**Policy Number:**



**Photo: 33**

**Date Taken:**  
12/29/2025

**Taken By:**  
Christopher Manuel

**Description:**  
View of the driver  
side tire tread  
measurements



**Photo: 34**

**Date Taken:**  
12/29/2025

**Taken By:**  
Christopher Manuel

**Description:**  
View of the driver  
side tire tread  
measurements

## Claim Photo

**Our File Number:** 277-065690  
**Adjuster:** Devon Karnitz  
**Insured:** Deluxe Transport LLC  
**Date of Loss:** 11/25/2025  
**Customer File Number:** 2025033801  
**Policy Number:**



**Photo: 35**

**Date Taken:**  
12/29/2025

**Taken By:**  
Christopher Manuel

**Description:**  
View of the driver  
side tire tread  
measurements



**Photo: 36**

**Date Taken:**  
12/29/2025

**Taken By:**  
Christopher Manuel

**Description:**  
View of the driver  
side tire tread  
measurements



## Claim Photo

**Our File Number:** 277-065690  
**Adjuster:** Devon Karnitz  
**Insured:** Deluxe Transport LLC  
**Date of Loss:** 11/25/2025  
**Customer File Number:** 2025033801  
**Policy Number:**



**Photo: 37**

**Date Taken:**  
12/29/2025

**Taken By:**  
Christopher Manuel

**Description:**  
View of the driver  
side tire tread  
measurements



**Photo: 38**

**Date Taken:**  
12/29/2025

**Taken By:**  
Christopher Manuel

**Description:**  
View of the driver  
side tire tread  
measurements

## Claim Photo

**Our File Number:** 277-065690  
**Adjuster:** Devon Karnitz  
**Insured:** Deluxe Transport LLC  
**Date of Loss:** 11/25/2025  
**Customer File Number:** 2025033801  
**Policy Number:**



**Photo: 39**

**Date Taken:**  
12/29/2025

**Taken By:**  
Christopher Manuel

**Description:**  
View of the  
passenger side tire  
tread measurements



**Photo: 40**

**Date Taken:**  
12/29/2025

**Taken By:**  
Christopher Manuel

**Description:**  
View of the  
passenger side tire  
tread measurements



## Claim Photo

**Our File Number:** 277-065690  
**Adjuster:** Devon Karnitz  
**Insured:** Deluxe Transport LLC  
**Date of Loss:** 11/25/2025  
**Customer File Number:** 2025033801  
**Policy Number:**



**Photo: 41**

**Date Taken:**  
12/29/2025

**Taken By:**  
Christopher Manuel

**Description:**  
View of the  
passenger side tire  
tread measurements



**Photo: 42**

**Date Taken:**  
12/29/2025

**Taken By:**  
Christopher Manuel

**Description:**  
View of the  
passenger side tire  
tread measurements

## Claim Photo

**Our File Number:** 277-065690  
**Adjuster:** Devon Karnitz  
**Insured:** Deluxe Transport LLC  
**Date of Loss:** 11/25/2025  
**Customer File Number:** 2025033801  
**Policy Number:**



**Photo: 43**

**Date Taken:**  
12/29/2025

**Taken By:**  
Christopher Manuel

**Description:**  
View of the  
passenger side tire  
tread measurements



**Photo: 44**

**Date Taken:**  
12/29/2025

**Taken By:**  
Christopher Manuel

**Description:**  
View of the  
passenger side tire  
tread measurements



## Claim Photo

**Our File Number:** 277-065690  
**Adjuster:** Devon Karnitz  
**Insured:** Deluxe Transport LLC  
**Date of Loss:** 11/25/2025  
**Customer File Number:** 2025033801  
**Policy Number:**



**Photo: 45**

**Date Taken:**  
12/29/2025

**Taken By:**  
Christopher Manuel

**Description:**  
View of the  
passenger side tire  
tread measurements



**Photo: 46**


**Date Taken:**  
12/29/2025

**Taken By:**  
Christopher Manuel

**Description:**  
View of the engine,  
no observable  
damage

## Claim Photo

**Our File Number:** 277-065690  
**Adjuster:** Devon Karnitz  
**Insured:** Deluxe Transport LLC  
**Date of Loss:** 11/25/2025  
**Customer File Number:** 2025033801  
**Policy Number:**



**Photo: 47**

**Date Taken:**  
12/29/2025

**Taken By:**  
Christopher Manuel

**Description:**  
View of the engine,  
no observable  
damage



**Photo: 48**

**Date Taken:**  
12/29/2025


**Taken By:**  
Christopher Manuel

**Description:**  
View of the engine,  
no observable  
damage



## Claim Photo

**Our File Number:** 277-065690  
**Adjuster:** Devon Karnitz  
**Insured:** Deluxe Transport LLC  
**Date of Loss:** 11/25/2025  
**Customer File Number:** 2025033801  
**Policy Number:**



**Photo: 49**

**Date Taken:**  
12/29/2025

**Taken By:**  
Christopher Manuel

**Description:**  
View of the engine,  
no observable  
damage



**Photo: 50**


**Date Taken:**  
12/29/2025

**Taken By:**  
Christopher Manuel

**Description:**  
View of the engine,  
no observable  
damage

## Claim Photo

**Our File Number:** 277-065690  
**Adjuster:** Devon Karnitz  
**Insured:** Deluxe Transport LLC  
**Date of Loss:** 11/25/2025  
**Customer File Number:** 2025033801  
**Policy Number:**



**Photo: 51**

**Date Taken:**  
12/29/2025

**Taken By:**  
Christopher Manuel

**Description:**  
View of the engine,  
no observable  
damage



**Photo: 52**

**Date Taken:**  
12/29/2025

**Taken By:**  
Christopher Manuel

**Description:**  
View of the engine,  
no observable  
damage



## Claim Photo

**Our File Number:** 277-065690  
**Adjuster:** Devon Karnitz  
**Insured:** Deluxe Transport LLC  
**Date of Loss:** 11/25/2025  
**Customer File Number:** 2025033801  
**Policy Number:**




**Photo: 53**

**Date Taken:**  
12/29/2025

**Taken By:**  
Christopher Manuel

**Description:**  
View of the engine,  
no observable  
damage



**Photo: 54**

**Date Taken:**  
12/29/2025

**Taken By:**  
Christopher Manuel

**Description:**  
View of the engine,  
no observable  
damage

## Claim Photo

**Our File Number:** 277-065690  
**Adjuster:** Devon Karnitz  
**Insured:** Deluxe Transport LLC  
**Date of Loss:** 11/25/2025  
**Customer File Number:** 2025033801  
**Policy Number:**




**Photo: 55**

**Date Taken:**  
12/29/2025

**Taken By:**  
Christopher Manuel

**Description:**  
View of the engine,  
no observable  
damage



**Photo: 56**

**Date Taken:**  
12/29/2025

**Taken By:**  
Christopher Manuel

**Description:**  
View of the engine,  
no observable  
damage



## Claim Photo

**Our File Number:** 277-065690  
**Adjuster:** Devon Karnitz  
**Insured:** Deluxe Transport LLC  
**Date of Loss:** 11/25/2025  
**Customer File Number:** 2025033801  
**Policy Number:**



**Photo: 57**

**Date Taken:**  
12/29/2025

**Taken By:**  
Christopher Manuel

**Description:**  
View of the engine,  
no observable  
damage