

VIN of 2024 JLG 660SJ .

MODEL: 660SJ

PVC: 2407

DESIGNATION: TYPE 3 GROUP B MEWP

SERIAL NO: 0300325361

G.V.W. 26595 lbs/ 12063 kg

MAX  MAX  MAX 

YEAR OF MANUFACTURE: 2024

MAX  MAX  MAX 

28 MPH / 12.5 MS

MAX  MAX  MAX 

550 lbs 250 kg

750 lbs 340 kg

X lbs X kg

30 LBF/100 N

MAX  MAX  MAX 

197 lbs 90 kg

220 lbs 100 kg

X lbs X kg

65.7 FT/20.02 M

MAX  MAX  MAX 

THIS MACHINE MEETS OR EXCEEDS APPLICABLE REQUIREMENTS OF ANSI A92.20 - 2021 and CSA 354.6 - 2017 AS ORIGINALLY MANUFACTURED FOR INTENDED PURPOSES.

JLG INDUSTRIES, INC.
McCONNELLSBURG, PA. 17233-9533 U.S.A.

VIN of 2024 JLG 660SJ .



Odometer of 2024 JLG 660SJ .



Odometer of 2024 JLG 660SJ .



Identification tags of make and model of the unit of 2024 JLG 660SJ .



Identification tags of make and model of the unit of 2024 JLG 660SJ .



Driver side of vehicle of 2024 JLG 660SJ .



Driver side of vehicle of 2024 JLG 660SJ .



Driver side of vehicle of 2024 JLG 660SJ .



Passenger side of vehicle of 2024 JLG 660SJ .



Passenger side of vehicle of 2024 JLG 660SJ .



Passenger side of vehicle of 2024 JLG 660SJ .



Front of vehicle of 2024 JLG 660SJ .



Rear of vehicle of 2024 JLG 660SJ .



Wheels of 2024 JLG 660SJ .



Wheels of 2024 JLG 660SJ .



Wheels of 2024 JLG 660SJ .




Wheels of 2024 JLG 660SJ .



Interior view beneath the side panels on each side of the unit showing the motor, hydraulics, and electrical controls.



Interior view beneath the side panels on each side of the unit showing the motor, hydraulics, and electrical controls.




Interior view beneath the side panels on each side of the unit showing the motor, hydraulics, and electrical controls.



Interior view beneath the side panels on each side of the unit showing the motor, hydraulics, and electrical controls.



Interior view beneath the side panels on each side of the unit showing the motor, hydraulics, and electrical controls.




Interior view beneath the side panels on each side of the unit showing the motor, hydraulics, and electrical controls.



Interior view beneath the side panels on each side of the unit showing the motor, hydraulics, and electrical controls.



Interior view beneath the side panels on each side of the unit showing the motor, hydraulics, and electrical controls.



Interior view beneath the side panels on each side of the unit showing the motor, hydraulics, and electrical controls.



Interior view beneath the side panels on each side of the unit showing the motor, hydraulics, and electrical controls.



Interior view beneath the side panels on each side of the unit showing the motor, hydraulics, and electrical controls.



Interior view beneath the side panels on each side of the unit showing the motor, hydraulics, and electrical controls.



Interior view beneath the side panels on each side of the unit showing the motor, hydraulics, and electrical controls.



Interior view beneath the side panels on each side of the unit showing the motor, hydraulics, and electrical controls.



Interior view beneath the side panels on each side of the unit showing the motor, hydraulics, and electrical controls.



Interior view beneath the side panels on each side of the unit showing the motor, hydraulics, and electrical controls.



Electrical warnings on all sides of the vehicle.



Electrical warnings on all sides of the vehicle.



Electrical warnings on all sides of the vehicle.



Electrical warnings on all sides of the vehicle.



Electrical warnings on all sides of the vehicle.



Electrical warnings on all sides of the vehicle.



Electrical warnings on all sides of the vehicle.



Undercarriage.



Damage overview photos.



Damage overview photos.



Damage overview photos.



Damage overview photos.



Damage overview photos.



Damage overview photos.



Damage overview photos.



Damage overview photos.



Damage overview photos.



Damage overview photos.



Damage overview photos.



Damage overview photos.



Damage overview photos.



Damage overview photos.



Damage overview photos.



Damage overview photos.



Damage overview photos.



Basket overview with control box. This was separated from the unit at time of inspection.



Basket overview with control box. This was separated from the unit at time of inspection.



Basket overview with control box. This was separated from the unit at time of inspection.



Basket overview with control box. This was separated from the unit at time of inspection.



Basket overview with control box. This was separated from the unit at time of inspection.

