2016 Date: 12/24/2025 Year: Make: INTERNATIONAL Reference #: 037230021442 Estimated By: **AMA Claim Solutions** Model: Prostar Name: B & T Express Unit #: 2040 Address: VIN: 3HSDJAPR0GN403199 City/State/Zip: North Lima, OH 44452 Style: MDHD: Conventional Phone: 800-888-8268 Plate/State: PWL8676 - OH Inspected Date: WMI: FIN: Claimant: Odometer: 12/11/2025 Date of Loss: Color: Claim Contact: Date Of Loss: 12/11/2025 Contact Title: Inspected At: Wallys Auto Service and Contact Phone: Х Claim Number: 25-12071

Total Loss

File Number:

Oper	ation	Description	Part #	Туре		Labor	Paint	•		Parts		Misc
		Front Bumper, 3-P	iece w/o F	og Lamp								
	Replace	Front Bumper Assembly w/o Fog Lamps (non-painted)		LKQ		1.90		1	@	\$1,793.75	\$1,793.75	5
^		Vander Haags										
		Hood, Grille, & Hea	adlamps									
	Replace	Fender Panel (Right)		New		9.00	3.50	1	@	\$786.72	\$786.72	2
	Replace	Fender Adhesive		Mtrls	AddPrt			1	@	\$95.00	\$95.00)
		Add for Underside - Fender Pane (Right)	ıl		AddPnt		1.20					
		Aim Head Lamps			AddLbr	0.50						
		Add R&I Hood Assembly			AddLbr	2.00						
		Add to R&I Single Fender Mount Mirror	ed		AddLbr	0.30						
		Drill for Fender Mirror, Single			AddLbr	0.30						
	Replace	Rear View Fender Mounted Mirro (Right)	or	New		1.00		1	@	\$201.19	\$201.19)
	Replace	Headlamp Assembly, Standard (Right)		A/M	Incl			1	@	\$164.98	\$164.98	3
		Wheels & Tires - P	ainted									
	Replace	Rear Wheel - Outer - Axle #1 (Right)		New		1.40	1.00	1	@	\$199.41	\$199.41	_
		Non-Adjacent Overlap			Adj		-0.20					
	Replace	Rear Tire - Outer - Axle #1 (Righ	nt)	New	Incl			1	<u> </u>	\$500.22	\$500.22	2
	Replace	Add for Tire Disposal		Mtrls	AddPrt			1	@	\$5.00	\$5.00)
		Add to Balance Tire			AddLbr	0.20						
		Sleeper Cab	. -									
	Replace	Sleeper Cab Assembly 56		New		34.00	24.00	1	@	\$13,700.32	\$13,700.32	2
		Non-Adjacent Overlap			Ādj		-0.20					
		Add for Inside - Sleeper Cab Assembly 56			AddPnt		9.60					
		Add to Adjust Cab Height			AddLbr	0.50						

Contact Email:

Date: 12/24/2025 Year: 2016

Reference #: 037230021442 Make: INTERNATIONAL

Estimated By: AMA Claim Solutions Model: Prostar Name: B & T Express Unit #: 2040

(Operation	Description	Part #	Туре	I	Labor	Paint		Parts		Misc
21		Add with Cab Extender (Right Side)		AddLb	r	1.00					
22		Charge A/C		AddLb	rм	1.40					
23		Recover Freon		AddLb	r M	0.30					
	•	Frame									
24 *	k Repair	Adjust Front & Rear Alignment			М	4.00					
25 *	Repair	Set Up and Measure Frame			F	3.50					
	•	Calculated Values									
26	`	Shop Supplies		Mtrls							\$216.30
27		Hazardous Waste									\$10.00
28		Truck Cover		Mtrls		0.50		@	\$12.00	\$0.0	00
29	`	Two stage paint.					10.50				
30	`	Paint Materials		Mtrls							\$1,976.00

An '*' indicates user change of database part and '^' indicates manually entered or custom database rows.

Estimate Notes:

Aftermarket Parts - 4StateTrucks.com

Summary	Amount	Rate	Disc	Total
Body Labor	52.6	\$115.00	0.00%	\$6,049.00
Paint Labor	49.4	\$115.00	0.00%	\$5,681.00
Mechanical	5.7	\$155.00	0.00%	\$883.50
Frame	3.5	\$125.00	0.00%	\$437.50
Misc. Labor	0.0	\$85.00	0.00%	\$0.00
Parts	\$17,458.59		0.00%	\$17,458.59
Misc.				\$2,202.30
Sub-total				\$32,711.89
Sales Tax				2,289.83
	State (Labor, Parts, Materials) \$32,711.89 @ 7.0000%: \$2,289.83			
Total				\$35,001.72
Betterment				\$0.00
Deductible				\$0.00
Grand Total				\$35,001.72

Date:

12/24/2025

Reference #: Estimated By: 037230021442

AMA Claim Solutions

Name:

B & T Express

Year:

2016

Make:

INTERNATIONAL

Model: Unit #: Prostar 2040

Repair Facility: Address:

Phone: () -

Email:

Agreed With: License 1: License 2: Fed Tax ID: Registration #: Appraised By:

AMA Claim Solutions

License #1:

NPN 21444411 Colin Alexander

License #2: Phone:

903-662-6100

Email:

heavy@ama.claims

Date: 12/24/2025 Year: 2016

Reference #: 037230021442 Make: INTERNATIONAL

Estimated By: AMA Claim Solutions Model: Prostar Name: B & T Express Unit #: 2040

TERMS & CONDITIONS

I, Colin Alexander, PA license #1248866 hereby certify under penalty of perjury that this estimate was personally prepared by me in accordance with the provisions set forth by the Commonwealth of Pennsylvania State Insurance Commission. I certify that my estimate was given to the owner/shop.

The above is an estimate based on inspection and does not cover additional parts or labor which may be required after the work has been started. Occasionally worn or damaged parts are discovered which may not have been evident on the first inspection. Because of this, the above prices are not guaranteed. Quotations on parts and labor are current and subject to change.

*** THIS ESTIMATE/SUPPLEMENT IS SUBJECT TO AUDIT AND REVISION BY THE INSURANCE COMPANY ***

*** THIS IS NOT AN AUTHORIZATION TO REPAIR. ALL REPAIR COSTS ARE THE RESPONSIBILITY OF THE VEHICLE OWNER, WHO ULTIMATELY MUST AUTHORIZE ALL REPAIRS. NO ESTIMATES OR SUPPLEMENTS WILL BE HONORED WITHOUT PRIOR INSPECTION AND AUTHORIZATION. ***

*** COPY OF THIS APPRAISAL/SUPPLEMENT ONLY IS NOT AN ACCEPTANCE OF COVERAGE OR LIABILITY. ALL ISSUES OF COVERAGE OR LIABILITY ARE TO BE DETERMINED BY THE INSURANCE COMPANY. ***

Fraud Disclaimer:

ANY PERSON WHO KNOWINGLY PRESENTS A FALSE OR FRAUDULENT CLAIM FOR THE PAYMENT OF A LOSS IS GUILTY OF A CRIME AND MAY BE SUBJECT TO FINES AND CONFINEMENT.

Alternative Parts Disclaimer:

THIS ESTIMATE MAY HAVE BEEN PREPARED BASED ON THE USE OF AUTOMOBILE PARTS NOT MADE BY THE ORIGINAL MANUFACTURER. PARTS USED IN THE REPAIR OF YOUR VEHICLE BY OTHER THAN THE ORIGINAL MANUFACTURER ARE REQUIRED TO BE AT LEAST EQUAL IN LIKE KIND AND QUALITY IN TERMS OF FIT, QUALITY AND PERFORMANCE TO THE ORIGINAL MANUFACTURER PARTS THEY ARE REPLACING. SUCH PARTS CAN BE IDENTIFIED BY THE LETTER "A" ON THIS ESTIMATE. IF THE USE OF AN AFTERMARKET PART VOIDS THE EXISTING WARRANTY ON THE PART BEING REPLACED OR ON ANY OTHER PART, THE AFTERMARKET PART SHALL HAVE A WARRANTY EQUAL TO OR BETTER THAN THE REMAINDER OF THE EXISTING WARRANTY. THE AFTERMARKET PARTS ARE WARRANTED BY THE MANUFACTURER OR DISTRIBUTOR OF THE PART AND NOT THE MANUFACTURER OF THE VEHICLE.

Cianad	Data
Signed _	 Date