

Claim Photo

Our File Number: 277-066516
Adjuster: Jason Baka
Insured: DASEKE RM LLC
Date of Loss: 01/16/2026
Customer File Number: 001960-278797-AP-01
Policy Number:



Photo: 1

Date Taken:
02/03/2026

Taken By:
Daniela Hunglinger

Description:
VIN ID - 2023
Kenworth T680




Photo: 2

Date Taken:
02/03/2026

Taken By:
Daniela Hunglinger

Description:
Information tag on
unit

Claim Photo

Our File Number: 277-066516
Adjuster: Jason Baka
Insured: DASEKE RM LLC
Date of Loss: 01/16/2026
Customer File Number: 001960-278797-AP-01
Policy Number:




Photo: 3

Date Taken:
02/03/2026

Taken By:
Daniela Hunglinger

Description:
Production Date on unit




Photo: 4

Date Taken:
02/03/2026

Taken By:
Daniela Hunglinger

Description:
Info tag - 2023
Kenworth

Claim Photo

Our File Number: 277-066516
Adjuster: Jason Baka
Insured: DASEKE RM LLC
Date of Loss: 01/16/2026
Customer File Number: 001960-278797-AP-01
Policy Number:




Photo: 5

Date Taken:
02/03/2026

Taken By:
Daniela Hunglinger

Description:
VIN ID and
Chassis information




Photo: 6

Date Taken:
02/03/2026

Taken By:
Daniela Hunglinger

Description:
Annual inspection
tag

Claim Photo

Our File Number: 277-066516
Adjuster: Jason Baka
Insured: DASEKE RM LLC
Date of Loss: 01/16/2026
Customer File Number: 001960-278797-AP-01
Policy Number:



Photo: 7

Date Taken:
02/03/2026

Taken By:
Daniela Hunglinger

Description:
unable to retrieve
mileage



Photo: 8

Date Taken:
02/03/2026

Taken By:
Daniela Hunglinger

Description:
Dash/Cluster

Claim Photo

Our File Number: 277-066516
Adjuster: Jason Baka
Insured: DASEKE RM LLC
Date of Loss: 01/16/2026
Customer File Number: 001960-278797-AP-01
Policy Number:



Photo: 9

Date Taken:
02/03/2026

Taken By:
Daniela Hunglinger

Description:
Interior/instrument
panel



Photo: 10

Date Taken:
02/03/2026

Taken By:
Daniela Hunglinger

Description:
overall view
interior of cab

Claim Photo

Our File Number: 277-066516
Adjuster: Jason Baka
Insured: DASEKE RM LLC
Date of Loss: 01/16/2026
Customer File Number: 001960-278797-AP-01
Policy Number:



Photo: 11

Date Taken:
02/03/2026

Taken By:
Daniela Hunglinger

Description:
windshield Damage



Photo: 12

Date Taken:
02/03/2026

Taken By:
Daniela Hunglinger

Description:
Left Door Glass-
DMGE

Claim Photo

Our File Number: 277-066516
Adjuster: Jason Baka
Insured: DASEKE RM LLC
Date of Loss: 01/16/2026
Customer File Number: 001960-278797-AP-01
Policy Number:



Photo: 13

Date Taken:
02/03/2026

Taken By:
Daniela Hunglinger

Description:
interior/sleeper area



Photo: 14

Date Taken:
02/03/2026

Taken By:
Daniela Hunglinger

Description:
sleeper area

Claim Photo

Our File Number: 277-066516
Adjuster: Jason Baka
Insured: DASEKE RM LLC
Date of Loss: 01/16/2026
Customer File Number: 001960-278797-AP-01
Policy Number:




Photo: 15

Date Taken:
02/03/2026

Taken By:
Daniela Hunglinger

Description:
interior view



Photo: 16

Date Taken:
02/03/2026

Taken By:
Daniela Hunglinger

Description:
interior/sleeper
trims and cabinets

Claim Photo

Our File Number: 277-066516
Adjuster: Jason Baka
Insured: DASEKE RM LLC
Date of Loss: 01/16/2026
Customer File Number: 001960-278797-AP-01
Policy Number:



Photo: 17

Date Taken:
02/03/2026

Taken By:
Daniela Hunglinger

Description:
view of cab area



Photo: 18

Date Taken:
02/03/2026

Taken By:
Daniela Hunglinger

Description:
windshield opening
-damaged

Claim Photo

Our File Number: 277-066516
Adjuster: Jason Baka
Insured: DASEKE RM LLC
Date of Loss: 01/16/2026
Customer File Number: 001960-278797-AP-01
Policy Number:



Photo: 19

Date Taken:
02/03/2026

Taken By:
Daniela Hunglinger

Description:
upper overhead
trims



Photo: 20

Date Taken:
02/03/2026

Taken By:
Daniela Hunglinger

Description:
Cab Floor
conditions

Claim Photo

Our File Number: 277-066516
Adjuster: Jason Baka
Insured: DASEKE RM LLC
Date of Loss: 01/16/2026
Customer File Number: 001960-278797-AP-01
Policy Number:

**Photo: 21**

Date Taken:
02/03/2026

Taken By:
Daniela Hunglinger

Description:
Glass debris all over
interior cab area

**Photo: 22**

Date Taken:
02/03/2026

Taken By:
Daniela Hunglinger

Description:
damaged brackets

Claim Photo

Our File Number: 277-066516
Adjuster: Jason Baka
Insured: DASEKE RM LLC
Date of Loss: 01/16/2026
Customer File Number: 001960-278797-AP-01
Policy Number:



Photo: 23

Date Taken:
02/03/2026

Taken By:
Daniela Hunglinger

Description:
Left Front
Tire/Wheel



Photo: 24

Date Taken:
02/03/2026

Taken By:
Daniela Hunglinger

Description:
Left Front Tire
Depth measurement

Claim Photo

Our File Number: 277-066516
Adjuster: Jason Baka
Insured: DASEKE RM LLC
Date of Loss: 01/16/2026
Customer File Number: 001960-278797-AP-01
Policy Number:



Photo: 25

Date Taken:
02/03/2026

Taken By:
Daniela Hunglinger

Description:
Right Front Tire
/wheel



Photo: 26

Date Taken:
02/03/2026

Taken By:
Daniela Hunglinger

Description:
right Front Tire
Depth measurement

Claim Photo

Our File Number: 277-066516
Adjuster: Jason Baka
Insured: DASEKE RM LLC
Date of Loss: 01/16/2026
Customer File Number: 001960-278797-AP-01
Policy Number:



Photo: 27

Date Taken:
02/03/2026

Taken By:
Daniela Hunglinger

Description:
Right Side/ Rear
Tires/wheels




Photo: 28

Date Taken:
02/03/2026

Taken By:
Daniela Hunglinger

Description:
Right Rear Tires
Depth
Measurements

Claim Photo

Our File Number: 277-066516
Adjuster: Jason Baka
Insured: DASEKE RM LLC
Date of Loss: 01/16/2026
Customer File Number: 001960-278797-AP-01
Policy Number:



Photo: 29

Date Taken:
02/03/2026

Taken By:
Daniela Hunglinger

Description:
Right Rear Tire
Depth
measurements



Photo: 30

Date Taken:
02/03/2026

Taken By:
Daniela Hunglinger

Description:
Right Rear Tire
Depth
measurements

Claim Photo

Our File Number: 277-066516
Adjuster: Jason Baka
Insured: DASEKE RM LLC
Date of Loss: 01/16/2026
Customer File Number: 001960-278797-AP-01
Policy Number:




Photo: 31

Date Taken:
02/03/2026

Taken By:
Daniela Hunglinger

Description:
Right Rear Tire
Depth
measurements



Photo: 32

Date Taken:
02/03/2026

Taken By:
Daniela Hunglinger

Description:
LEFT Rear Tire
/Wheels

Claim Photo

Our File Number: 277-066516
Adjuster: Jason Baka
Insured: DASEKE RM LLC
Date of Loss: 01/16/2026
Customer File Number: 001960-278797-AP-01
Policy Number:



Photo: 33

Date Taken:
02/03/2026

Taken By:
Daniela Hunglinger

Description:
Left Rear Tire
Depth
measurements




Photo: 34

Date Taken:
02/03/2026

Taken By:
Daniela Hunglinger

Description:
Left Rear Tire
Depth
measurements

Claim Photo

Our File Number: 277-066516
Adjuster: Jason Baka
Insured: DASEKE RM LLC
Date of Loss: 01/16/2026
Customer File Number: 001960-278797-AP-01
Policy Number:



Photo: 35

Date Taken:
02/03/2026

Taken By:
Daniela Hunglinger

Description:
Left Rear Tire
Depth
measurements



Photo: 36

Date Taken:
02/03/2026

Taken By:
Daniela Hunglinger

Description:
Left Rear Tire
Depth
measurements

Claim Photo

Our File Number: 277-066516
Adjuster: Jason Baka
Insured: DASEKE RM LLC
Date of Loss: 01/16/2026
Customer File Number: 001960-278797-AP-01
Policy Number:




Photo: 37

Date Taken:
02/03/2026

Taken By:
Daniela Hunglinger

Description:
Fifth Wheel



Photo: 38

Date Taken:
02/03/2026

Taken By:
Daniela Hunglinger

Description:
Thermo King-
Auxiliary unit

Claim Photo

Our File Number: 277-066516
Adjuster: Jason Baka
Insured: DASEKE RM LLC
Date of Loss: 01/16/2026
Customer File Number: 001960-278797-AP-01
Policy Number:



Photo: 39

Date Taken:
02/03/2026

Taken By:
Daniela Hunglinger

Description:
Decals on Door



Photo: 40

Date Taken:
02/03/2026

Taken By:
Daniela Hunglinger

Description:
Decals/placards on unit

Claim Photo

Our File Number: 277-066516
Adjuster: Jason Baka
Insured: DASEKE RM LLC
Date of Loss: 01/16/2026
Customer File Number: 001960-278797-AP-01
Policy Number:



Photo: 41

Date Taken:
02/03/2026

Taken By:
Daniela Hunglinger

Description:
Front End



Photo: 42

Date Taken:
02/03/2026

Taken By:
Daniela Hunglinger

Description:
Left Front

Claim Photo

Our File Number: 277-066516
Adjuster: Jason Baka
Insured: DASEKE RM LLC
Date of Loss: 01/16/2026
Customer File Number: 001960-278797-AP-01
Policy Number:



Photo: 43

Date Taken:
02/03/2026

Taken By:
Daniela Hunglinger

Description:
Right Front




Photo: 44

Date Taken:
02/03/2026

Taken By:
Daniela Hunglinger

Description:
REAR END

Claim Photo

Our File Number: 277-066516
Adjuster: Jason Baka
Insured: DASEKE RM LLC
Date of Loss: 01/16/2026
Customer File Number: 001960-278797-AP-01
Policy Number:



Photo: 45

Date Taken:
02/03/2026

Taken By:
Daniela Hunglinger

Description:
RIGHT REAR



Photo: 46

Date Taken:
02/03/2026

Taken By:
Daniela Hunglinger

Description:
LEFT REAR

Claim Photo

Our File Number: 277-066516
Adjuster: Jason Baka
Insured: DASEKE RM LLC
Date of Loss: 01/16/2026
Customer File Number: 001960-278797-AP-01
Policy Number:



Photo: 47

Date Taken:
02/03/2026

Taken By:
Daniela Hunglinger

Description:
Left top-Damaged
area




Photo: 48

Date Taken:
02/03/2026

Taken By:
Daniela Hunglinger

Description:
Left Side of Roof,
Left Extender-
DAMAGE

Claim Photo

Our File Number: 277-066516
Adjuster: Jason Baka
Insured: DASEKE RM LLC
Date of Loss: 01/16/2026
Customer File Number: 001960-278797-AP-01
Policy Number:



Photo: 49

Date Taken:
02/03/2026

Taken By:
Daniela Hunglinger

Description:
view of left fuel
tank




Photo: 50

Date Taken:
02/03/2026

Taken By:
Daniela Hunglinger

Description:
Left Top extender-
DMGE

Claim Photo

Our File Number: 277-066516
Adjuster: Jason Baka
Insured: DASEKE RM LLC
Date of Loss: 01/16/2026
Customer File Number: 001960-278797-AP-01
Policy Number:



Photo: 51

Date Taken:
02/03/2026

Taken By:
Daniela Hunglinger

Description:
Damage to back
section of
panel/roof



Photo: 52

Date Taken:
02/03/2026

Taken By:
Daniela Hunglinger

Description:
Mudflap-DMGE

Claim Photo

Our File Number: 277-066516
Adjuster: Jason Baka
Insured: DASEKE RM LLC
Date of Loss: 01/16/2026
Customer File Number: 001960-278797-AP-01
Policy Number:



Photo: 53

Date Taken:
02/03/2026

Taken By:
Daniela Hunglinger

Description:
storage
compartment



Photo: 54

Date Taken:
02/03/2026

Taken By:
Daniela Hunglinger

Description:
Left Side Damage

Claim Photo

Our File Number: 277-066516
Adjuster: Jason Baka
Insured: DASEKE RM LLC
Date of Loss: 01/16/2026
Customer File Number: 001960-278797-AP-01
Policy Number:



Photo: 55

Date Taken:
02/03/2026

Taken By:
Daniela Hunglinger

Description:
Left Door, mirror
assy, left side
sleeper panel, left
top roof window
and panel-DMGE



Photo: 56

Date Taken:
02/03/2026

Taken By:
Daniela Hunglinger

Description:
LEFT SIDE
Damage panels

Claim Photo

Our File Number: 277-066516
Adjuster: Jason Baka
Insured: DASEKE RM LLC
Date of Loss: 01/16/2026
Customer File Number: 001960-278797-AP-01
Policy Number:



Photo: 57

Date Taken:
02/03/2026

Taken By:
Daniela Hunglinger

Description:
fuel tank-LEFT



Photo: 58

Date Taken:
02/03/2026

Taken By:
Daniela Hunglinger

Description:
Left Side Sleeper
transition panel-
dmge

Claim Photo

Our File Number: 277-066516
Adjuster: Jason Baka
Insured: DASEKE RM LLC
Date of Loss: 01/16/2026
Customer File Number: 001960-278797-AP-01
Policy Number:




Photo: 59

Date Taken:
02/03/2026

Taken By:
Daniela Hunglinger

Description:
LEFT SIDE
DAMAGE AREA



Photo: 60

Date Taken:
02/03/2026

Taken By:
Daniela Hunglinger

Description:
Left Hood/Fender,
Windshield and left
rear view mirror
(missing from
dmge)

Claim Photo

Our File Number: 277-066516
Adjuster: Jason Baka
Insured: DASEKE RM LLC
Date of Loss: 01/16/2026
Customer File Number: 001960-278797-AP-01
Policy Number:



Photo: 61

Date Taken:
02/03/2026

Taken By:
Daniela Hunglinger

Description:
Left Fender/Hood
Mirror, left area of
hood-DMGE



Photo: 62

Date Taken:
02/03/2026

Taken By:
Daniela Hunglinger

Description:
Left Headlamp-
Damage

Claim Photo

Our File Number: 277-066516
Adjuster: Jason Baka
Insured: DASEKE RM LLC
Date of Loss: 01/16/2026
Customer File Number: 001960-278797-AP-01
Policy Number:



Photo: 63

Date Taken:
02/03/2026

Taken By:
Daniela Hunglinger

Description:
Left End of bumper



Photo: 64

Date Taken:
02/03/2026

Taken By:
Daniela Hunglinger

Description:
Left End of Brush
Guard-DMGE

Claim Photo

Our File Number: 277-066516
Adjuster: Jason Baka
Insured: DASEKE RM LLC
Date of Loss: 01/16/2026
Customer File Number: 001960-278797-AP-01
Policy Number:



Photo: 65

Date Taken:
02/03/2026

Taken By:
Daniela Hunglinger

Description:
Left Sleeper-
DAMAGE



Photo: 66

Date Taken:
02/03/2026

Taken By:
Daniela Hunglinger

Description:
Left Skirt-DMGE

Claim Photo

Our File Number: 277-066516
Adjuster: Jason Baka
Insured: DASEKE RM LLC
Date of Loss: 01/16/2026
Customer File Number: 001960-278797-AP-01
Policy Number:




Photo: 67

Date Taken:
02/03/2026

Taken By:
Daniela Hunglinger

Description:
Left Sleeper Shock-
DMGE




Photo: 68

Date Taken:
02/03/2026

Taken By:
Daniela Hunglinger

Description:
bracket behind skirt
-LEFT

Claim Photo

Our File Number: 277-066516
Adjuster: Jason Baka
Insured: DASEKE RM LLC
Date of Loss: 01/16/2026
Customer File Number: 001960-278797-AP-01
Policy Number:



Photo: 69

Date Taken:
02/03/2026

Taken By:
Daniela Hunglinger

Description:
Left Rear outer
tires



Photo: 70

Date Taken:
02/03/2026

Taken By:
Daniela Hunglinger

Description:
Left Rear 2nd
Outer

Claim Photo

Our File Number: 277-066516
Adjuster: Jason Baka
Insured: DASEKE RM LLC
Date of Loss: 01/16/2026
Customer File Number: 001960-278797-AP-01
Policy Number:



Photo: 71

Date Taken:
02/03/2026

Taken By:
Daniela Hunglinger

Description:
Left 2nd outer



Photo: 72

Date Taken:
02/03/2026

Taken By:
Daniela Hunglinger

Description:
Right Rear Flap-
damage

Claim Photo

Our File Number: 277-066516
Adjuster: Jason Baka
Insured: DASEKE RM LLC
Date of Loss: 01/16/2026
Customer File Number: 001960-278797-AP-01
Policy Number:



Photo: 73

Date Taken:
02/03/2026

Taken By:
Daniela Hunglinger

Description:
marking on right
side rear




Photo: 74

Date Taken:
02/03/2026

Taken By:
Daniela Hunglinger

Description:
Left Rear

Claim Photo

Our File Number: 277-066516
Adjuster: Jason Baka
Insured: DASEKE RM LLC
Date of Loss: 01/16/2026
Customer File Number: 001960-278797-AP-01
Policy Number:




Photo: 75

Date Taken:
02/03/2026

Taken By:
Daniela Hunglinger

Description:
Right Rear



Photo: 76

Date Taken:
02/03/2026

Taken By:
Daniela Hunglinger

Description:
Right Side Damage

Claim Photo

Our File Number: 277-066516
Adjuster: Jason Baka
Insured: DASEKE RM LLC
Date of Loss: 01/16/2026
Customer File Number: 001960-278797-AP-01
Policy Number:



Photo: 77

Date Taken:
02/03/2026

Taken By:
Daniela Hunglinger

Description:
Right Sleeper
shock



Photo: 78

Date Taken:
02/03/2026

Taken By:
Daniela Hunglinger

Description:
Left Fender/Hood
mirror-DMGe

Claim Photo

Our File Number: 277-066516
Adjuster: Jason Baka
Insured: DASEKE RM LLC
Date of Loss: 01/16/2026
Customer File Number: 001960-278797-AP-01
Policy Number:



Photo: 79

Date Taken:
02/03/2026

Taken By:
Daniela Hunglinger

Description:
Left Fender, Cowl
and Trim-
DAMAGE



Photo: 80

Date Taken:
02/03/2026

Taken By:
Daniela Hunglinger

Description:
Engine
compartment (Left)

Claim Photo

Our File Number: 277-066516
Adjuster: Jason Baka
Insured: DASEKE RM LLC
Date of Loss: 01/16/2026
Customer File Number: 001960-278797-AP-01
Policy Number:



Photo: 81

Date Taken:
02/03/2026

Taken By:
Daniela Hunglinger

Description:
Engine
compartment
(right)



Photo: 82

Date Taken:
02/03/2026

Taken By:
Daniela Hunglinger

Description:
Left Front

Claim Photo

Our File Number: 277-066516
Adjuster: Jason Baka
Insured: DASEKE RM LLC
Date of Loss: 01/16/2026
Customer File Number: 001960-278797-AP-01
Policy Number:



Photo: 83

Date Taken:
02/03/2026

Taken By:
Daniela Hunglinger

Description:
right front bumper
bracket-damage



Photo: 84

Date Taken:
02/03/2026

Taken By:
Daniela Hunglinger

Description:
Oil spill all over the
engine area and
components

Claim Photo

Our File Number: 277-066516
Adjuster: Jason Baka
Insured: DASEKE RM LLC
Date of Loss: 01/16/2026
Customer File Number: 001960-278797-AP-01
Policy Number:



Photo: 85

Date Taken:
02/03/2026

Taken By:
Daniela Hunglinger

Description:
oil spill all over the
engine
compartment area




Photo: 86

Date Taken:
02/03/2026

Taken By:
Daniela Hunglinger

Description:
spill all over the
engine
compartment area
and hood inner side

Claim Photo

Our File Number: 277-066516
Adjuster: Jason Baka
Insured: DASEKE RM LLC
Date of Loss: 01/16/2026
Customer File Number: 001960-278797-AP-01
Policy Number:



Photo: 87

Date Taken:
02/03/2026

Taken By:
Daniela Hunglinger

Description:
Left inner
fender/hood-
DAMAGE



Photo: 88

Date Taken:
02/03/2026

Taken By:
Daniela Hunglinger

Description:
Left Front
suspension-DMGE

Claim Photo

Our File Number: 277-066516
Adjuster: Jason Baka
Insured: DASEKE RM LLC
Date of Loss: 01/16/2026
Customer File Number: 001960-278797-AP-01
Policy Number:



Photo: 89

Date Taken:
02/03/2026

Taken By:
Daniela Hunglinger

Description:
oil spill all over




Photo: 90

Date Taken:
02/03/2026

Taken By:
Daniela Hunglinger

Description:
condenser, radiator
cooling pack

Claim Photo

Our File Number: 277-066516
Adjuster: Jason Baka
Insured: DASEKE RM LLC
Date of Loss: 01/16/2026
Customer File Number: 001960-278797-AP-01
Policy Number:



Photo: 91

Date Taken:
02/03/2026

Taken By:
Daniela Hunglinger

Description:
left front spring-
dmge



Photo: 92

Date Taken:
02/03/2026

Taken By:
Daniela Hunglinger

Description:
left front spring

Claim Photo

Our File Number: 277-066516
Adjuster: Jason Baka
Insured: DASEKE RM LLC
Date of Loss: 01/16/2026
Customer File Number: 001960-278797-AP-01
Policy Number:



Photo: 93

Date Taken:
02/03/2026

Taken By:
Daniela Hunglinger

Description:
Left Cowl -DMGE



Photo: 94

Date Taken:
02/03/2026

Taken By:
Daniela Hunglinger

Description:
Engine tag

Claim Photo

Our File Number: 277-066516
Adjuster: Jason Baka
Insured: DASEKE RM LLC
Date of Loss: 01/16/2026
Customer File Number: 001960-278797-AP-01
Policy Number:



Photo: 95

Date Taken:
02/03/2026

Taken By:
Daniela Hunglinger

Description:
inner fender shield-
DMGE




Photo: 96

Date Taken:
02/03/2026

Taken By:
Daniela Hunglinger

Description:
Left Front Damage

Claim Photo

Our File Number: 277-066516
Adjuster: Jason Baka
Insured: DASEKE RM LLC
Date of Loss: 01/16/2026
Customer File Number: 001960-278797-AP-01
Policy Number:



Photo: 97

Date Taken:
02/03/2026

Taken By:
Daniela Hunglinger

Description:
2023 Kenworth -
Extensive Left Side
Damage and Right
Side



Photo: 98

Date Taken:
02/03/2026

Taken By:
Daniela Hunglinger

Description:
unit inspected at
Wiggins towing
Byers, Colorado .