

Photo Sheet

Iron Insurance Adjusters

7600 Crescent Lake Ct.

Fort Worth TX 76137

8177794970

Claims@ironadjusters.com



INSURED & INSPECTION ADDRESS

Pro Star Logistics Group Inc

35400 Antelope Road

Murrieta, CA 92563

Project/Claim: Iron Adjusters File Number: 26-00258 | Claim Number: ATL220554

Policy: 799514/01/2025

Date of Origin: 01/08/2026

Type of Inspection: Heavy Equipment

2007 Gillig G27D102N4 Transit
Bus | VIN: 15GGD271771078429

Date taken: 02/04/2026

Taken by: Garrett Cox

Front Left Corner



2007 Gillig G27D102N4 Transit
Bus | VIN: 15GGD271771078429

Date taken: 02/04/2026

Taken by: Garrett Cox

Rear Left Corner



Photo Sheet

Iron Insurance Adjusters

7600 Crescent Lake Ct.

Fort Worth TX 76137

8177794970

Claims@ironadjusters.com



INSURED & INSPECTION ADDRESS

Pro Star Logistics Group Inc

35400 Antelope Road

Murrieta, CA 92563

Project/Claim: Iron Adjusters File Number: 26-00258 | Claim Number: ATL220554

Policy: 799514/01/2025

Date of Origin: 01/08/2026

Type of Inspection: Heavy Equipment

2007 Gillig G27D102N4 Transit
Bus | VIN: 15GGD271771078429

Date taken: 02/04/2026

Taken by: Garrett Cox

Rear View



2007 Gillig G27D102N4 Transit
Bus | VIN: 15GGD271771078429

Date taken: 02/04/2026

Taken by: Garrett Cox

Rear Right Corner



Photo Sheet

Iron Insurance Adjusters

7600 Crescent Lake Ct.

Fort Worth TX 76137

8177794970

Claims@ironadjusters.com



INSURED & INSPECTION ADDRESS

Pro Star Logistics Group Inc

35400 Antelope Road

Murrieta, CA 92563

Project/Claim: Iron Adjusters File Number: 26-00258 | Claim Number: ATL220554

Policy: 799514/01/2025

Date of Origin: 01/08/2026

Type of Inspection: Heavy Equipment

2007 Gillig G27D102N4 Transit
Bus | VIN: 15GGD271771078429

Date taken: 02/04/2026

Taken by: Garrett Cox

Front Right Corner



2007 Gillig G27D102N4 Transit
Bus | VIN: 15GGD271771078429

Date taken: 02/04/2026

Taken by: Garrett Cox

Front View



Photo Sheet



Iron Insurance Adjusters
7600 Crescent Lake Ct.
Fort Worth TX 76137
8177794970
Claims@ironadjusters.com

INSURED & INSPECTION ADDRESS

Pro Star Logistics Group Inc
35400 Antelope Road
Murrieta, CA 92563

Project/Claim: Iron Adjusters File Number: 26-00258 | Claim Number: ATL220554
Policy: 799514/01/2025
Date of Origin: 01/08/2026
Type of Inspection: Heavy Equipment

2007 Gillig G27D102N4 Transit
Bus | VIN: 15GGD271771078429

Date taken: 02/04/2026

Taken by: Garrett Cox

VIN Tag | VIN:
15GGD271771078429

MANUFACTURED BY GILLIG CORP.			
HAYWARD, CA		DATE: 10/10/2007	
GVWR: 17,963	kg	39,600	lb.
GAWR: FRONT 6,623	kg	14,600	lb.
WITH 315-80R 22.5 J	TIRES, 8.25 X 22.5		RIMS
AT 724	kPa 105	psi COLD SINGLE	
GAWR: REAR 11,340	kg	25,000	lb.
WITH 315-80R 22.5 J	TIRES, 8.25 X 22.5		RIMS
AT 655	kPa 95	psi COLD DUAL	
THIS VEHICLE CONFORMS TO ALL APPLICABLE U.S. FEDERAL MOTOR VEHICLE SAFETY STANDARDS IN EFFECT ON THE DATE OF MANUFACTURE SHOWN ABOVE.			
VEHICLE I.D. NO.: 15GGD271771078429		MODEL: G27D102N4	
TYPE OF VEHICLE: BUS			
ENGINE NUMBER: 46799312			
CAPACITY: 39 + 40		PASSENGERS	
UNLADEN WEIGHT: 27,420		lb.	

2007 Gillig G27D102N4 Transit
Bus | VIN: 15GGD271771078429

Date taken: 02/04/2026

Taken by: Garrett Cox

Unit Number: 2715



Photo Sheet

Iron Insurance Adjusters

7600 Crescent Lake Ct.

Fort Worth TX 76137

8177794970

Claims@ironadjusters.com



INSURED & INSPECTION ADDRESS

Pro Star Logistics Group Inc

35400 Antelope Road

Murrieta, CA 92563

Project/Claim: Iron Adjusters File Number: 26-00258 | Claim Number: ATL220554

Policy: 799514/01/2025

Date of Origin: 01/08/2026

Type of Inspection: Heavy Equipment

2007 Gillig G27D102N4 Transit
Bus | VIN: 15GGD271771078429

Date taken: 02/04/2026

Taken by: Garrett Cox

No Miles - No Power



2007 Gillig G27D102N4 Transit
Bus | VIN: 15GGD271771078429

Date taken: 02/04/2026

Taken by: Garrett Cox

Dash Overview



Photo Sheet



Iron Insurance Adjusters
7600 Crescent Lake Ct.
Fort Worth TX 76137
8177794970
Claims@ironadjusters.com

INSURED & INSPECTION ADDRESS

Pro Star Logistics Group Inc
35400 Antelope Road
Murrieta, CA 92563


Project/Claim: Iron Adjusters File Number: 26-00258 | Claim Number: ATL220554
Policy: 799514/01/2025
Date of Origin: 01/08/2026
Type of Inspection: Heavy Equipment

2007 Gillig G27D102N4 Transit
Bus | VIN: 15GGD271771078429

Date taken: 02/04/2026

Taken by: Garrett Cox

Left Side Window Damaged



2007 Gillig G27D102N4 Transit
Bus | VIN: 15GGD271771078429

Date taken: 02/04/2026

Taken by: Garrett Cox

Rear Left Corner Damage Overview



Photo Sheet

Iron Insurance Adjusters

7600 Crescent Lake Ct.

Fort Worth TX 76137

8177794970

Claims@ironadjusters.com



INSURED & INSPECTION ADDRESS

Pro Star Logistics Group Inc

35400 Antelope Road

Murrieta, CA 92563

Project/Claim: Iron Adjusters File Number: 26-00258 | Claim Number: ATL220554

Policy: 799514/01/2025

Date of Origin: 01/08/2026

Type of Inspection: Heavy Equipment

2007 Gillig G27D102N4 Transit
Bus | VIN: 15GGD271771078429

Date taken: 02/04/2026

Taken by: Garrett Cox

Rear Left Corner Damage Overview



2007 Gillig G27D102N4 Transit
Bus | VIN: 15GGD271771078429

Date taken: 02/04/2026

Taken by: Garrett Cox

Top Damage & Damage To Roof



Photo Sheet

Iron Insurance Adjusters

7600 Crescent Lake Ct.

Fort Worth TX 76137

8177794970

Claims@ironadjusters.com



INSURED & INSPECTION ADDRESS

Pro Star Logistics Group Inc

35400 Antelope Road

Murrieta, CA 92563

Project/Claim: Iron Adjusters File Number: 26-00258 | Claim Number: ATL220554

Policy: 799514/01/2025

Date of Origin: 01/08/2026

Type of Inspection: Heavy Equipment

2007 Gillig G27D102N4 Transit
Bus | VIN: 15GGD271771078429

Date taken: 02/04/2026

Taken by: Garrett Cox

Rear Engine Cover Damage



2007 Gillig G27D102N4 Transit
Bus | VIN: 15GGD271771078429

Date taken: 02/04/2026

Taken by: Garrett Cox

Engine Bay Overview




Photo Sheet

Iron Insurance Adjusters

7600 Crescent Lake Ct.

Fort Worth TX 76137

8177794970

Claims@ironadjusters.com



INSURED & INSPECTION ADDRESS

Pro Star Logistics Group Inc

35400 Antelope Road

Murrieta, CA 92563

Project/Claim: Iron Adjusters File Number: 26-00258 | Claim Number: ATL220554

Policy: 799514/01/2025

Date of Origin: 01/08/2026

Type of Inspection: Heavy Equipment

2007 Gillig G27D102N4 Transit
Bus | VIN: 15GGD271771078429

Date taken: 02/04/2026

Taken by: Garrett Cox

Engine Regulator



2007 Gillig G27D102N4 Transit
Bus | VIN: 15GGD271771078429

Date taken: 02/04/2026

Taken by: Garrett Cox

Rear Left Corner Damage




Photo Sheet

Iron Insurance Adjusters

7600 Crescent Lake Ct.

Fort Worth TX 76137

8177794970

Claims@ironadjusters.com



INSURED & INSPECTION ADDRESS

Pro Star Logistics Group Inc

35400 Antelope Road

Murrieta, CA 92563

Project/Claim: Iron Adjusters File Number: 26-00258 | Claim Number: ATL220554

Policy: 799514/01/2025

Date of Origin: 01/08/2026

Type of Inspection: Heavy Equipment

2007 Gillig G27D102N4 Transit
Bus | VIN: 15GGD271771078429

Date taken: 02/04/2026

Taken by: Garrett Cox

Bumper Damage



2007 Gillig G27D102N4 Transit
Bus | VIN: 15GGD271771078429

Date taken: 02/04/2026

Taken by: Garrett Cox

Cooling System Damage




Photo Sheet

Iron Insurance Adjusters

7600 Crescent Lake Ct.

Fort Worth TX 76137

8177794970

Claims@ironadjusters.com



INSURED & INSPECTION ADDRESS

Pro Star Logistics Group Inc

35400 Antelope Road

Murrieta, CA 92563

Project/Claim: Iron Adjusters File Number: 26-00258 | Claim Number: ATL220554

Policy: 799514/01/2025

Date of Origin: 01/08/2026

Type of Inspection: Heavy Equipment

2007 Gillig G27D102N4 Transit
Bus | VIN: 15GGD271771078429

Date taken: 02/04/2026

Taken by: Garrett Cox

Cooling System Damage, Rear
Structor Frame Damage



2007 Gillig G27D102N4 Transit
Bus | VIN: 15GGD271771078429

Date taken: 02/04/2026

Taken by: Garrett Cox

Alr Ride & Panel Damage



Photo Sheet

Iron Insurance Adjusters

7600 Crescent Lake Ct.

Fort Worth TX 76137

8177794970

Claims@ironadjusters.com



INSURED & INSPECTION ADDRESS

Pro Star Logistics Group Inc

35400 Antelope Road

Murrieta, CA 92563

Project/Claim: Iron Adjusters File Number: 26-00258 | Claim Number: ATL220554

Policy: 799514/01/2025

Date of Origin: 01/08/2026

Type of Inspection: Heavy Equipment

2007 Gillig G27D102N4 Transit
Bus | VIN: 15GGD271771078429

Date taken: 02/04/2026

Taken by: Garrett Cox

Rear Frame & Panel Damage



2007 Gillig G27D102N4 Transit
Bus | VIN: 15GGD271771078429

Date taken: 02/04/2026

Taken by: Garrett Cox

Rear Frame & Panel Damage



Photo Sheet

Iron Insurance Adjusters

7600 Crescent Lake Ct.

Fort Worth TX 76137

8177794970

Claims@ironadjusters.com



INSURED & INSPECTION ADDRESS

Pro Star Logistics Group Inc

35400 Antelope Road

Murrieta, CA 92563

Project/Claim: Iron Adjusters File Number: 26-00258 | Claim Number: ATL220554

Policy: 799514/01/2025

Date of Origin: 01/08/2026

Type of Inspection: Heavy Equipment

2007 Gillig G27D102N4 Transit
Bus | VIN: 15GGD271771078429

Date taken: 02/04/2026

Taken by: Garrett Cox

Rear Frame & Panel Damage



2007 Gillig G27D102N4 Transit
Bus | VIN: 15GGD271771078429

Date taken: 02/04/2026

Taken by: Garrett Cox

Gellig Panel



Photo Sheet



Iron Insurance Adjusters
7600 Crescent Lake Ct.
Fort Worth TX 76137
8177794970
Claims@ironadjusters.com

INSURED & INSPECTION ADDRESS

Pro Star Logistics Group Inc
35400 Antelope Road
Murrieta, CA 92563

Project/Claim: Iron Adjusters File Number: 26-00258 | Claim Number: ATL220554
Policy: 799514/01/2025
Date of Origin: 01/08/2026
Type of Inspection: Heavy Equipment

2007 Gillig G27D102N4 Transit
Bus | VIN: 15GGD271771078429

Date taken: 02/04/2026

Taken by: Garrett Cox

Wheel & Tire Damage



2007 Gillig G27D102N4 Transit
Bus | VIN: 15GGD271771078429

Date taken: 02/04/2026

Taken by: Garrett Cox

Tire Tread 8/32nds



Photo Sheet



Iron Insurance Adjusters
7600 Crescent Lake Ct.
Fort Worth TX 76137
8177794970
Claims@ironadjusters.com

INSURED & INSPECTION ADDRESS

Pro Star Logistics Group Inc
35400 Antelope Road
Murrieta, CA 92563

Project/Claim: Iron Adjusters File Number: 26-00258 | Claim Number: ATL220554
Policy: 799514/01/2025
Date of Origin: 01/08/2026
Type of Inspection: Heavy Equipment

2007 Gillig G27D102N4 Transit
Bus | VIN: 15GGD271771078429

Date taken: 02/04/2026

Taken by: Garrett Cox

Tire Tread 10/32nds



2007 Gillig G27D102N4 Transit
Bus | VIN: 15GGD271771078429

Date taken: 02/04/2026

Taken by: Garrett Cox

Tire Tread 10/32nds



Photo Sheet



Iron Insurance Adjusters
7600 Crescent Lake Ct.
Fort Worth TX 76137
8177794970
Claims@ironadjusters.com

INSURED & INSPECTION ADDRESS

Pro Star Logistics Group Inc
35400 Antelope Road
Murrieta, CA 92563

Project/Claim: Iron Adjusters File Number: 26-00258 | Claim Number: ATL220554
Policy: 799514/01/2025
Date of Origin: 01/08/2026
Type of Inspection: Heavy Equipment

2007 Gillig G27D102N4 Transit
Bus | VIN: 15GGD271771078429

Date taken: 02/04/2026

Taken by: Garrett Cox

Tire Tread 6/32nds



2007 Gillig G27D102N4 Transit
Bus | VIN: 15GGD271771078429

Date taken: 02/04/2026

Taken by: Garrett Cox

Overview Inside The Bus




Photo Sheet



Iron Insurance Adjusters
7600 Crescent Lake Ct.
Fort Worth TX 76137
8177794970
Claims@ironadjusters.com

INSURED & INSPECTION ADDRESS

Pro Star Logistics Group Inc
35400 Antelope Road
Murrieta, CA 92563


Project/Claim: Iron Adjusters File Number: 26-00258 | Claim Number: ATL220554
Policy: 799514/01/2025
Date of Origin: 01/08/2026
Type of Inspection: Heavy Equipment

2007 Gillig G27D102N4 Transit
Bus | VIN: 15GGD271771078429

Date taken: 02/04/2026

Taken by: Garrett Cox

Overview Inside The Bus



2007 Gillig G27D102N4 Transit
Bus | VIN: 15GGD271771078429

Date taken: 02/04/2026

Taken by: Garrett Cox

Aution Sale Tag



Photo Sheet



Iron Insurance Adjusters
7600 Crescent Lake Ct.
Fort Worth TX 76137
8177794970
Claims@ironadjusters.com

INSURED & INSPECTION ADDRESS

Pro Star Logistics Group Inc
35400 Antelope Road
Murrieta, CA 92563


Project/Claim: Iron Adjusters File Number: 26-00258 | Claim Number: ATL220554
Policy: 799514/01/2025
Date of Origin: 01/08/2026
Type of Inspection: Heavy Equipment

2007 Gillig G27D102N4 Transit
Bus | VIN: 15GGD271771078429

Date taken: 02/05/2026

Taken by: Insured Provided Photo

Photo Provided By The Insured



2007 Gillig G27D102N4 Transit
Bus | VIN: 15GGD271771078429

Date taken: 02/05/2026

Taken by: Insured Provided Photo

Photo Provided By The Insured




Photo Sheet

Iron Insurance Adjusters

7600 Crescent Lake Ct.

Fort Worth TX 76137

8177794970

Claims@ironadjusters.com



INSURED & INSPECTION ADDRESS

Pro Star Logistics Group Inc

35400 Antelope Road

Murrieta, CA 92563

Project/Claim: Iron Adjusters File Number: 26-00258 | Claim Number: ATL220554

Policy: 799514/01/2025

Date of Origin: 01/08/2026

Type of Inspection: Heavy Equipment

2007 Gillig G27D102N4 Transit
Bus | VIN: 15GGD271771078429

Date taken: 02/05/2026

Taken by: Insured Provided Photo

Photo Provided By The Insured



2007 Gillig G27D102N4 Transit
Bus | VIN: 15GGD271771078429

Date taken: 02/05/2026

Taken by: Insured Provided Photo

Photo Provided By The Insured




Photo Sheet



Iron Insurance Adjusters
7600 Crescent Lake Ct.
Fort Worth TX 76137
8177794970
Claims@ironadjusters.com

INSURED & INSPECTION ADDRESS

Pro Star Logistics Group Inc
35400 Antelope Road
Murrieta, CA 92563

Project/Claim: Iron Adjusters File Number: 26-00258 | Claim Number: ATL220554
Policy: 799514/01/2025
Date of Origin: 01/08/2026
Type of Inspection: Heavy Equipment

2007 Gillig G27D102N4 Transit
Bus | VIN: 15GGD271771078429

Date taken: 02/05/2026

Taken by: Insured Provided Photo

Photo Provided By The Insured



2007 Gillig G27D102N4 Transit
Bus | VIN: 15GGD271771078429

Date taken: 02/05/2026

Taken by: Insured Provided Photo

Photo Provided By The Insured



Photo Sheet

Iron Insurance Adjusters

7600 Crescent Lake Ct.

Fort Worth TX 76137

8177794970

Claims@ironadjusters.com



INSURED & INSPECTION ADDRESS

Pro Star Logistics Group Inc

35400 Antelope Road

Murrieta, CA 92563

Project/Claim: Iron Adjusters File Number: 26-00258 | Claim Number: ATL220554

Policy: 799514/01/2025

Date of Origin: 01/08/2026

Type of Inspection: Heavy Equipment

2007 Gillig G27D102N4 Transit
Bus | VIN: 15GGD271771078429

Date taken: 02/05/2026

Taken by: Insured Provided Photo

Photo Provided By The Insured



2007 Gillig G27D102N4 Transit
Bus | VIN: 15GGD271771078429

Date taken: 02/05/2026

Taken by: Insured Provided Photo

Photo Provided By The Insured



IRONADJUSTERS
Heavy Equipment Insurance Adjusters

2007 Gillig G27D102N4 Transit
Bus | VIN: 15GGD271771078429

Taken by: Insured Provided Photo

Photo Provided By The Insured

Pro Star Logistics Group Inc
35400 Antelope Road
Murrieta, CA 92563

A photograph showing the severe damage to the rear of a blue and white bus. The rear section is crushed and mangled, with debris scattered on the ground. A red tow strap is visible attached to the wreckage.

2007 Gillig G27D102N4 Transit
Bus | VIN: 15GGD271771078429

Taken by: Insured Provided Photo

Photo Provided By The Insured

Bill of Lading

Ship From:
6314 N. Perry St.
Baltimore, MD 21207

SIC# ☐ FOB

Ship To: Location No:

24850 Antelope Rd
Murrelet, CA 92563

CID# ☐ FOB

Third Party Freight Charges - Bill To:

Date: 19-January-2008

Bill of Lading No. 1

BARCODE SPACE

Carrier Name: Acton

Trailer No:

Seal Number(s):

SIAC:

Pro No:

BARCODE SPACE

Freight Charge Terms (prepaid unless marked otherwise)

☐ Prepaid ☐ Collect ☐ 3rd Party

☐ Master BOL: Watchacted underlying BOLs

Special Instructions:

Customer Order No. # Weight: Pallets: 100

Confirmed Order Information

Additional Shipper Info

Totals

Hauling Unit		Package		Weight		H.M.C.		Description	
QTY	TYPE	QTY	TYPE	Weight	Unit	H.M.C.	Unit	Description	
				30000.00	Bus				

Confirmed Order Information

Commodity Description

Shipment description and classification are to be observed in forwarding, to be used for marking and packaging, and to be observed in the event of a claim.

LTL Only
NEMC
No. Class

30000.00 Totals

Please Note: In order to receive full insurance, all shipments are required to state specifically in writing the agreed or estimated value of the property to be shipped.

The agreed or estimated value of the property is specifically stated by the shipper in the "Weight" section of this bill.

NOTE: Liability Limitation for loss or damage in this shipment may be specified. See **SECTION 10, TRANSPORTATION AND BILL OF LADING**.

SECTION 10: Limitation of Liability for Loss or Damage in this Shipment. If the shipper desires to limit the liability of the carrier for loss or damage, the shipper must specify the agreed or estimated value of the property to be shipped in the "Weight" section of this bill. The agreed or estimated value of the property is specifically stated by the shipper in the "Weight" section of this bill.

It is hereby agreed that the above stated estimate of value is for the purpose of limiting the liability of the carrier for loss or damage in this shipment.

SHIPPER'S SIGNATURE: _____ DATE: _____

COO Amt. \$

Fee Terms: ☐ Collect ☐ Prepaid

☐ Customer Check Acceptable

Shipper Signature: _____

Carrier Label:

☐ By Shipper

☐ By Receiver

Freight Carrier:

☐ By Shipper

☐ By Receiver

☐ By Union Freight

Carrier Information: Please provide complete name, address, and telephone number of the carrier to whom bills of lading should be sent.

Carrier Name: _____ Address: _____

Carrier Telephone: _____

Bill of Lading

Bill of Lading

103-06
Jan 2008