



BRYMAK LLC
USDOT #3659978
MC: 1264958
VIN: #LJ311489
GWGT 80.000


Jan 27, 2025 at 1:14:18 PM

DOT info




Jan 27, 2025 at 1:23:18 PM
891 Implement Dr
Dickinson ND 58601
United States

confirmed mileage




VIN



GVW info



front and right side




front and left side



Jan 27, 2025 at 1:08:41 PM
891 Implement Dr
Dickinson ND 58601
United States

rear and right side



Jan 27, 2025 at 1:08:22 PM
891 Implement Dr
Dickinson ND 58601
United States

reaer and left side cab



Jan 27, 2025 at 1:07:12 PM
891 Implement Dr
Dickinson ND 58601
United States

left corner front numper and grille



Jan 27, 2025 at 1:07:17 PM
891 Implement Dr
Dickinson ND 58601
United States

left front corner suspension, hood and wheel



rear and right side




right rear tires and rims




Jan 27, 2025 at 1:08:18 PM
891 Implement Dr
Dickinson ND 58601
United States

left rear tires and rims



Jan 27, 2025 at 1:07:56 PM
891 Implement Dr
Dickinson ND 58601
United States

driver side seteps and battery box



small broken parts on display




bolted support to frame is cracked



left fender extension cracked



Init number and code name



Jan 27, 2025 at 1:14:32 PM
891 Implement Dr
Dickinson ND 58601
United States

left front tire slashed



Jan 27, 2025 at 1:08:52 PM
891 Implement Dr
Dickinson ND 58601
United States

APU



right side cracks in hood



Cummins X15 engine 450 horse



hoses and turbo pushed back from radiator



right front steer tire ruined



Jan 27, 2025 at 1:28:12 PM
891 Implement Dr
Dickinson ND 58601
United States

front fender extnsion on left side and driver mirror