

Claim Photo

Our File Number: 277-065698

Adjuster: Devon Karnitz

Insured: Trinity Transport Inc.

Date of Loss: 12/02/2025

Customer File Number: A00777462

Policy Number:

cia
CUSTARD
INSURANCE ADJUSTERS




Photo: 1

Date Taken:
12/22/2025

Taken By:
Marc Berman

Description:
vehicle registration
and Vin
#1DW1A5328ES4
99518




Photo: 2

Date Taken:
12/22/2025

Taken By:
Marc Berman

Description:
4 pt view of vehicle

Claim Photo

Our File Number: 277-065698
Adjuster: Devon Karnitz
Insured: Trinity Transport Inc.
Date of Loss: 12/02/2025
Customer File Number: A00777462
Policy Number:



Photo: 3

Date Taken:
12/22/2025

Taken By:
Marc Berman

Description:
rear view of vehicle



Photo: 4

Date Taken:
12/22/2025

Taken By:
Marc Berman

Description:
company logo

Claim Photo

Our File Number: 277-065698
Adjuster: Devon Karnitz
Insured: Trinity Transport Inc.
Date of Loss: 12/02/2025
Customer File Number: A00777462
Policy Number:



Photo: 5

Date Taken:
12/22/2025

Taken By:
Marc Berman

Description:
4 pt view of vehicle



Photo: 6

Date Taken:
12/22/2025

Taken By:
Marc Berman

Description:
trailer license plate

Claim Photo

Our File Number: 277-065698
Adjuster: Devon Karnitz
Insured: Trinity Transport Inc.
Date of Loss: 12/02/2025
Customer File Number: A00777462
Policy Number:

cia
CUSTARD
INSURANCE ADJUSTERS



Photo: 7

Date Taken:
12/22/2025

Taken By:
Marc Berman

Description:
rear view of vehicle




Photo: 8

Date Taken:
12/22/2025

Taken By:
Marc Berman

Description:
U bar damaged

Claim Photo

Our File Number: 277-065698

Adjuster: Devon Karnitz

Insured: Trinity Transport Inc.

Date of Loss: 12/02/2025

Customer File Number: A00777462

Policy Number:

cia
CUSTARD
INSURANCE ADJUSTERS



Photo: 9

Date Taken:
12/22/2025

Taken By:
Marc Berman

Description:
damage to back of
trailer drivers side



Photo: 10

Date Taken:
12/22/2025

Taken By:
Marc Berman

Description:
damage to back of
trailer drivers side

Claim Photo

Our File Number:

277-065698

Adjuster:

Devon Karnitz

Insured:

Trinity Transport Inc.

Date of Loss:

12/02/2025

Customer File Number: A00777462

Policy Number:

cia
CUSTARD
INSURANCE ADJUSTERS



Photo: 11

Date Taken:
12/22/2025

Taken By:
Marc Berman

Description:
inside trailer




Photo: 12

Date Taken:
12/22/2025

Taken By:
Marc Berman

Description:
damage to back of
trailer drivers side

Claim Photo

Our File Number: 277-065698
Adjuster: Devon Karnitz
Insured: Trinity Transport Inc.
Date of Loss: 12/02/2025
Customer File Number: A00777462
Policy Number:

cia
CUSTARD
INSURANCE ADJUSTERS



Photo: 13

Date Taken:
12/22/2025

Taken By:
Marc Berman

Description:
damage to back of
trailer drivers side



Photo: 14

Date Taken:
12/22/2025

Taken By:
Marc Berman

Description:
damage to back of
trailer drivers side

Claim Photo

Our File Number: 277-065698
Adjuster: Devon Karnitz
Insured: Trinity Transport Inc.
Date of Loss: 12/02/2025
Customer File Number: A00777462
Policy Number:

cia
CUSTARD
INSURANCE ADJUSTERS



Photo: 15

Date Taken:
12/22/2025

Taken By:
Marc Berman

Description:
damage to back of
trailer drivers side



Photo: 16

Date Taken:
12/22/2025

Taken By:
Marc Berman

Description:
damage to back of
trailer drivers side

Claim Photo

Our File Number: 277-065698
Adjuster: Devon Karnitz
Insured: Trinity Transport Inc.
Date of Loss: 12/02/2025
Customer File Number: A00777462
Policy Number:

cia
CUSTARD
INSURANCE ADJUSTERS



Photo: 17

Date Taken:
12/22/2025

Taken By:
Marc Berman

Description:
damage to back of
trailer drivers side



Photo: 18

Date Taken:
12/22/2025

Taken By:
Marc Berman

Description:
damage to back of
trailer drivers side

Claim Photo

Our File Number: 277-065698
Adjuster: Devon Karnitz
Insured: Trinity Transport Inc.
Date of Loss: 12/02/2025
Customer File Number: A00777462
Policy Number:



Photo: 19

Date Taken:
12/22/2025

Taken By:
Marc Berman

Description:
damage to back of
trailer drivers side



Photo: 20

Date Taken:
12/22/2025

Taken By:
Marc Berman

Description:
damage to back of
trailer drivers side

Claim Photo

Our File Number: 277-065698
Adjuster: Devon Karnitz
Insured: Trinity Transport Inc.
Date of Loss: 12/02/2025
Customer File Number: A00777462
Policy Number:

cia
CUSTARD
INSURANCE ADJUSTERS



Photo: 21

Date Taken:
12/22/2025

Taken By:
Marc Berman

Description:
4 pt view



Photo: 22

Date Taken:
12/22/2025

Taken By:
Marc Berman

Description:
rear drivers side
corner

Claim Photo

Our File Number: 277-065698
Adjuster: Devon Karnitz
Insured: Trinity Transport Inc.
Date of Loss: 12/02/2025
Customer File Number: A00777462
Policy Number:

cia
CUSTARD
INSURANCE ADJUSTERS



Photo: 23

Date Taken:
12/22/2025

Taken By:
Marc Berman

Description:
rear drivers side
corner



Photo: 24

Date Taken:
12/22/2025

Taken By:
Marc Berman

Description:
rear drivers side
corner

Claim Photo

Our File Number: 277-065698
Adjuster: Devon Karnitz
Insured: Trinity Transport Inc.
Date of Loss: 12/02/2025
Customer File Number: A00777462
Policy Number:

cia
CUSTARD
INSURANCE ADJUSTERS



Photo: 25

Date Taken:
12/22/2025

Taken By:
Marc Berman

Description:
rear drivers side
corner



Photo: 26

Date Taken:
12/22/2025

Taken By:
Marc Berman

Description:
rear drivers side
corner

Claim Photo

Our File Number: 277-065698
Adjuster: Devon Karnitz
Insured: Trinity Transport Inc.
Date of Loss: 12/02/2025
Customer File Number: A00777462
Policy Number:



Photo: 27

Date Taken:
12/22/2025

Taken By:
Marc Berman

Description:
damages from
inside trailer



Photo: 28

Date Taken:
12/22/2025

Taken By:
Marc Berman

Description:
damages from
inside trailer

Claim Photo

Our File Number: 277-065698
Adjuster: Devon Karnitz
Insured: Trinity Transport Inc.
Date of Loss: 12/02/2025
Customer File Number: A00777462
Policy Number:



Photo: 29

Date Taken:
12/22/2025

Taken By:
Marc Berman

Description:
damages from
inside trailer



Photo: 30

Date Taken:
12/22/2025

Taken By:
Marc Berman

Description:
damages from
inside trailer

Claim Photo

Our File Number: 277-065698
Adjuster: Devon Karnitz
Insured: Trinity Transport Inc.
Date of Loss: 12/02/2025
Customer File Number: A00777462
Policy Number:



Photo: 31

Date Taken:
12/22/2025

Taken By:
Marc Berman

Description:
pieces of trailer



Photo: 32

Date Taken:
12/22/2025

Taken By:
Marc Berman

Description:
damages to drivers
side rear corner

Claim Photo

Our File Number: 277-065698
Adjuster: Devon Karnitz
Insured: Trinity Transport Inc.
Date of Loss: 12/02/2025
Customer File Number: A00777462
Policy Number:



Photo: 33

Date Taken:
12/22/2025

Taken By:
Marc Berman

Description:
rear drivers side
wheels out of
alignment



Photo: 34

Date Taken:
12/22/2025

Taken By:
Marc Berman

Description:
rear drivers side
wheels out of
alignment

Claim Photo

Our File Number: 277-065698
Adjuster: Devon Karnitz
Insured: Trinity Transport Inc.
Date of Loss: 12/02/2025
Customer File Number: A00777462
Policy Number:

cia
CUSTARD
INSURANCE ADJUSTERS



Photo: 35

Date Taken:
12/22/2025

Taken By:
Marc Berman

Description:
rear license plate



Photo: 36

Date Taken:
12/22/2025

Taken By:
Marc Berman

Description:
underneath trailer

Claim Photo

Our File Number: 277-065698
Adjuster: Devon Karnitz
Insured: Trinity Transport Inc.
Date of Loss: 12/02/2025
Customer File Number: A00777462
Policy Number:



Photo: 37

Date Taken:
12/22/2025

Taken By:
Marc Berman

Description:
underneath trailer



Photo: 38

Date Taken:
12/22/2025

Taken By:
Marc Berman

Description:
4 pt view of trailer

Claim Photo

Our File Number: 277-065698
Adjuster: Devon Karnitz
Insured: Trinity Transport Inc.
Date of Loss: 12/02/2025
Customer File Number: A00777462
Policy Number:




Photo: 39

Date Taken:
12/22/2025

Taken By:
Marc Berman

Description:
crack to underneath
trailer



Photo: 40

Date Taken:
12/22/2025

Taken By:
Marc Berman

Description:
4 pt view of trailer

Claim Photo

Our File Number: 277-065698
Adjuster: Devon Karnitz
Insured: Trinity Transport Inc.
Date of Loss: 12/02/2025
Customer File Number: A00777462
Policy Number:

cia
CUSTARD
INSURANCE ADJUSTERS



Photo: 41

Date Taken:
12/22/2025

Taken By:
Marc Berman

Description:
4 pt view of trailer



Photo: 42

Date Taken:
12/22/2025

Taken By:
Marc Berman

Description:
inside of trailer
passenger side

Claim Photo

Our File Number: 277-065698
Adjuster: Devon Karnitz
Insured: Trinity Transport Inc.
Date of Loss: 12/02/2025
Customer File Number: A00777462
Policy Number:




Photo: 43

Date Taken:
12/22/2025

Taken By:
Marc Berman

Description:
rear door




Photo: 44

Date Taken:
12/22/2025

Taken By:
Marc Berman

Description:
inside of trailer

Claim Photo

Our File Number: 277-065698
Adjuster: Devon Karnitz
Insured: Trinity Transport Inc.
Date of Loss: 12/02/2025
Customer File Number: A00777462
Policy Number:



Photo: 45

Date Taken:
12/22/2025

Taken By:
Marc Berman

Description:
inside of trailer




Photo: 46

Date Taken:
12/22/2025

Taken By:
Marc Berman

Description:
inside of trailer

Claim Photo

Our File Number: 277-065698
Adjuster: Devon Karnitz
Insured: Trinity Transport Inc.
Date of Loss: 12/02/2025
Customer File Number: A00777462
Policy Number:



Photo: 47

Date Taken:
12/22/2025

Taken By:
Marc Berman

Description:
inside of trailer



Photo: 48

Date Taken:
12/22/2025

Taken By:
Marc Berman

Description:
inside of trailer

Claim Photo

Our File Number: 277-065698
Adjuster: Devon Karnitz
Insured: Trinity Transport Inc.
Date of Loss: 12/02/2025
Customer File Number: A00777462
Policy Number:

cia
CUSTARD
INSURANCE ADJUSTERS



Photo: 49

Date Taken:
12/22/2025

Taken By:
Marc Berman

Description:
rear drivers side
corner



Photo: 50

Date Taken:
12/22/2025

Taken By:
Marc Berman

Description:
rear U bar bent

Claim Photo

Our File Number: 277-065698
Adjuster: Devon Karnitz
Insured: Trinity Transport Inc.
Date of Loss: 12/02/2025
Customer File Number: A00777462
Policy Number:



Photo: 51

Date Taken:
12/22/2025

Taken By:
Marc Berman

Description:
rear of trailer