

Sedgwick
131 Saundersville Road
Hendersonville, TN 37075

Phone: (615) 590-1550 Phone: (615) 000-0000

Address:
City/State/Zip: Franklin, MI 48009
Phone: - -
Cell Phone: - -
Purchase Order:
Customer Number: 069710001205
Claim Contact: Dave Wilkerson
Contact Title: Employee
Contact Phone: (248) 310-5792 x
Contact Email:

VIN: E220238
Style: Material Handler
Plate/State: -
WMI: FIN:
Odometer:
Color:
Date Of Loss: 12/30/2025
Authorized By:
Claim Number: 2026P0008
RO:



Photo of Front



Photo of Right



Product Identification Tag.



Photo of Left



ROPS / Operators area



Right rear corner



The equipment frame is heavily rusted and worn.





Mast




Controls and Gauges



Damage to starter and wiring



Damage to multiple hydraulic lines and junctions




170_6+556_n_saginaw_st_pontiac_mi_48342.jpg

Multiple lines were exposed to heat before the fire was put out.




Area between the Mast and Drivers area



the fire happened in an area that is not easily accessible,
which is under the main body of the lift.

The equipment would need to be torn down to capture the
full scope of damage.



The area where the fire started below the operator station
and Mast