

Claim Photo

Our File Number: 277-066403
Adjuster: David Crans
Insured: Looks Great Services of MS Inc.
Date of Loss: 01/07/2026
Customer File Number: 001529-107519-AP-02
Policy Number:

cia
CUSTARD
INSURANCE ADJUSTERS



Photo: 9

Date Taken:
01/23/2026

Taken By:
Donald Traweek

Description:
Right rear corner of insured truck and attenuator.



Photo: 10

Date Taken:
01/23/2026

Taken By:
Donald Traweek

Description:
Left rear corner view of insured truck and attenuator.

Claim Photo

Our File Number: 277-066403
Adjuster: David Crans
Insured: Looks Great Services of MS Inc.
Date of Loss: 01/07/2026
Customer File Number: 001529-107519-AP-02
Policy Number:



Photo: 11

Date Taken:
01/23/2026

Taken By:
Donald Traweek

Description:
MS License plate
on insured truck.



Photo: 12

Date Taken:
01/23/2026

Taken By:
Donald Traweek

Description:
Attenuator
information.

Claim Photo

Our File Number: 277-066403
Adjuster: David Crans
Insured: Looks Great Services of MS Inc.
Date of Loss: 01/07/2026
Customer File Number: 001529-107519-AP-02
Policy Number:



Photo: 13

Date Taken:
01/23/2026

Taken By:
Donald Traweek

Description:
Attenuator info tag.



Photo: 14

Date Taken:
01/23/2026

Taken By:
Donald Traweek

Description:
Weld crack on
attenuator,

Claim Photo

Our File Number:

277-066403

Adjuster:

David Crans

Insured:

Looks Great Services of MS Inc.

Date of Loss:

01/07/2026

Customer File Number: 001529-107519-AP-02

Policy Number:

cia
CUSTARD
INSURANCE ADJUSTERS



Photo: 15

Date Taken:
01/23/2026

Taken By:
Donald Traweek

Description:



Photo: 16

Date Taken:
01/23/2026

Taken By:
Donald Traweek

Description:
Damaged left side tail lamp bracket on attenuator.

Claim Photo

Our File Number: 277-066403
Adjuster: David Crans
Insured: Looks Great Services of MS Inc.
Date of Loss: 01/07/2026
Customer File Number: 001529-107519-AP-02
Policy Number:



Photo: 17

Date Taken:
01/23/2026

Taken By:
Donald Traweek

Description:
Crack in weld on attenuator.



Photo: 18

Date Taken:
01/23/2026

Taken By:
Donald Traweek

Description:
Small crack in weld
on attenuator.

Claim Photo

Our File Number: 277-066403
Adjuster: David Crans
Insured: Looks Great Services of MS Inc.
Date of Loss: 01/07/2026
Customer File Number: 001529-107519-AP-02
Policy Number:



Photo: 19

Date Taken:
01/23/2026

Taken By:
Donald Traweek

Description:
Minor damage to
attenuator framing.



Photo: 20

Date Taken:
01/23/2026

Taken By:
Donald Traweek

Description:
Small crack in weld
on left side at
mount of
attenuator.

Claim Photo

Our File Number: 277-066403
Adjuster: David Crans
Insured: Looks Great Services of MS Inc.
Date of Loss: 01/07/2026
Customer File Number: 001529-107519-AP-02
Policy Number:



Photo: 21

Date Taken:
01/23/2026

Taken By:
Donald Traweek

Description:
Damaged right side tail lamp bracket on attenuator.



Photo: 22

Date Taken:
01/23/2026

Taken By:
Donald Traweek

Description:
Right side attenuator mount.

Claim Photo

Our File Number: 277-066403
Adjuster: David Crans
Insured: Looks Great Services of MS Inc.
Date of Loss: 01/07/2026
Customer File Number: 001529-107519-AP-02
Policy Number:

cia
CUSTARD
INSURANCE ADJUSTERS



Photo: 23

Date Taken:
01/23/2026

Taken By:
Donald Traweek

Description:
Rear view of
attenuator.



Photo: 24

Date Taken:
01/23/2026

Taken By:
Donald Traweek

Description:
Right side
mounting point of
attenuator, appears
to have slight bow.

Claim Photo

Our File Number: 277-066403
Adjuster: David Crans
Insured: Looks Great Services of MS Inc.
Date of Loss: 01/07/2026
Customer File Number: 001529-107519-AP-02
Policy Number:



Photo: 25

Date Taken:
01/23/2026

Taken By:
Donald Traweek

Description:
Left side of attenuator at mounting point which may have slight bow.



Photo: 26

Date Taken:
01/23/2026

Taken By:
Donald Traweek

Description:

Claim Photo

Our File Number: 277-066403
Adjuster: David Crans
Insured: Looks Great Services of MS Inc.
Date of Loss: 01/07/2026
Customer File Number: 001529-107519-AP-02
Policy Number:



Photo: 27

Date Taken:
01/23/2026

Taken By:
Donald Traweek

Description:
Front of insured unit



Photo: 28

Date Taken:
01/23/2026

Taken By:
Donald Traweek

Description:
Left side view of engine, no engine label.

Claim Photo

Our File Number: 277-066403
Adjuster: David Crans
Insured: Looks Great Services of MS Inc.
Date of Loss: 01/07/2026
Customer File Number: 001529-107519-AP-02
Policy Number:



Photo: 29

Date Taken:
01/23/2026

Taken By:
Donald Traweek

Description:
Right side view of engine.



Photo: 30

Date Taken:
01/23/2026

Taken By:
Donald Traweek

Description:
Grease pencil on right front of frame rail showing VIN.

Claim Photo

Our File Number: 277-066403
Adjuster: David Crans
Insured: Looks Great Services of MS Inc.
Date of Loss: 01/07/2026
Customer File Number: 001529-107519-AP-02
Policy Number:



Photo: 31

Date Taken:
01/23/2026

Taken By:
Donald Traweek

Description:
Left front steer tire measurement.



Photo: 32

Date Taken:
01/23/2026

Taken By:
Donald Traweek

Description:
Right steer tire measurement,
15/32.

Claim Photo

Our File Number: 277-066403
Adjuster: David Crans
Insured: Looks Great Services of MS Inc.
Date of Loss: 01/07/2026
Customer File Number: 001529-107519-AP-02
Policy Number:



Photo: 33

Date Taken:
01/23/2026

Taken By:
Donald Traweek

Description:
Left rear outer tire
measurement,
24/32.



Photo: 34

Date Taken:
01/23/2026

Taken By:
Donald Traweek

Description:
Left rear inner tire
measurement,
24/32.

Claim Photo

Our File Number: 277-066403
Adjuster: David Crans
Insured: Looks Great Services of MS Inc.
Date of Loss: 01/07/2026
Customer File Number: 001529-107519-AP-02
Policy Number:



Photo: 35

Date Taken:
01/23/2026

Taken By:
Donald Traweek

Description:
Right rear outer tire
measurement,
24/32.



Photo: 36

Date Taken:
01/23/2026

Taken By:
Donald Traweek

Description:
Right rear inner tire
measurement,
23/32.

Claim Photo

Our File Number: 277-066403
Adjuster: David Crans
Insured: Looks Great Services of MS Inc.
Date of Loss: 01/07/2026
Customer File Number: 001529-107519-AP-02
Policy Number:

cia
CUSTARD
INSURANCE ADJUSTERS



Photo: 37

Date Taken:
01/23/2026

Taken By:
Donald Traweek

Description:
Inside steel wheels.




Photo: 38

Date Taken:
01/23/2026

Taken By:
Donald Traweek

Description:
Old left side hood damage.

Claim Photo

Our File Number: 277-066403
Adjuster: David Crans
Insured: Looks Great Services of MS Inc.
Date of Loss: 01/07/2026
Customer File Number: 001529-107519-AP-02
Policy Number:



Photo: 39

Date Taken:
01/23/2026

Taken By:
Donald Traweek

Description:
Right side view of insured unit with attenuator in down position.



Photo: 40

Date Taken:
01/23/2026

Taken By:
Donald Traweek

Description:
Left side view of insured unit.