

December 12, 2025

First Report

c/o Davies Group - Austin
c/o Davies Claims North America, Inc. 4500 South 129th East Avenue, Suite 132 East
Tulsa, OK 74134

Re:	Named Insured	:	SPIRIT 503 FREIGHT LINE LLC
	Date of Loss	:	11/11/2025
	Company Claim #	:	261.218
	Our File #	:	2700.2645
	Vehicle Description	:	2016 Great Dane Trailer, VIN: B704825

COVERAGE

Our assignment notes the involved vehicle as a 2016 Great Dane Dry Van Trailer, VIN: 1GRAA0627GB704825.

DAMAGES

We are in receipt of the photographs provided by your office. The photographs document damage to the trailer. The scope of the damage includes the side panels, posts, upper rails, roof panel, roof bows, J molding, interior panel, emblem and sealant.

Enclosed is an appraisal for the visible damage in the amount of \$23,046.21. There is potential for supplemental damage should a tear down inspection be performed. We searched online for comparable trailers and located units with resale values ranging from \$15,000.00 to \$25,000.00. The trailer appears to be a total loss.

FURTHER WORK

We are closing our file at this time. Thank you for allowing us to be of service. If we can be of any further assistance, please advise.

Sincerely,

Kendall Berry

Kendall Berry
kendal.berry@us.davies-group.com



Transportation Truck & Cargo Adjusters

4500 South 129th East Avenue, Suite 132 East

Tulsa, OK 74134

Phone: (918) 455-3900 Fax: (918) 455-7460

Date: 12/12/2025
Reference #: 037540014391
Estimated By: Kendal Berry
Name: SPIRIT 503 FREIGHT LINE LLC

Year: 2016
Make: Great Dane
Model: T680
Unit #:

Address:
City/State/Zip: ,
Phone: - -
Inspected Date:
Claimant:
Date of Loss: 11/11/2025
Claim Contact:
Contact Title:
Contact Phone: x
Contact Email:

VIN: 1GRAA0627GB704825
Style: Dry Freight/Reefer/Insulated
Plate/State: -
WMI: FIN:
Odometer:
Color:
Date Of Loss: 11/11/2025
Inspected At:
Claim Number: 261.218
File Number: 2700.2645

Operation		Description	Part #	Type	Labor	Paint	-----Parts-----	Misc
----- Side Panels -----								
1	*	Replace	Side Panel - Additional (Right)	New	8.00		2 @ \$238.57	\$477.14
2	*	Replace	Inner Post (Right)	New	8.00		4 @ \$108.84	\$435.36
----- Upper Rail -----								
3		Replace	Upper Rail 53' (Left)	New	22.90		1 @ \$1,892.12	\$1,892.12
4		Replace	Upper Rail 53' (Right)	New	22.90		1 @ \$1,892.12	\$1,892.12
----- Roof -----								
5		Replace	Roof Panel 53'	New	26.50		1 @ \$1,448.50	\$1,448.50
6	*	Replace	SEM Metal Bite Finishing Glaze	Mtrls AddPrt			1 @ \$88.42	\$88.42
7	*	Replace	Roof Bow (Each)	New	2.50		5 @ \$45.73	\$228.65
8	^	Replace	J Molding	New			1 @ \$234.16	\$234.16
----- Interior Walls -----								
9	*	Replace	Insert, Steel Panel (Right)	New	13.00		3 @ \$326.89	\$980.67
----- Custom Services -----								
10	^	Replace	Enviromental Fee	New			1 @ \$556.60	\$556.60
11	^	Replace	Great Dane Emblem	New	0.50		1 @ \$84.19	\$84.19
12			Fasteners	CS			1 @ \$500.00	\$500.00
----- Calculated Values -----								
13	^		Shop Supplies	Mtrls				\$1,391.50

An '*' indicates user change of database part and '^' indicates manually entered or custom database rows.

Estimate Notes:



Transportation Truck & Cargo Adjusters

4500 South 129th East Avenue, Suite 132 East

Tulsa, OK 74134

Phone: (918) 455-3900 Fax: (918) 455-7460

Date:	12/12/2025	Year:	2016
Reference #:	037540014391	Make:	Great Dane
Estimated By:	Kendal Berry	Model:	T680
Name:	SPIRIT 503 FREIGHT LINE LLC	Unit #:	

Summary	Amount	Rate	Disc	Total
Body Labor	104.3	\$115.00	0.00%	\$11,994.50
Paint Labor	0.0	\$115.00	0.00%	\$0.00
Mechanical	0.0	\$115.00	0.00%	\$0.00
Frame	0.0	\$115.00	0.00%	\$0.00
Misc. Labor	0.0	\$0.00	0.00%	\$0.00
Parts	\$8,817.93		0.00%	\$8,817.93
Misc.				\$1,391.50
Sub-total				\$22,203.93
Sales Tax	State (Parts, Materials) \$10,209.43 @ 8.2500%: \$842.28			842.28

Total	\$23,046.21
Betterment	\$0.00
Deductible	\$0.00
Grand Total	\$23,046.21

Repair Facility:

Address:

Phone: () -

Email:

Agreed With:

License 1:

License 2:

Fed Tax ID:

Registration #:

Appraised By: Kendal Berry

License #1:

License #2:

Phone: 918-455-3900

Email: kendal.berry@us.davis-group.com



Transportation Truck & Cargo Adjusters

4500 South 129th East Avenue, Suite 132 East

Tulsa, OK 74134

Phone: (918) 455-3900 Fax: (918) 455-7460

Date:	12/12/2025	Year:	2016
Reference #:	037540014391	Make:	Great Dane
Estimated By:	Kendal Berry	Model:	T680
Name:	SPIRIT 503 FREIGHT LINE LLC	Unit #:	

TERMS & CONDITIONS

The above is an estimate based on inspection and does not cover additional parts or labor which may be required after the work has been started. Occasionally worn or damaged parts are discovered which may not have been evident on the first inspection. Because of this, the above prices are not guaranteed. Quotations on parts and labor are current and subject to change.

Signed _____ Date _____









































