

Claim Photo

Our File Number: 277-065404
Adjuster: Devon Karnitz
Insured: Arturo Lozano-Lugo
Date of Loss:
Customer File Number: 235502809
Policy Number:



Photo: 1
Date Taken: 12/16/2025
Taken By: Gregory Spillman
Description: 2006 Volvo VIN label. 4V4NC9GHX6N443821




Photo: 2
Date Taken: 12/16/2025
Taken By: Gregory Spillman
Description: Information label. Production October 2005.

Claim Photo

Our File Number: 277-065404
Adjuster: Devon Karnitz
Insured: Arturo Lozano-Lugo
Date of Loss:
Customer File Number: 235502809
Policy Number:




Photo: 3

Date Taken:
12/16/2025

Taken By:
Gregory Spillman

Description:
Information label:
Engine is VE D12-465 Transmission is FRO-16210C 10 speed.




Photo: 4

Date Taken:
12/16/2025

Taken By:
Gregory Spillman

Description:
Information label:

Claim Photo

Our File Number: 277-065404
Adjuster: Devon Karnitz
Insured: Arturo Lozano-Lugo
Date of Loss:
Customer File Number: 235502809
Policy Number:



Photo: 5

Date Taken:
12/16/2025

Taken By:
Gregory Spillman

Description:
Ignition key did not
actuate odometer.




Photo: 6

Date Taken:
12/16/2025

Taken By:
Gregory Spillman

Description:
Odometer did not
illuminate.

Claim Photo

Our File Number: 277-065404
Adjuster: Devon Karnitz
Insured: Arturo Lozano-Lugo
Date of Loss:
Customer File Number: 235502809
Policy Number:



Photo: 7

Date Taken:
12/16/2025

Taken By:
Gregory Spillman

Description:
Information label
on left upper corner
of windshield



Photo: 8

Date Taken:
12/16/2025

Taken By:
Gregory Spillman

Description:
Driver door panel

Claim Photo

Our File Number: 277-065404
Adjuster: Devon Karnitz
Insured: Arturo Lozano-Lugo
Date of Loss:
Customer File Number: 235502809
Policy Number:



Photo: 9

Date Taken:
12/16/2025

Taken By:
Gregory Spillman

Description:
Steering wheel



Photo: 10

Date Taken:
12/16/2025

Taken By:
Gregory Spillman

Description:
Center instrument
panel

Claim Photo

Our File Number: 277-065404
Adjuster: Devon Karnitz
Insured: Arturo Lozano-Lugo
Date of Loss:
Customer File Number: 235502809
Policy Number:



Photo: 11

Date Taken:
12/16/2025

Taken By:
Gregory Spillman

Description:
Eaton Fuller shifter.



Photo: 12

Date Taken:
12/16/2025

Taken By:
Gregory Spillman

Description:
Driver floor under
instrument panel.

Claim Photo

Our File Number: 277-065404
Adjuster: Devon Karnitz
Insured: Arturo Lozano-Lugo
Date of Loss:
Customer File Number: 235502809
Policy Number:



Photo: 13

Date Taken:
12/16/2025

Taken By:
Gregory Spillman

Description:
Passenger side
instrument panel




Photo: 14

Date Taken:
12/16/2025

Taken By:
Gregory Spillman

Description:
Passenger seat.

Claim Photo

Our File Number: 277-065404
Adjuster: Devon Karnitz
Insured: Arturo Lozano-Lugo
Date of Loss:
Customer File Number: 235502809
Policy Number:




Photo: 15

Date Taken:
12/16/2025

Taken By:
Gregory Spillman

Description:
Driver seat




Photo: 16

Date Taken:
12/16/2025

Taken By:
Gregory Spillman

Description:
Sleeper

Claim Photo

Our File Number: 277-065404
Adjuster: Devon Karnitz
Insured: Arturo Lozano-Lugo
Date of Loss:
Customer File Number: 235502809
Policy Number:



Photo: 17

Date Taken:
12/16/2025

Taken By:
Gregory Spillman

Description:
Sleeper



Photo: 18

Date Taken:
12/16/2025

Taken By:
Gregory Spillman

Description:
Sleeper

Claim Photo

Our File Number: 277-065404
Adjuster: Devon Karnitz
Insured: Arturo Lozano-Lugo
Date of Loss:
Customer File Number: 235502809
Policy Number:



Photo: 19

Date Taken:
12/16/2025

Taken By:
Gregory Spillman

Description:
Sleeper



Photo: 20

Date Taken:
12/16/2025

Taken By:
Gregory Spillman

Description:
Sleeper

Claim Photo

Our File Number: 277-065404
Adjuster: Devon Karnitz
Insured: Arturo Lozano-Lugo
Date of Loss:
Customer File Number: 235502809
Policy Number:



Photo: 21

Date Taken:
12/16/2025

Taken By:
Gregory Spillman

Description:
Sunroof over forward cab



Photo: 22

Date Taken:
12/16/2025

Taken By:
Gregory Spillman

Description:
Shift pattern

Claim Photo

Our File Number: 277-065404
Adjuster: Devon Karnitz
Insured: Arturo Lozano-Lugo
Date of Loss:
Customer File Number: 235502809
Policy Number:



Photo: 23

Date Taken:
12/16/2025

Taken By:
Gregory Spillman

Description:
License plate



Photo: 24

Date Taken:
12/16/2025

Taken By:
Gregory Spillman

Description:
Inner front wheel

Claim Photo

Our File Number: 277-065404
Adjuster: Devon Karnitz
Insured: Arturo Lozano-Lugo
Date of Loss:
Customer File Number: 235502809
Policy Number:



Photo: 25

Date Taken:
12/16/2025

Taken By:
Gregory Spillman

Description:
Between tandem
wheels.



Photo: 26

Date Taken:
12/16/2025

Taken By:
Gregory Spillman

Description:
Inner rear tandem
wheel

Claim Photo

Our File Number: 277-065404
Adjuster: Devon Karnitz
Insured: Arturo Lozano-Lugo
Date of Loss:
Customer File Number: 235502809
Policy Number:



Photo: 27

Date Taken:
12/16/2025

Taken By:
Gregory Spillman

Description:
Driver seat



Photo: 28

Date Taken:
12/16/2025

Taken By:
Gregory Spillman

Description:
Placard

Claim Photo

Our File Number: 277-065404
Adjuster: Devon Karnitz
Insured: Arturo Lozano-Lugo
Date of Loss:
Customer File Number: 235502809
Policy Number:



Photo: 29

Date Taken:
12/16/2025

Taken By:
Gregory Spillman

Description:
Left front corner



Photo: 30

Date Taken:
12/16/2025

Taken By:
Gregory Spillman

Description:
Right front corner

Claim Photo

Our File Number: 277-065404
Adjuster: Devon Karnitz
Insured: Arturo Lozano-Lugo
Date of Loss:
Customer File Number: 235502809
Policy Number:



Photo: 31

Date Taken:
12/16/2025

Taken By:
Gregory Spillman

Description:
Left rear corner



Photo: 32

Date Taken:
12/16/2025

Taken By:
Gregory Spillman

Description:
Right rear corner

Claim Photo

Our File Number: 277-065404
Adjuster: Devon Karnitz
Insured: Arturo Lozano-Lugo
Date of Loss:
Customer File Number: 235502809
Policy Number:



Photo: 33

Date Taken:
12/16/2025

Taken By:
Gregory Spillman

Description:
Facing rear frame




Photo: 34

Date Taken:
12/16/2025

Taken By:
Gregory Spillman

Description:
Fifth wheel plate

Claim Photo

Our File Number: 277-065404
Adjuster: Devon Karnitz
Insured: Arturo Lozano-Lugo
Date of Loss:
Customer File Number: 235502809
Policy Number:



Photo: 35

Date Taken:
12/16/2025

Taken By:
Gregory Spillman

Description:
Fifth wheel plate



Photo: 36

Date Taken:
12/16/2025

Taken By:
Gregory Spillman

Description:
Right side damage

Claim Photo

Our File Number: 277-065404
Adjuster: Devon Karnitz
Insured: Arturo Lozano-Lugo
Date of Loss:
Customer File Number: 235502809
Policy Number:



Photo: 37

Date Taken:
12/16/2025

Taken By:
Gregory Spillman

Description:
Right side damage



Photo: 38

Date Taken:
12/16/2025

Taken By:
Gregory Spillman

Description:
Right side damage

Claim Photo

Our File Number: 277-065404
Adjuster: Devon Karnitz
Insured: Arturo Lozano-Lugo
Date of Loss:
Customer File Number: 235502809
Policy Number:




Photo: 39

Date Taken:
12/16/2025

Taken By:
Gregory Spillman

Description:
Right side damage



Photo: 40

Date Taken:
12/16/2025

Taken By:
Gregory Spillman

Description:
Right side damage

Claim Photo

Our File Number: 277-065404
Adjuster: Devon Karnitz
Insured: Arturo Lozano-Lugo
Date of Loss:
Customer File Number: 235502809
Policy Number:



Photo: 41

Date Taken:
12/16/2025

Taken By:
Gregory Spillman

Description:
Right side damage



Photo: 42

Date Taken:
12/16/2025

Taken By:
Gregory Spillman

Description:
Right side damage

Claim Photo

Our File Number: 277-065404
Adjuster: Devon Karnitz
Insured: Arturo Lozano-Lugo
Date of Loss:
Customer File Number: 235502809
Policy Number:




Photo: 43

Date Taken:
12/16/2025

Taken By:
Gregory Spillman

Description:
Front suspension
damage



Photo: 44

Date Taken:
12/16/2025

Taken By:
Gregory Spillman

Description:
Left front corner
damage

Claim Photo

Our File Number: 277-065404
Adjuster: Devon Karnitz
Insured: Arturo Lozano-Lugo
Date of Loss:
Customer File Number: 235502809
Policy Number:



Photo: 45

Date Taken:
12/16/2025

Taken By:
Gregory Spillman

Description:
Left side damage



Photo: 46

Date Taken:
12/16/2025

Taken By:
Gregory Spillman

Description:
Left side damage

Claim Photo

Our File Number: 277-065404
Adjuster: Devon Karnitz
Insured: Arturo Lozano-Lugo
Date of Loss:
Customer File Number: 235502809
Policy Number:



Photo: 47

Date Taken:
12/16/2025

Taken By:
Gregory Spillman

Description:
Left side step and
battery damage



Photo: 48

Date Taken:
12/16/2025

Taken By:
Gregory Spillman

Description:
Left lower damage

Claim Photo

Our File Number: 277-065404
Adjuster: Devon Karnitz
Insured: Arturo Lozano-Lugo
Date of Loss:
Customer File Number: 235502809
Policy Number:



Photo: 49

Date Taken:
12/16/2025

Taken By:
Gregory Spillman

Description:
Left front steer tire




Photo: 50

Date Taken:
12/16/2025

Taken By:
Gregory Spillman

Description:
Front suspension
damage

Claim Photo

Our File Number: 277-065404
Adjuster: Devon Karnitz
Insured: Arturo Lozano-Lugo
Date of Loss:
Customer File Number: 235502809
Policy Number:



Photo: 51

Date Taken:
12/16/2025

Taken By:
Gregory Spillman

Description:
Engine from underneath. Hood is jammed and will not open.




Photo: 52

Date Taken:
12/16/2025

Taken By:
Gregory Spillman

Description:
Front suspension damage

Claim Photo

Our File Number: 277-065404
Adjuster: Devon Karnitz
Insured: Arturo Lozano-Lugo
Date of Loss:
Customer File Number: 235502809
Policy Number:



Photo: 53

Date Taken:
12/16/2025

Taken By:
Gregory Spillman

Description:
Front suspension
damage




Photo: 54

Date Taken:
12/16/2025

Taken By:
Gregory Spillman

Description:
Facing back of
truck from
underneath

Claim Photo

Our File Number: 277-065404
Adjuster: Devon Karnitz
Insured: Arturo Lozano-Lugo
Date of Loss:
Customer File Number: 235502809
Policy Number:



Photo: 55

Date Taken:
12/16/2025

Taken By:
Gregory Spillman

Description:
Facing back of
truck from
underneath



Photo: 56

Date Taken:
12/16/2025

Taken By:
Gregory Spillman

Description:
Left front leaf
spring

Claim Photo

Our File Number: 277-065404
Adjuster: Devon Karnitz
Insured: Arturo Lozano-Lugo
Date of Loss:
Customer File Number: 235502809
Policy Number:



Photo: 57

Date Taken:
12/16/2025

Taken By:
Gregory Spillman

Description:
LF steer tire 12/32



Photo: 58

Date Taken:
12/16/2025

Taken By:
Gregory Spillman

Description:
LFO 20/32

Claim Photo

Our File Number: 277-065404
Adjuster: Devon Karnitz
Insured: Arturo Lozano-Lugo
Date of Loss:
Customer File Number: 235502809
Policy Number:




Photo: 59

Date Taken:
12/16/2025

Taken By:
Gregory Spillman

Description:
LFI 16/32



Photo: 60

Date Taken:
12/16/2025

Taken By:
Gregory Spillman

Description:
LRO 0/32

Claim Photo

Our File Number: 277-065404
Adjuster: Devon Karnitz
Insured: Arturo Lozano-Lugo
Date of Loss:
Customer File Number: 235502809
Policy Number:



Photo: 61

Date Taken:
12/16/2025

Taken By:
Gregory Spillman

Description:
LRI 4/32



Photo: 62

Date Taken:
12/16/2025

Taken By:
Gregory Spillman

Description:
RF steer tire 16/32

Claim Photo

Our File Number: 277-065404
Adjuster: Devon Karnitz
Insured: Arturo Lozano-Lugo
Date of Loss:
Customer File Number: 235502809
Policy Number:



Photo: 63

Date Taken:
12/16/2025

Taken By:
Gregory Spillman

Description:
RFO 8/32




Photo: 64

Date Taken:
12/16/2025

Taken By:
Gregory Spillman

Description:
RFI 8/32

Claim Photo

Our File Number: 277-065404
Adjuster: Devon Karnitz
Insured: Arturo Lozano-Lugo
Date of Loss:
Customer File Number: 235502809
Policy Number:



Photo: 65

Date Taken:
12/16/2025

Taken By:
Gregory Spillman

Description:
RRO 4/32



Photo: 66

Date Taken:
12/16/2025

Taken By:
Gregory Spillman

Description:
RRI 4/32