

Claim Photo

Our File Number: 277-065823
Adjuster: Mike Hogan
Insured: WSB LLC
Date of Loss: 11/21/2025
Customer File Number: 5630127428
Policy Number:



Photo: 1

Date Taken:
12/31/2025

Taken By:
Sheila Allen

Description:
Insured vehicle
VIN




Photo: 2

Date Taken:
12/31/2025

Taken By:
Sheila Allen

Description:
Insured excavator

Claim Photo

Our File Number: 277-065823
Adjuster: Mike Hogan
Insured: WSB LLC
Date of Loss: 11/21/2025
Customer File Number: 5630127428
Policy Number:



Photo: 3

Date Taken:
12/31/2025

Taken By:
Sheila Allen

Description:
Insured excavator



Photo: 4

Date Taken:
12/31/2025

Taken By:
Sheila Allen

Description:
Insured excavator

Claim Photo

Our File Number: 277-065823
Adjuster: Mike Hogan
Insured: WSB LLC
Date of Loss: 11/21/2025
Customer File Number: 5630127428
Policy Number:



Photo: 5

Date Taken:
12/31/2025

Taken By:
Sheila Allen

Description:
Insured excavator




Photo: 6

Date Taken:
12/31/2025

Taken By:
Sheila Allen

Description:
Insured excavator

Claim Photo

Our File Number: 277-065823
Adjuster: Mike Hogan
Insured: WSB LLC
Date of Loss: 11/21/2025
Customer File Number: 5630127428
Policy Number:



Photo: 7

Date Taken:
12/31/2025

Taken By:
Sheila Allen

Description:
Insured excavator



Photo: 8

Date Taken:
12/31/2025

Taken By:
Sheila Allen

Description:
Insured excavator

Claim Photo

Our File Number: 277-065823
Adjuster: Mike Hogan
Insured: WSB LLC
Date of Loss: 11/21/2025
Customer File Number: 5630127428
Policy Number:




Photo: 9

Date Taken:
12/31/2025

Taken By:
Sheila Allen

Description:
Insured excavator
interior.




Photo: 10

Date Taken:
12/31/2025

Taken By:
Sheila Allen

Description:
Insured excavator
interior.

Claim Photo

Our File Number: 277-065823
Adjuster: Mike Hogan
Insured: WSB LLC
Date of Loss: 11/21/2025
Customer File Number: 5630127428
Policy Number:



Photo: 11

Date Taken:
12/31/2025

Taken By:
Sheila Allen

Description:
Insured excavator
damaged radiator




Photo: 12

Date Taken:
12/31/2025

Taken By:
Sheila Allen

Description:
Insured excavator
damaged radiator
that cause engine
damage.

Claim Photo

Our File Number: 277-065823
Adjuster: Mike Hogan
Insured: WSB LLC
Date of Loss: 11/21/2025
Customer File Number: 5630127428
Policy Number:



Photo: 13

Date Taken:
12/31/2025

Taken By:
Sheila Allen

Description:
Insured excavator
puncture that
caused radiator to
leak fluid and
damage the engine.




Photo: 14

Date Taken:
12/31/2025

Taken By:
Sheila Allen

Description:
Insured excavator
damaged engine.

Claim Photo

Our File Number: 277-065823
Adjuster: Mike Hogan
Insured: WSB LLC
Date of Loss: 11/21/2025
Customer File Number: 5630127428
Policy Number:




Photo: 15

Date Taken:
12/31/2025

Taken By:
Sheila Allen

Description:
Insured excavator
damaged engine.




Photo: 16

Date Taken:
12/31/2025

Taken By:
Sheila Allen

Description:
Insured excavator
damaged engine.

Claim Photo

Our File Number: 277-065823
Adjuster: Mike Hogan
Insured: WSB LLC
Date of Loss: 11/21/2025
Customer File Number: 5630127428
Policy Number:




Photo: 17

Date Taken:
12/31/2025

Taken By:
Sheila Allen

Description:
Insured excavator
damaged engine.




Photo: 18

Date Taken:
12/31/2025

Taken By:
Sheila Allen

Description:
Insured excavator
damaged engine.

Claim Photo

Our File Number: 277-065823
Adjuster: Mike Hogan
Insured: WSB LLC
Date of Loss: 11/21/2025
Customer File Number: 5630127428
Policy Number:



Photo: 19

Date Taken:
12/31/2025

Taken By:
Sheila Allen

Description:
Insured excavator
damaged engine.




Photo: 20

Date Taken:
12/31/2025

Taken By:
Sheila Allen

Description:
Insured excavator
damaged engine.

Claim Photo

Our File Number: 277-065823
Adjuster: Mike Hogan
Insured: WSB LLC
Date of Loss: 11/21/2025
Customer File Number: 5630127428
Policy Number:




Photo: 21

Date Taken:
12/31/2025

Taken By:
Sheila Allen

Description:
Insured excavator
damaged engine.




Photo: 22

Date Taken:
12/31/2025

Taken By:
Sheila Allen

Description:
Insured excavator
damaged engine.