

## Claim Photo

Our File Number:


Adjuster:

Insured:

Date of Loss:

Customer File Number:

Policy Number:



**Photo: 1**

**Date Taken:**  
12/15/2025

**Taken By:**  
Maria Hill-Dudley

**Description:**  
Insured trailer's rear.



**Photo: 2**

**Date Taken:**  
12/15/2025

**Taken By:**  
Maria Hill-Dudley

**Description:**  
Insured trailer's rear.

## Claim Photo

Our File Number:

Adjuster:

Insured:

Date of Loss:

Customer File Number:

Policy Number:



**Photo: 3**

**Date Taken:**  
12/15/2025

**Taken By:**  
Maria Hill-Dudley

**Description:**  
Photograph of the  
insured trailer's  
seal.



**Photo: 4**

**Date Taken:**  
12/15/2025

**Taken By:**  
Maria Hill-Dudley

**Description:**  
Photograph of the  
insured trailer's  
seal.



## Claim Photo

Our File Number:


Adjuster:

Insured:

Date of Loss:

Customer File Number:

Policy Number:



**Photo: 5**

**Date Taken:**  
12/15/2025

**Taken By:**  
Maria Hill-Dudley

**Description:**  
Photograph of the  
insured trailer's  
seal.



**Photo: 6**

**Date Taken:**  
12/15/2025

**Taken By:**  
Maria Hull-Dudley

**Description:**  
Photograph of the  
insured trailer's  
license plate

## Claim Photo

Our File Number:

Adjuster:

Insured:

Date of Loss:

Customer File Number:

Policy Number:



**Photo: 7**

**Date Taken:**  
12/15/2025

**Taken By:**  
Maria Hill-Dudley

**Description:**  
Photograph of the insured trailer's rear.



**Photo: 8**

**Date Taken:**  
12/15/2025

**Taken By:**  
Maria Hill-Dudley

**Description:**  
Photograph of the insured trailer's rear doors.



## Claim Photo

Our File Number:

Adjuster:

Insured:

Date of Loss:

Customer File Number:

Policy Number:



**Photo: 9**

**Date Taken:**  
12/15/2025

**Taken By:**  
Maria Hill-Dudley

**Description:**  
Photograph of the insured trailer's rear door.



**Photo: 10**

**Date Taken:**  
12/15/2025

**Taken By:**  
Maria Hill-Dudley

**Description:**  
Photograph of the insured trailer's rear doors.

## Claim Photo

Our File Number:

Adjuster:

Insured:

Date of Loss:

Customer File Number:

Policy Number:



**Photo: 11**

**Date Taken:**  
12/15/2025

**Taken By:**  
Maria Hill-Dudley

**Description:**  
Photograph of the insured trailer's rear



**Photo: 12**

**Date Taken:**  
12/15/2025

**Taken By:**  
Maria Hill-Dudley

**Description:**  
Photograph of the insured trailer's rear door.



## Claim Photo

Our File Number:

Adjuster:

Insured:

Date of Loss:

Customer File Number:

Policy Number:



**Photo: 13**

**Date Taken:**  
12/15/2025

**Taken By:**  
Maria Hill-Dudley

**Description:**  
Photograph of the  
insured trailer's  
rear cc bar.



**Photo: 14**

**Date Taken:**  
12/15/2025

**Taken By:**  
MariaHill-Dudley

**Description:**  
Photograph of the  
insured trailer's  
rear cc bar.

## Claim Photo

Our File Number:


Adjuster:

Insured:

Date of Loss:

Customer File Number:

Policy Number:




**Photo: 15**

**Date Taken:**  
12/15/2025

**Taken By:**  
Maria Hill-Dudley

**Description:**  
Photograph of the  
insured trailer's  
rear door.



**Photo: 16**

**Date Taken:**  
12/15/2025

**Taken By:**  
Maria Hill-Dudley

**Description:**  
Photograph of the  
insured trailer's  
rear door.



## Claim Photo

Our File Number:

Adjuster:

Insured:

Date of Loss:

Customer File Number:

Policy Number:




**Photo: 17**

**Date Taken:**  
12/15/2025

**Taken By:**  
Maria Hill-Dudley

**Description:**  
Photograph of the  
insured trailer's  
rear doors.



**Photo: 18**

**Date Taken:**  
12/15/2025

**Taken By:**  
Maria Hill-Dudley

**Description:**  
Photograph of the  
insured trailer's  
rear doors.

## Claim Photo

Our File Number:


Adjuster:

Insured:

Date of Loss:

Customer File Number:

Policy Number:



**Photo: 19**

**Date Taken:**  
12/15/2025

**Taken By:**  
Maria Hill-Dudley

**Description:**  
Photograph of the  
insured trailer's  
rear door.



**Photo: 20**

**Date Taken:**  
12/15/2025

**Taken By:**  
Maria Hill-Dudley

**Description:**  
Photograph of the  
insured trailer's  
unit number.



## Claim Photo

Our File Number:


Adjuster:

Insured:

Date of Loss:

Customer File Number:

Policy Number:



**Photo: 21**

**Date Taken:**  
12/15/2025

**Taken By:**  
Maria Hill-Dudley

**Description:**  
Photograph of the insured trailer's rear wall driver's side.



**Photo: 22**

**Date Taken:**  
12/15/2025

**Taken By:**  
Maria Hill-Dudley

**Description:**  
Photograph of the insured trailer's thermometer.

Claim Photo

Our File Number:  
Adjuster:  
Insured:  
Date of Loss:  
Customer File Number:  
Policy Number:



Photo: 23

Date Taken:  
12/15/2025

Taken By:  
Maria Hill-Dudley

Description:  
Photograph of the insured trailer's internal temperature.




Photo: 24

Date Taken:  
12/15/2025

Taken By:  
Maria Hill-Dudley

Description:  
Photograph of the insured trailer's rear Vin.



## Claim Photo

Our File Number:


Adjuster:

Insured:

Date of Loss:

Customer File Number:

Policy Number:




**Photo: 25**

**Date Taken:**  
12/15/2025

**Taken By:**  
Maria Hill-Dudley

**Description:**  
Photograph of the insured trailer's front.



**Photo: 26**

**Date Taken:**  
12/15/2025

**Taken By:**  
Maria Hill-Dudley

**Description:**  
Photograph of the insured trailer's annual inspection sticker.

## Claim Photo

Our File Number:

Adjuster:

Insured:

Date of Loss:

Customer File Number:

Policy Number:



**Photo: 27**

**Date Taken:**  
12/15/2025

**Taken By:**  
Maria Hill-Dudley

**Description:**  
Photograph of the insured trailer's rear.



**Photo: 28**

**Date Taken:**  
12/15/2025

**Taken By:**  
Maria Hill-Dudley

**Description:**  
Photograph of the insured trailer's rear.



## Claim Photo

Our File Number:

Adjuster:

Insured:

Date of Loss:

Customer File Number:

Policy Number:



**Photo: 29**

**Date Taken:**  
12/15/2025

**Taken By:**  
Maria Hill-Dudley

**Description:**  
Photograph of the insured trailer's doors.



**Photo: 30**

**Date Taken:**  
12/15/2025

**Taken By:**  
Maria Hill-Dudley

**Description:**  
Photograph of the insured trailer's rear doors.

## Claim Photo

Our File Number:

Adjuster:

Insured:

Date of Loss:

Customer File Number:

Policy Number:



**Photo: 31**

**Date Taken:**  
12/15/2025

**Taken By:**  
Maria Hill-Dudley

**Description:**  
Photograph of the insured trailer's rear.



**Photo: 32**

**Date Taken:**  
12/15/2025

**Taken By:**  
Maria Hill-Dudley

**Description:**  
Photograph of the insured trailer's rear.



## Claim Photo

Our File Number:


Adjuster:

Insured:

Date of Loss:

Customer File Number:

Policy Number:



**Photo: 33**

**Date Taken:**  
12/15/2025

**Taken By:**  
Maria Hill-Dudley

**Description:**  
Photograph of the  
insured trailer's  
rear.



**Photo: 34**

**Date Taken:**  
12/15/2025

**Taken By:**  
Maria Hill-Dudley

**Description:**  
Photograph of the  
insured trailer's  
rear.

## Claim Photo

Our File Number:

Adjuster:

Insured:

Date of Loss:

Customer File Number:

Policy Number:



**Photo: 35**

**Date Taken:**  
12/15/2025

**Taken By:**  
Maria Hill-Dudley

**Description:**  
Photograph of the  
insured trailer's  
rear.



**Photo: 36**

**Date Taken:**  
12/15/2025

**Taken By:**  
Maria Hill-Dudley

**Description:**  
Photograph of the  
insured trailer's  
passenger side.